NO. OF COMICS PECCIVED]		Form C-103
	-		Supersedes Old
	NEW MEXICO OIL CONSE	RVATION COMMISSION	C-102 and C-103 Effective 1-1-65
SANTA FE			
FILC			Sa. Indicute Type of Lease
U.S.G.S.	4		State Free
LAND OFFICE	4		S. Store Off & Gua Leave No.
CPERATOR	j		1
SUND: DO NOT USE THIS FOR FOR THE	RY NOTICES AND REPORTS ON A	WELLS ICK TO A DIFFERENT ACSERVOID. IPPERDSNIS.	7. Unit Agreement Name
1.			7. Unit Agreement Nume
WELL X CAS	014ť.R-		6. Fam et Louse Hano
2. Name of Operator			
Sun Oil Company			U.D. Sawyer
3. Address of Operator	L T = 70700		5
P.O. Box 1861 Midlar	1d, lexas /9/02	·	10. Field and Fool, or Wildcat
4. Lecution of Well			Crossroads Siluro Dev
UNIT LETTER	330 FERT FROM THE South	LINE AND2310 FEET FR	⁰¹¹
THE East LINE, SECTI	10N TOWNSHIP 9-S	BANGE 36-E NME	***************************************
			12. County
uuuuuuttiittiittiittiittiittiittiittiit	15. Elevention (Show whether 1	DF, KI, GK, clc.	
	4033.5 DF		
16. Check	Appropriate Box To Indicate Na	ature of Notice, Report or (Other Data
	NTENTION TO:	SUBSEQUE	NT REPORT OF:
			· •
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING YEST AND CEMENT JOB	
Device 9 Track Devices	If non commonoial part	OTHER	L
Pert & lest Penn;	If non-commercial, perfy	•	
and test San Andres	I want the state of particulated	ils, and give pertinent dates, includ	ing estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attachment for proposed well work; estimated starting date: 2-15-78/

INTO Den Harry	nd complete to the best of my knowledge and bellet. Office Assistant	DATE
Odg Signed By		JAN 1 6 1978

ULL COBBS N. M.

.

WELLWORK PROCEDURE

11-30-77

- 1. MIRU. Install BOP.
- RIH w/Slick line for TD check. If TD at 11460 or below continue with procedure. If not, Run 4-1/2" bit, Scraper, and DC's on 2-7/8" Tbg. Clean out hole to 11460'. POH.
- 3. Use Welex to <u>Perforate 11443-11453</u> by Welex GR-NG Log dated 9-14-63. Perforate w/1JSPF using 4" Deep penetrating Jet Charge.
- 4. RIH w/Tbg. and RDG PKR. Spot 100 gal. 15% NEHCL 11460-11358. Pull Up and set Pkr. at approx. 11350 and acidize with an additional 1000 gal. 15% NEHCL dropping 1 RCNBS every Bbl. Flush w/treated BW acidize @ 3 BPM. SWAB to determine productivity.
- 5. If zone produces at Commercial Rates, put on line and test. If Non-Commercial, RIH w/CIBP on wireline and set @11400'. Prepare to perforate San Andres.
- 6. Use Welex to perforate 4880 w/4JS. RIH with Baker Model "K" retainer on wireline and set @ 4850.
- 7. Run 2-7/8" Tbg. w/stinger and set into retainer. Load annulus and test to 1000 psi. Test tubing to 4000 psi. Attempt to establish circulation behind 5-1/2" Csg.
 - <u>If circulation is established</u> Use Howco to pump 300 gals. Mud Flush. <u>Cement w/150 sx. Class</u> "C" Neat. Displace Cmt. To retainer and reverse out. Run Temp. Survey for TOC.

If circulation is not established - squeeze Csg. w/150 sx. Class "C". POH. Perforate 5-1/2" Csg. w/4JS at 4800. RIH w/Tbg. and RDG. Set Pkr. at 4600 and pressure annulus to 1000 psi. Squeeze w/100 sx. Class "C" Neat and reverse out. Release Pkr. and POH. RIH with 4-1/2" bit and DC's. Drill out cmt to top of retainer at 4850. Test squeeze to 1500 psi and POH.

- 8. Use Welex to perforate 4806-12; 4816-22; 4827-44 w/lJSPF using 4" deep penetrating Jet charge. Use Welex GR-NG Log as mentioned above.
- 9. RIH with Tbg. and RDG. Spot 100 gal. 15% NEHCL 4846-4744. Pull up and set Pkr. at Apx. 4700 and acidize with additional 3000 gal. 15% NEHCL dropping 1 RCNBS Every 1-1/4 Bbl. Flush w/Trt'd Brine water. Acidize at 2-3 BPM. SWAB to determine zone productivity.
- 10. If production is Non-Commercial, TA well pending futher evaluation.

RECEIVED JAN 16 1978 CIL CONSERVATION COMM. HOBBS, N. M.