

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Sun Oil Company		8. Farm or Lease Name New Mexico "C" State
3. Address of Operator Box 1861, Midland, Texas		9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>West</u> THE <u>7</u> LINE, SECTION <u>11S</u> TOWNSHIP <u>34E</u> RANGE <u>11S</u> NMPM.		10. Field and Pool, or Wildcat Inbe Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4202 GR		12. County Lea

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Pull rods and pump
- 2) Wash 3 sx sand down tubing
- 3) Spot 50 sx cmt plug 9762-9078, load hole with a mud ladent fluid, pull tubing.
- 4) Locate free point of 4- $\frac{1}{2}$ " OD csg. and pull.
- 5) Run tubing, spot 50 sx. plug 50' in and out of 4- $\frac{1}{2}$ " csg stub and at 5425-5163.
- 6) Spot 75 sx plug 4050-3788, 50' in and out of 8- $\frac{5}{8}$ " csg shoe.
- 7) Locate free point of 8- $\frac{5}{8}$ " csg and pull.
- 8) Run tubing, spot 50 sx plug 50' in and out of 4- $\frac{1}{2}$ " csg stub and 75 sx 450-335.
- 9) Place 10' plug at surface, cut off pipe and erect marker.
- 10) Clean location

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE Proration Clerk DATE 6-22-72

APPROVED BY Joe D. Ramsey TITLE Asst. I, Supr. DATE JUN 26 1972  
CONDITIONS OF APPROVAL, IF ANY: