

FMU Tr 14 #2 P&A Continued:

Proposed P&A Procedure

1. GIH with 3-7/8" bit to PBTD (3701'). Circ hole with 9.5 PPG mud. POOH with bit.
2. Dump 20' of cement on top of CIBP.
3. GIH with tubing to 1810' (bottom Santa Rosa perf at 1790'). Spot 85 sack plug from 1810'-695' in two stages. WOC and tag plug. TOC to be at 820' maximum.
4. Spot 10 sack plug at 313' (131' of fill).
5. Spot 3 sack surface plug (30' of fill).
6. Install P&A marker. Clean and level location.

PL Smith
10-22-92