NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION FILE I U.S.G.S. I LAND OFFICE I	C-102 and C-103 Effective 1-1-65 5a. Indicate Type of Lease
FILE	Effective 1-1-65
FILE Image: Constraint of the second secon	5a. Indicate Type of Lease
LAND OFFICE	
	State 👷 🛛 Fee
OPERATOR	
	5, State Oil & Gas Lease No.
	OG 670
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
1.	7. Unit Agreement Name
OIL GAS OTHER- Water Injection Well	Elving Mell (SA) Unit
2. Name of Operator	Flying "M" (SA) Unit 8. Farm or Lease Name
Coastal States Gas Producing Company	Flying "M" San Andres
3. Address of Operator	9. Well No.
P. O. Box 235, Midland, Texas 79701	<u>/=-</u> 2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER J, 1980 FEET FROM THE south line and 1980 FEET FR	Flving "M" (SA)
THE CARSE LINE, SECTION 17 TOWNSHIP 98 RANGE 33E NMF	ו• Λ
15. Elevation (Show whether DF, RT, GR, etc.) 4385 GR	12. County
^{16.} Check Appropriate Box To Indicate Nature of Notice, Report or C	Other Data
· · · · · · · · · · · · · · · · · · ·	NT REPORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	
OTHER	
OTHER	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Give New Mexico Oil Conservation Commission, Hobbs office, 24 hours prior 1. notice before setting first plug.
- Spot 100' cement plug on bottom. Allow 12 hours WOC. Tag top of plug. It must 2. be 50' above top perforation at 4417'.
- Determine free point; cut off and pull recoverable casing. 3.
- 4. Mud up between all cement plugs with a 25 sx. salt gel/100 bbl. brine mixture.
- Spot 100' cement plug in and out of casing stub. 5.
- 6.
- Spot 100' cement plug from top of salt at 1950'. Spot 100' cement plug in and out of surface casing bottomed at 270'. 7.
- 8. Cap at surface with 10' cement plug.

18. I hereby certify that the information	above is true and complete	e to the best of my knowledge and belief.	
SIGNED FDALL	nd	TITLE District Production Manager	DATE 2-26-74
,	· · · · · · · · · · · · · · · · · · ·	TITLE	
CONDITIONS OF APPROVAL, IF ANY:			