

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No.
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <b>SUN OIL COMPANY</b>		7. Unit Agreement Name  8. Farm or Lease Name <b>New Mexico "C" State</b>
3. Address of Operator <b>Box 1861, Midland, Texas 79701</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>7</b> TOWNSHIP <b>11S</b> RANGE <b>34E</b> NMPM.		10. Field and Pool, or Wildcat <b>Inbe-Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4212 DF</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Pull Rods and Pump.
- 2) Wash 4 sx. sand down tubing.
- 3) Spot 50 sx. cmt. from 9769-9085 over perforations.
- 4) Locate free point of 4-1/2" csg. and pull.
- 5) Run tubing, spot 50 sx. plug, 50' in and out of 4-1/2" csg. stub, and 5415-5240'.
- 6) Spot 75 sx. 4000' to 3738'. 50' in and out of 8-5/8" csg. shoe.
- 7) Locate free point of 8-5/8" csg. and pull.
- 8) Spot 70 sx. cmt. 50' in and out of 8-5/8" csg. stub, and 75 sx. 450-335'.
- 9) Place 10' plug at the surface, out of pipe and erect marker.
- 10) Clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles Gray</u>	TITLE <u>Proration Clerk</u>	DATE <u>6-22-72</u>
Signed by <u>Joe D. Ramey</u> Dist. 1, Supv		
APPROVED BY _____	TITLE _____	DATE <u>JUN 26 1972</u>
CONDITIONS OF APPROVAL, IF ANY:		