Submit 3 Copies to Appropriate Dismict Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.	
DISTRICT			30-025-21754 5. Indicate Type of Lease	
P.O. Drawer DD, Artosia, NM 88210 DISTRICT III				
1000 Rio Brazos Rd., Aziec, NM 87410			6. Side Cir at Cas Lease I	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Ag Flying "M" (S	
1. Type of Well: OIL QAS WELL X WELL	CONTR.		Tract 26	
2. Name of Operator		<u> </u>	8. Well No.	
Coastal Oil & Gas Co 3. Address of Operator	rporation		9. Pooi name or Wildcat	2
211 N. Robinson, Suite 1700, Oklahoma City, OK 73102			Flying "M" 🗲	andundres
4. Well Location	20_ Feet From TheEast	Line and520	Feet From The	North Line
Section 28	Township 9S Rar 10. Elevation (Show whether L	nge <u>33E</u> DF, RKB, RT, GR, etc.)	NMPM Lea	
4333.6' GR				
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING CASING TEST AND C				
OTHER:	L	OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
1-2-92: MIRU Pulling Unit. POH and laid down rods, pump and 145 jts of 2-7/8", 10rd tubing.				
Mud anchor left in well. Hauled tubing to yard. Set swab tank. SDFN. 1-3-92: RU reverse unit & power swivel. TIH with WO shoe, 16' extension & jars on 2-3/8"workstrip				
Tag fish @4527'. Wash over to 4547'.POOH with 28'BPMA fish. TIH with Baker Model R packe				
on 2-3/8" workstring & set @ 4348'. SDFN. 1-4-92: RU charger. Loaded annulus with 2% KCL wtr, press. to 400psi. Acidized well with 500 gals				
15% NEEF 03.4BPM/Min 1250#.Max 2000#.ISIP 1100#,10 min vac.)Swabbed back load SWI.				
1-7-92: RIH with swab. FL @ 1850'.First Run 5 Bbls wtr. RDMO. Set 500 Bbl frac tank, loaded with 450 Bbls of 2% KCL water.				
1-8-92: RU Pfizer. Pumped 50 Bbls 2% KCL water, 350 Bbls Floperm 500,50 Bbls oil flush @ 1/3 BPM (Max 1900#). SWI for polymer to cross-link. RD Pfizer.				
(Max 1900#). SW	for polymer to cross-l + POH with 2-3/8" work	ink. RD Pfizer string & Baker	Model R packer.	TIH with 2-3/8",
1-15-92:MIRU Pulling Unit. POH with 2-3/8" workstring & Baker Model R packer. TIH with 2-3/8", 4.7#, J-55,8rd,EUE tubing.(BOT @4498',SN@4472',TA@4408')SDFN.				
1-16-92: RIH with 2"x1-1/2"x16' pump, 107-3/4"rods,69-7/8"rods. Hung well on. Returned to producti Ibereby cartify that the information above is true and complete to the best of my knowledge and belief.				
I hereby certify that the information above is a	1 Milli -	Sr. Petroleu	m Engineer DA	1/21/92
				(405) LEPHONE NO. 239-7031
TYPE OR FRINT NAME Clarence	f. Miller			
(This space for State Use) RIGINAL SIGN	ED BY JERRY SEXTON			JAN 28'92
わざる目的ない	A CARLEND AND A CAR		DA	
