

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form O-103  
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ For ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT TO DRILL (FORM O-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Pruitt <i>E. B. 1</i>
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 20 TOWNSHIP 9-S RANGE 34-E NMPM.	10. Field and Pool, or wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4288.5' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon the well as follows:

Move in service unit. Pull tubing anchor and tubing. Run in hole with CIBP and set at 9740'. Pressure test CIBP to 500 PSI. Cap CIBP with 35' of cement. Run freepoint survey and cut 5½" casing 100' above freepoint. Pull 5½" casing. Spot a 50 sack cement plug across 5½" casing stub. Pull up and spot a 25 sack plug across the 8-5/8" casing shoe at 4060'. Run freepoint survey and cut 8-5/8" casing 100' above freepoint. Pull 8-5/8" casing. Spot a 50 sack cement plug across the 8-5/8" casing stub. Pull up and spot a 50 sack cement plug across the 13-5/8" casing shoe at 355'. Spot a 10 sack surface plug. Weld on cap and erect PXA marker. (Use plugging mud between all plugs.)

0+5-NMOC D, H

1-HOU

1-DMF

1-W. Stafford, HOU

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Assist. Admin. Analyst DATE 12-17-82  
ORIGINAL SIGNED BY  
APPROVED BY JERRY SEXTON TITLE \_\_\_\_\_ DATE DEC 21 1982  
CONDITIONS OF APPROVAL, IF ANY: DISTRICT 1, CLERK