

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5b. State Oil & Gas Lease No. API# 30-025-24492	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator CARR WELL SERVICE, INC.		8. Farm or Lease Name EXCHANGE OIL & GAS
3. Address of Operator P.O. BOX 69090 ODESSA TX 79769-9090		9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> 660' FEET FROM THE <u>FSL</u> LINE AND <u>660</u> FEET FROM THE <u>FEL SEC.</u> LINE, SECTION <u>13</u> TOWNSHIP <u>T-9-S</u> RANGE <u>R-33-E</u> N.M.P.M.		10. Field and Pool, or Whicat VADA (PENN)
15. Elevation (Show whether DF, RT, GR, etc.) 4310'		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE FILE 1109.

- 100' CMT PLUG FROM 9600'-9500' TAG OR CIBP W/35' CMT @ 9575'
- 100' CMT PLUG @5-1/2 CSG STUB 50 IN. + 50 OUT TAG (5500'+-)
- 100 CMT PLUG 50' BELOW 8-5/8 SHOE TO 50' ABOVE SHOE. TAG (8-5/8 SHOE @3943')
- PERF. 8-5/8" CSG @ 1930' SWUEEZE 100' INSIDE & OUTSIDE CSG.
- 100' CMT PLUG IN & OUT OF 8-5/8" CSG STUB. TAG
- 100' CMT PLUG 50' BELOW & 50' ABOVE 12-3/4 CSG SHOE. TAG (SHOE @422')
- 10 SX PLUG FROM 10' TO SURF.
- INSTALL DRY HOLE MARKER.

NOTE: HOLE WILL BE CIRCULATED W/10# BRINE W/25# SALT GEL PER BBL.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Me. P. Kautz TITLE Supervisor DATE 2-5-90
APPROVED BY Paul Kautz Geologist DATE FEB 07 1990

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 6 1990

OCD
HODS OFFICE