

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103 -
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-155-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator TEXACO Inc.		8. Farm or Lease Name N.M. "O" St. NCT -/
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240		9. Well No. 22
4. Location of Well UNIT LETTER <u>M</u> <u>500</u> FEET FROM THE <u>South</u> LINE AND <u>560</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 4010' (DF)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORATE REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig Up. Install BOP.
2. Drill out cement retainer in Glorieta string @ 6030'.
3. Perforate Glorieta string W/2-JSPF @ 6021', 27', 30', 38', 92', 96', 6101', 07', 10', and 6120'.
4. Set RBP below perfs. and packer @ 6070'. Acidize perfs. 6092'-6120' W/ 2500 gals. 20% NEFE Acid in 3 stages using 300# rock salt between stages. Flush W/ 800 Gals. 2% KCL water.
5. Reset RBP @ 6046' and packer @ 5800'. Acidize perforations 5861' -6038' W/ 5000 Gals. 20% NEFE Acid in 3 stages using 450# rock salt between stages. Flush W/ 800 Gals. 2% KCL water.
6. Perforate Blinbry string W/ 2-JSPF from 6125'- 6130'.
7. Install pumping equipment. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst Dist Mgr DATE 3/17/83

ORIGINAL SIGNED BY J. J. JEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 21 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 18 1983

O.C.D.
HOBBS OFFICE