

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Comp. Federal
SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-1
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NM-32410
2. NAME OF OPERATOR Meridian Oil, Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 21 Desta Drive Midland, Texas 79705	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FWL, Sec. 13, T-18-S, R-32-E	8. FARM OR LEASE NAME Shinnery Federal
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3831' GR	10. FIELD AND POOL, OR WILDCAT Wildcat (Wolfcamp)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 13, T-18-S, R-32-E
	12. COUNTY OR PARISH Lea
	13. STATE N.M.

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) to test Bone Springs Zone <input checked="" type="checkbox"/>	

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

RIH w/GR-CCL from 10,200' back to 8000', RIH w/5½" CIBP, set @ 11,140',
Load csg. w/150 Bbls. 2% KCL water, RIH w/4" csg. gun. Perforated 9710-15',
9718-36', 9744-52' (34 holes). RIH w/5½" Guiberson UNI V packer, 314 jts. 2-7/8"
6.5 N-80 tbg. Set packer @ 9863', test CIBP @ 2000#, pull & set packer @ 9620',
ND BOP. Text 2-7/8" / 5-½" annulus 500#. RIH w/swab, FL @ surface, swab 3 hrs.
recovered 35 BLW w/trace of oil, FL 5100' FS.

SEE ATTACHMENT

RECEIVED
 JUN 27 9 14 AM 1988
 6-23-88

18. I hereby certify that the foregoing is true and correct.

SIGNED *Donnie W. Walker* TITLE Operations Tech III DATE 6-23-88

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE *John W. Chester*

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 27 9 14 AM '88

CARL
AMT
CE
135

8. If fluid entry is limited, MIRU stimulation company. NU surface lines and test to 7000 psi. NU wellhead isolation tool. Place, monitor and maintain 500 psi on the casing-tubing annulus. Pump 2500 gallons of 15% NEFe HCl acid with 0.2% corrosion inhibitor and 0.2% surfactant. Space out 39 RCNBS (Sp. gr. = 1.3) throughout job. Displace acid with 53 bbls of 2% KCl water. If ballout occurs, surge balls off perfs and continue displacement.

Note: Anticipated Treating Pressure = 4500 psi
Maximum Treating Pressure = 6000 psi (Burst S.F. = 1.8)
Anticipated Treating Rate = 4 BPM

RDMO stimulation company.

9. Swab/flow test well recording rates and cuts. If zone swab tests wet, a squeeze procedure will be provided by project engineer at that time. If zone is not wet, continue with procedure.
10. ND tree. NU BOP. Release packer and POH. MIRU wireline unit. RIH with 4" casing guns and perforate the Second Bone Spring dolomite at the following intervals: 8594'-8604' and 8678'-8706' with 1 JSPF at 120° phasing for a total of 40 holes. POH. RDMO wireline unit.
11. RIH with a 5-1/2" RBP with extended head, 5-1/2" treating packer, SN and ±8750' of 2-7/8" 6.5# N-80 tubing. Set RBP at ±8750'. Set packer ±10' above RBP and pressure test to 1000 psi. Release packer and pull up to ±8500'. Set packer at ±8500'. ND BOP. NU tree. Swab well down to SN if possible.
12. If fluid entry is limited, MIRU stimulation company. NU surface lines and test to 7000 psi. NU wellhead isolation tool. Place, monitor and maintain 500 psi on the casing-tubing annulus. Pump 4000 gallons of 15% NEFe HCl acid with 0.2% corrosion inhibitor and 0.2% surfactant. Space out 60 RCNBS (Sp. gr. = 1.3) throughout job. Displace acid with 51 bbls of 2% KCl water. If ballout occurs, surge balls off perfs and continue displacement.

Note: Anticipated Treating Pressure = 4500 psi
Maximum Treating Pressure = 6000 psi (Burst S.F. = 1.8)
Anticipated Treating Rate = 4 BPM

RDMO stimulation company.

13. Swab/flow test well recording rates and cuts. If zone swab tests wet, a squeeze procedure will be provided by project engineer at that time.
14. ND tree. NU BOP. Release packer and drop down to $\pm 8750'$. Release RBP and POH. RIH with drill bailer on sand line and knock out CIBP at $\pm 9680'$ to $\pm 11150'$. POH.
15. RIH with production tubing (assuming all Bone Spring zones productive) as follows:
 - Bull plugged MA
 - Perforated Sub
 - Mechanical SN
 - 4 joints of 2-7/8", 6.5# N-80 tubing
 - 5-1/2" TAC
 - $\pm 9700'$ of 2-7/8" 6.5# N-80 tubing

Set TAC. ND BOP. NU pump tee and RIH with pump and rods as follows:

- 2-1/2" x 1-1/4" x 36' RHBM pump
- 7/8" pony rod
- 33K shear tool
- $\pm 4900'$ of 7/8" steel sucker rods
- $\pm 4900'$ of 1.2" fiberglass sucker rods

Balance pumping unit and put on pump reporting production volumes to Midland office.

RECEIVED

JUL 19 1989

OCD
NOBBS OFFICE