

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <u>Warren Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>Warren Unit McKee</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. WELL NO. <u>27</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>660' FSL & 2310' FSL - Unit Letter C</u>	10. FIELD AND POOL, OR WILDCAT <u>Warren McKee</u>
14. PERMIT NO. <u>30-025-07830</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>20-20S-38E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	<u>Gravel Pack</u>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting, any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 9/16/87. MIKU. Circulate well w/150 bbls 9" brine w/2% KCl TFW. Release Hg anchor & POCH. Run csq scraper to 9040'. Drill out scale & sand to 9101'. Circulate well w/ 420 bbls filtered 9ppg brine w/2% KCl. POCH. Co in hole w/289, to open end Hg to 9100'. Reverse circulate to clean csq. Flush w/315 bbls filtered 9" brine w/2% KCl. POCH. Perforate 8953' - 9079'. Swab well. Run csq scraper to 9060'. Drill out sand & debris to 9101'. Pumped 50 bbls HEC polymer & flushed w/270 bbls filtered 9" brine. Pickle Hg w/750 gals 15% HCL-NE-FC acid & 10 bbls HEC pad. Pump acid & pad to end of Hg & reverse out. Tag at 9101' & POCH. Set pk at 9086'. Co in hole w/ gravel pack assembly. Establish pumpin rate of 3 BPM at 1500 psi. Pumped gravel pack. Fish for 1" washpipe. Logged gravel pack. Ran producing equipment.

I hereby certify that the foregoing is true and correct

NEW Philip H. Finney

TITLE Administrative Supervisor

DATE March 29, 1988

This space for Federal or State office use:

APPROVAL OF
COMMISSIONERS OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

SJS