

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>B-1534</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>CONOCO INC.</b>	8. Farm or Lease Name <b>State J-2</b>
3. Address of Operator <b>P. O. Box 460, Hobbs, N.M. 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>B</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>2</b> TOWNSHIP <b>22S</b> RANGE <b>36E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Arrowhead Grayburg</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <b>open add' pay &amp; acidize</b> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- ① MIRU, Poot w/ rods & pump
- ② If fill above 3835', clean out to 3835'
- ③ Tag PBTD (3835') and run Gamma Ray from 3600' to PBTD
- ④ Perf intervals 3788'-91', 3793'-3804', and 3810'-20' w/ 4 JSPF
- ⑤ Set pkr @ 3700'
- ⑥ Pump 90 bbls 15% HCL-NE-FE and 200 lbs graded rock salt mixed in 2 bbls gelled 10 lb. brine in 3 equal stages
- ⑦ Flush w/ 40 bbls 2% KCL TFW
- ⑧ Rel pkr @ 3700'
- ⑨ Hang well on and place on test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Kevin L. Vogel* TITLE Administrative Supervisor DATE 4-7-86

ORIGINAL SIGNED BY JERRY SEXTON

PROVED BY DISTRICT I SUPERVISOR

EDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

**APR 10 1986**

*NMOCO-Hobbs*