

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-1506

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERF OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT L-1 (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Seven Rivers Queen Unit
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name Seven Rivers Queen Unit
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 48
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>23S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat Langlie Mattix 7Rivers
15. Elevation (Show whether DF, RT, GR, etc.) 3494' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4038', PBD 3800'. Present perforations 3694-3700, 3704-12, 3814-22'. Propose to perforate additional Langlie Mattix 7Rivers & acidize in the following manner:

1. POH w/completion assy.
2. Run bit & scraper to PBD.
3. CO w/sd pump to 3770'.
4. Perforate 3742-48' w/1 JSPF.
5. Run trtg pkr, spot acid across perms 3742-48'. Set pkr @ 3730' & acidize w/a total of 1500 gals 15% HCL-LSTNE acid & ball sealers.
6. Swab back acid load, POH w/trtg pkr.
7. Run completion assy & return to production.

I, the undersigned, certify that the information above is true and correct to the best of my knowledge and belief.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: