

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- _____

2. Name of Operator
Exxon Corporation

3. Address of Operator
Box 1600, Midland, Texas 79702

4. Location of Well
UNIT LETTER L 1980 FEET FROM THE SOUTH LINE AND 630 FEET FROM THE WEST LINE, SECTION 11 TOWNSHIP 22-5 RANGE 37-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3378' D.F

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No. _____

7. Unit Agreement Name _____

8. Farm or Lease Name
Paddock Unit

9. Well No.
78

10. Field and Pool, or Wildcat
Paddock

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See Attached Procedure.

Expires 10-1-79

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *D L Clemmer* TITLE Unit Head DATE 3-26-79

APPROVED BY _____ TITLE _____ DATE MAR 30 1979

CONDICIONS OF APPROVAL, IF ANY: Dist 1, Supv.

PROCEDURE

PADDOCK UNIT # 78

1. Spot a 100 ' (20 sx) Class "C" cement plug from 5040 ' to 4940 ' above the Paddock - tag top to verify position. (A CIBP with 35' (5 sx; 10 sx if thru tubing) cement on top may be set in place of this plug.)
2. Circulate hole with mud (see "C" above).
3. Spot 100' Class "C" cement plugs above the San Andres (20 sx) from 3800' to 3700' and above Queen (20 sx) from 3300' to 3200'.
4. Determine the freepoint of the 5 1/2 " production casing (T.O.C. at 2967' - calculated at 40% efficiency.)
 - a. If freepoint is below the 8-5/8 " intermediate casing seat at 2901 ' -
 - cut and pull the 5 1/2 " casing
 - spot a 100' (35 sx) plug across the cut (tag)
 - spot a 100' (35 sx) plug across the 8-5/8 " seat from 2950 ' to 2850 ' (tag).Combine plugs if cut is near seat.
 - b. If the freepoint is above the 8-5/8 " seat at 2901 ' -
 - cut and pull the 5 1/2 " casing.
 - spot a 100' (35 sx) plug across the 5 1/2 " cut (tag).
5. Determine the freepoint of 8-5/8 " intermediate casing (T.O.C. at 2084' - calculated at 30% efficiency.)
 - a. If freepoint is at or below 1200'
 - cut and pull 8-5/8 " casing.
 - spot a 100' (60 sx) plug across the casing cut (tag).
 - spot a 200' (135 sx) Class "C" cement plug from 1200 ' to 1000 ' above the salt (tag).
 - b. If freepoint is above 1200'
 - 1) and T.O.C. is below 1200' or unknown.
 - a) Perforate 8-5/8 " casing at 1100' and attempt to pump in and break circulation to surface outside 8-5/8 " -
 - (1) If can pump in
 - squeeze annulus and leave plug from 1200' to 1000' above the salt inside 8-5/8" under a cement retainer at 975' with 300 sx Dowell RFC cement (or equivalent). Close 8-5/8 " x 13-3/8 " casing valve before pump last 50 sx cement.
 - (2) If can't pump in
 - spot 200' (70 sx) plug inside 8-5/8 " casing from 1200' to 1000' above the salt (tag).
 - b) Cut and pull 8-5/8 " casing if freepoint is at or below surface (13-3/8 ") casing seat at 314 ' .
 - c) Spot a 100' (75 sx) Class "C" cement plug across the 8-5/8" csg. cut (tag).
 6. Set a 100' Class "C" cement plug from 365 ' to 265 ' across the surface (13-3/8 ") casing seat (tag, if exposed) and below the Ogallala.
 - 35 sx if in 8-5/8 " .
 - 75 sx if in 13-3/8 " , (tag).
 7. Spot a 10 sx plug at the surface.
 8. Set an approved dry hole marker and prepare the well for abandonment.