

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

20
re-

Form approved,
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

MAR 30 11 18 AM '89

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below)
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

12. COUNTY OR PARISH

13. STATE

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any project work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. GENERAL PRODUCTION EQUIPMENT

2. GIN W/ 4 3/4" BH. CLEANOUT WELL TOH

3. GIN AND SET RETRIEVABLE BRIDGE PLUG AT 6300' TOH (SEE ACID FRAC AND PERFORATIONS)

4. PERFORATE UPPER SOUTH BRUNSON DRINKARD AREA AT 6470-73, 84-85, 86-87, 88-89, 90-91, 92-93, 94-95, 96-97, 98-99, 100-101, 102-103, 104-105, 106-107, 108-109, 110-111, 112-113, AND 114-115. 24 INTERVALS. 100% ACID FRAC.

5. GIN W/ PACKER TEST WORKSTRING TO SOUTH BRUNSON SET PACKER AT 6235'

6. ACIDIZE PERFORATIONS WITH 5000 GALLONS 15% HCL. USE 46 1/2" GALLONS 15% HCL. 46 1/2" GALLONS 15% HCL. 46 1/2" GALLONS 15% HCL.

7. SOAB OR FLOW WELL BACK

8. GIN W/ ACID FRAC PERFORATIONS WITH 10,000 GALLONS 30% GELLED ACID FRAC. 10,000 GALLONS 40% GELLED PAD WITH 15,000 LBS OF WHITE HCL. 15% HCL. 15% HCL. 15% HCL.

9. SOAB OR FLOW WELL BACK

10. GIN AND RETRIEVE BP

11. GIN WITH PRODUCTION EQUIPMENT TEST FOR ALLOWABLE

12. GIN WITH NEW TEST FOR ALLOWABLE (UPPER SOUTH BRUNSON DRINKARD AREA)

18. I hereby certify that the foregoing is true and correct

SIGNED: [Signature]

TITLE

AREA SUPERINTENDENT

DATE

MAR 21 1989

(This space for Federal or State office use)

APPROVED BY: [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

4-6-89

*See Instructions on Reverse Side