

**Proposed Plugging Procedure
Conoco Inc.
Stevens B #19**

Surface casing: 7-5/8" csg @ 355' cmt'd to surface w/ 150 sx
Production csg: 4-1/2" csg @ 3,800' cmt'd w/ 200 sx, TOC 2,486' by CBL
Perforations: Penrose 3,627 – 3,734'; CIBP @ 3,540' (set12/18/91)

1. Set steel working pit. Flow well down as needed.
2. MIRU plugging equipment. NU BOP.
3. RU reverse unit and drill out cement 1,215 – 1,350'.
4. RIH w/ workstring and tag CIBP @ 3,540'. Circulate hole w/ mud and pump 25 sx C cmt on top of CIBP @ 3,540'.
5. Pump 25 sx C cmt 2,840 – 2,740'. WOC & TAG. **base of salt**
6. Pump 25 sx C cmt 1,200 – 1,100'. **top of salt**
7. POOH w/ tubing to 405' and pump 35 sx C cmt 405' to surface. **surface casing shoe**
8. Cut off wellhead and install dry hole marker. Cut off anchors and close working pit.

BUCKLE UP
FOR
SAFETY

2001 SEP 24 AM 9:24

RECEIVED