Responsible Party: Franklin Mountain Energy, LLC

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2206028617
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

OGRID: 373910

Contact Name: Craig Walters			Contact Telephone: 720-414-7868			
Contact email: cwalters@fmellc.com			Incident # (assigned by OCD): nAPP2206028617			
Contact mail 80206	ing address:	44 Cook Street, S	uite 1000, Denv	er, CO	1	
			Location	n of R	Release So	ource
Latitude 32.1	093		(NAD 83 in a	decimal de	Longitude -	-103.315017
Site Name: L	OE East Pac	l; ZIA FED COM	706H		Site Type:	Well Pad
Date Release	Discovered:	February 28, 202	2		API# 30-02	25-48583
Unit Letter	Section	Township	Range		Coun	ntv
P	24	25S	35E	Lea	Coun	inty
Material(s) Released (Select all that apply and attach calculated Crude Oil Volume Released (bbls)			tions or specific	Volume Recovered (bbls)		
	Materia	l(s) Released (Select al	ll that apply and atta	ch calcula	tions or specific	c justification for the volumes provided below)
						` ′
Produced	Water	Volume Release				Volume Recovered (bbls)
		Is the concentrate produced water		chlorid	e in the	☐ Yes ☐ No
Condensa	ite	Volume Release				Volume Recovered (bbls)
Natural G	ias	Volume Release	ed (Mcf)			Volume Recovered (Mcf)
Other (de	scribe)	Volume/Weight	Released (provi	de units) 24BBL	Volume/Weight Recovered (provide units) 19BBL
Cause of Rel	ease: Humai	l 1 error. Open ende	ed diesel hose wa	as left ru	nning and ov	 verfilled shaker tank.

Page 2 of 11

Incident ID	NAPP2206028617
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respo	nsible party consider this a major release?		
☐ Yes ⊠ No				
If YES, was immediate n	otice given to the OCD? By whom? To wh	nom? When and by what means (phone, email, etc)?		
	Initial R	esponse		
The responsible	party must undertake the following actions immediate	y unless they could create a safety hazard that would result in injury		
The source of the rele	ease has been stopped.			
The impacted area ha	as been secured to protect human health and	the environment.		
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.				
☑ All free liquids and recoverable materials have been removed and managed appropriately.				
If all the actions describe	d above have <u>not</u> been undertaken, explain	why:		
D. 10 15 20 9 D. (4) ND	TACAL TILL			
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred blease attach all information needed for closure evaluation.		
		best of my knowledge and understand that pursuant to OCD rules and		
public health or the environ	ment. The acceptance of a C-141 report by the C	fications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have		
		at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws		
Printed Name: Rachael	<u>Qverbey</u>	Title: Dir. Ops Planning & Regulatory		
Signature:	he	Date: _3/8/2022		
email: roverbey@fmet	lc.com	Telephone: 303-570-4057		
_/				
OCD Only				
Received by: Jocelyn	Harimon	Date: 03/14/2022		
				

Date 2/28/22 8:45 AM


Location: LOE East pad, Zia Fed Com 706H

Incident: Diesel hose overfilled dryer shaker bin resulting in an estimated 24 bbl diesel spill.

Description: H&P 518 had just finished up a safety meeting on running 5.5" production casing. After meeting I went down to the ground to explain and show motor hand what marker joints to pick up, as I was walking back up to rig floor, I noticed fluid coming out from under the water tank and immediately told derrick hand to go check his pits. As I witnessed float shoe being made up driller called me in doghouse and said derrickhand found a diesel hose running that had over filled the dryer shaker bin. I immediately went to shakers and noticed the fluid had made its way under the 3-sided tank to open tops and out past the gas buster. I then met with the solids control EE and asked him how this had happened at which he did not know. At 8:52 am I called drilling engineer Jason Townsend and let him know we had spill. I gathered up toolpusher and all available hands and set forth a plan to begin sucking up diesel to stop it from spreading any further and going into ground any deeper. Once plan to contain it was in place and I had an idea on the amount of the spill I contacted both the drilling engineer Jason & FME HSE Kent and let him know about the spill, Jason informed me he would call Clay.

Root Cause: Valve on an open-ended diesel hose was left on.


Remediation: Got rig vac and started sucking diesel off ground while other EE squeegeed diesel to vac. Once the suckable fluid was sucked up the contaminated dirt was scraped up and put in 3-sided cuttings bin. The remainder fluid and contaminated dirt under rig equipment will be remediated once drilling rig is off location. An estimated 19 bbls of the 24 bbls was recovered and put in the OBM active system.








NAPP2206028617







NAPP2206028617

Rachael Overbey

From: Jason Townsend

Sent: Friday, March 11, 2022 10:02 AM

To: Rachael Overbey
Cc: Vlad Roudakov

Subject: Volume Estimate - Zia Fed Com 706H Diesel Spill

Good morning Rachael,

The spill was noticed at 08:45 central time. At that time, there had been zero diesel usage from the mud diesel tank since the last report other than the unmanned 1" hose that was the cause of the spill. The sight glass on the mud diesel indicated that we were 54bbls lower in the tank than the previous reading from the night before. The tank that the hose was running into was a 30bbl tank. That leaves 24bbls unaccounted for and therefore on the ground. When we performed cleanup, we discharged our recovery fluid across the shakers. We gained 19bbls in pit volume from this discharge throughout the process. These numbers allowed us to estimate 5bbls remaining on the ground.

Regards,
Jason Townsend
Drilling Engineer
Franklin Mountain Energy
44 Cook Street, Suite 1000
Denver, CO 80206

Cell: 601.307.3138

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 89476

CONDITIONS

CONDIN	0110
Operator:	OGRID:
Franklin Mountain Energy LLC	373910
44 Cook Street	Action Number:
Denver, CO 80206	89476
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jharimon	None	3/14/2022