

## **Volumetrics Inc.**

3710 East Rio Grande St, Victoria, TX-77901

Phone: 361-827-4024

**Work Order** Company: OXY USA INC 4000501489 Field/Location: **NMSW** Sampled by: OXY/JE SPOT-CYLINDER

Station Name: CORRAL COMPRESSOR STA 2 SOUTH FUEL SKID OUTLE Sample Type:

Sample Temperature (F): Station Number: NA Sample Pressure (PSIG): Sample Date: 2/23/22 1:30 PM 125 **Analysis Date:** 3/7/22 11:00 AM Flow rate (MCF/Day): NA Instrument: INFICON Ambient Temperature (F): 23

Sampling method: Calibration/Verification Date: 3/7/2022 FILL & EMPTY

Cylinder Number: Heat Trace used: YES 27784

## **NATURAL GAS ANALYSIS: GPA 2261**

	Un-Normalized	Normalized	GPM	GPM	GPM
Components	Mol%	Mol%	14.650	14.730	15.025
Hydrogen Sulfide	0.0000	0.0000			
Nitrogen	1.3240	1.3598			
Methane	75.6525	77.7008			
Carbon Dioxide	0.1877	0.1928			
Ethane	11.5036	11.8151	3.153	3.170	3.234
Propane	5.8586	6.0172	1.654	1.663	1.696
Isobutane	0.7572	0.7777	0.254	0.255	0.260
N-butane	1.6243	1.6683	0.525	0.528	0.538
Isopentane	0.2101	0.2158	0.079	0.079	0.081
N-Pentane	0.1809	0.1858	0.067	0.068	0.069
Hexanes Plus	0.0650	0.0667	0.029	0.029	0.030
Total	97 3638	100 0000			

Hexanes plus split (60%-30%-10%)

14.650 psia	14.730 psia	15.025 psia
5.761	5.792	5.908
0.175	0.176	0.179
0.9965	0.9965	0.9964
0.7242	0.7242	0.7243
20.911	20.911	20.911
14.650 psia	14.730 psia	15.025 psia
1244.9	1251.8	1276.9
1223.3	1230.0	1254.7
1240.6	1247.4	1272.3
1219.0	1225.7	1250.2
	5.761 0.175 0.9965 0.7242 20.911 <b>14.650 psia</b> 1244.9 1223.3 1240.6	5.761 5.792 0.175 0.176 0.9965 0.9965 0.7242 0.7242 20.911 20.911  14.650 psia 14.730 psia 1244.9 1251.8 1223.3 1230.0 1240.6 1247.4

Temperature base 60 °F

Comment: FIELD H2S =0 PPM

Verified by

Mostaq Ahammad Petroleum Chemist Approved by

Deann Friend Laboratory Manager

## **UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**

Facility: Corral 2S CS Flare Date: 07/12/2022

**Duration of event:** 40 Minutes **MCF Flared:** 302

Start Time: 05:00 AM End Time: 05:40 AM

Cause: Equipment Malfunction > Dump Valve > Compressor Malfunctions > Compression Equipment

Shut Down

Method of Flared Gas Measurement: Gas Flare Meter

**Comments:** This upset event was not caused by any wells associated with the facility.

# 1. Reason why this event was beyond Operator's control:

This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program. In this case, a dump valve on the inlet scrubber at the Corral 2 North compressor station facility failed to dump liquids, which in turn, caused a hihi level switch to trip and shutdown all four (4) of the compressors. The Corral 2 North compressor station compression equipment was working normally and in good working operation prior the dump valve malfunctioning. Once the Oxy production tech received the compressor malfunction alarms as well as a flare alarm, the tech, who was in the area, arrived at the facility to troubleshoot the issues. Once it was determined that the dump valve on the inlet scrubber was failing to dump liquids, which caused the hihi level switch to trip, and shutdown the compression equipment, which prompted stranded gas to flare, the production tech cleared the dump valve, and the compression equipment's alarm panels were cleared, and the equipment was restarted. This event could not have been avoided or prevented from happening as technical or automated equipment, internally and externally, are inherently dynamic and its breakdown and/or malfunction can be sudden, reasonably unforeseeable and unexpected, which impact compression equipment operations and trigger additional malfunctions within the compressors as well as other type of equipment. This event is out of OXY's control yet, OXY made every effort to control and minimize emissions as much as possible. Though sudden and unexpected malfunctioning compressor issues occurred at Corral 2 North compressor station, OXY routed the overflow of stranded gas to flare at the Corral 2S compressor station in an effort to mitigate emissions for this event as the flare at this location can accommodate a higher volume of gas and in an effort to protect equipment, environment, and personnel.

# 2. Steps Taken to limit duration and magnitude of venting or flaring:

This facility is unmanned, except when Oxy production techs are gathering data daily or conducting daily walkthroughs to ensure that there are no problems, circumstances and/or assist other personnel on-site for maintenance purposes. It is OXY's policy to route all stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, as the part of the overall process or steps to take to limit duration and magnitude of flaring. Oxy personnel are in the field 24/7 and can physically see when we are flaring, which in turn, are communicated to additional Oxy field personnel. Internal OXY procedures ensure that upon gas compressor unit and/or multiple unit shutdown, increased sensor pressure/level alarms, other process equipment issues, etc., field production technician personnel are promptly notified, and are instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions. Oxy production technicians must assess whether the issue or circumstance is due to damage and repair is needed, or whether there are other reasons for its cause. The flare at this facility has a 98% combustion efficiency in order to lessen emissions as much as possible. In this case, a dump valve on the inlet scrubber at the Corral 2 North compressor station facility failed to dump liquids, which in turn, caused a hihi level switch to trip and shutdown all four (4) of the compressors. The Corral 2 North compressor station compression equipment was working normally and in good working operation prior the dump valve malfunctioning. Once the Oxy production tech received the compressor malfunction alarms as well as a flare alarm, the tech, who was in the area, arrived at the facility to troubleshoot the issues. Once it was determined that the dump valve on the inlet scrubber was failing to dump liquids, which caused the hihi level switch to trip, and shutdown the compression equipment, which prompted stranded gas to flare, the production tech cleared the dump valve, plus restarted the compression equipment when the alarm panels were cleared. This event could not have been avoided or prevented from happening as technical or automated equipment, internally and externally, are inherently dynamic and its breakdown and/or malfunction can be sudden, reasonably unforeseeable and unexpected, which impact compression equipment operations and trigger additional malfunctions within the compressors as well as other type of equipment. This event is out of OXY's control yet, OXY made every effort to control and minimize emissions as much as possible. Though sudden and unexpected malfunctioning compressor issues occurred at Corral 2 North compressor station, OXY routed the overflow of stranded gas to flare at the Corral 2S compressor station in an effort to mitigate emissions for this event as the flare at this location can accommodate a higher volume of gas and in an effort to protect equipment, environment, and personnel.

## 3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as notwithstanding typical operation field equipment design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause equipment malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive equipment preventative maintenance program in place. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this facility. As a potential remedy to prevent this type of circumstance occurring from happening in the future, Oxy production techs, during daily inspections of the facility, will be monitoring the dump valves and liquid levels on the inlet scrubber more closely.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

DEFINITIONS

Action 128479

#### **DEFINITIONS**

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	128479
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

### **DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- · venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS

Action 128479

# **QUESTIONS**

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	128479
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

#### QUESTIONS

Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.		
Incident Well	Not answered.	
Incident Facility	[fAPP2126640958] CORRAL #2 SOUTH COMP STATION	

Determination of Reporting Requirements			
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.			
Was this vent or flare caused by an emergency or malfunction	Yes		
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No		
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.		
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.  Was there at least 50 MCF of natural gas vented and/or flared during this event  Yes			
Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No		
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No		

Equipment Involved		
Primary Equipment Involved	Other (Specify)	
Additional details for Equipment Involved. Please specify	Emergency Flare > Equipment Malfunction > Dump Valve > Compressor Malfunctions > Compression Equipment Shut Down	

Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	78	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.		
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 128479

QUESTIONS	(continued)
-----------	-------------

(	Operator:	OGRID:
	OXY USA INC	16696
	P.O. Box 4294	Action Number:
	Houston, TX 772104294	128479
		Action Type:
		[C-129] Venting and/or Flaring (C-129)

## QUESTIONS

Date(s) and Time(s)		
Date vent or flare was discovered or commenced	07/12/2022	
Time vent or flare was discovered or commenced	05:00 AM	
Time vent or flare was terminated	05:40 PM	
Cumulative hours during this event	1	

Measured or Estimated Volume of Vented or Flared Natural Gas			
Natural Gas Vented (Mcf) Details	Not answered.		
Natural Gas Flared (Mcf) Details	Cause: Other   Other (Specify)   Natural Gas Flared   Released: 302 Mcf   Recovered: 0 Mcf   Lost: 302 Mcf ]		
Other Released Details	Not answered.		
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter		
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.		

Venting or Flaring Resulting from Downstream Activity				
Was this vent or flare a result of downstream activity	No			
Was notification of downstream activity received by this operator	Not answered.			
Downstream OGRID that should have notified this operator	Not answered.			
Date notified of downstream activity requiring this vent or flare	Not answered.			
Time notified of downstream activity requiring this vent or flare	Not answered.			

Steps and Actions to Prevent Waste				
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True			
Please explain reason for why this event was beyond this operator's control	This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program. In this case, a dump valve on the inlet scrubber at the Corral 2 North compressor station facility failed to dump liquids, which in turn, caused a hihi level switch to trip and shutdown all four (4) of the compressors. The Corral 2 North compressor station compression equipment was working normally and in good working operation prior the dump valve malfunctioning. Once the Oxy production tech received the compressor malfunction alarms as well as a flare alarm, the tech, who was in the area, arrived at the facility to troubleshoot the issues. Once it was determined that the dump valve on the inlet scrubber was failing to dump liquids, which caused the hihi level switch to trip, and shutdown the compression equipment, which prompted stranded gas to flare, the production tech cleared the dump valve, and the compression equipment's alarm panels were cleared, and the equipment was restarted. This event could not have been avoided or prevented from happening as technical or automated equipment, internally and externally, are inherently dynamic and its breakdown and/or malfunction can be sudden, reasonably unforeseable and unexpected, which impact compression equipment operations and trigger additional malfunctions within the compressors as well as other type of equipment. This event is out of OXY's control yet, OXY made every effort to control and minimize emissions as much as possible.			
Steps taken to limit the duration and magnitude of vent or flare	In this case, a dump valve on the inlet scrubber at the Corral 2 North compressor station facility failed to dump liquids, which in turn, caused a hihi level switch to trip and shutdown all four (4) of the compressors. The Corral 2 North compressor station compression equipment was working normally and in good working operation prior the dump valve malfunctioning. Once the Oxy production tech received the compressor malfunction alarms as well as a flare alarm, the tech, who was in the area, arrived at the facility to troubleshoot the issues. Once it was determined that the dump valve on the inlet scrubber was failing to dump liquids, which caused the hihi level switch to trip, and shutdown the compression equipment, which prompted stranded gas to flare, the production tech cleared the dump valve, plus restarted the compression equipment when the alarm panels were cleared. This event could not have been avoided or prevented from happening as technical or automated equipment, internally and externally, are inherently dynamic and its breakdown and/or malfunction can be sudden, reasonably unforeseeable and unexpected, which impact compression equipment operations and trigger additional malfunctions within the compressors as well as other type of equipment.			
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as notwithstanding typical operation field equipment design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause equipment malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive equipment preventative maintenance program in place. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this facility. As a potential remedy to prevent this type of circumstance occurring from happening in the future, Oxy production techs, during daily inspections of the facility, will be monitoring the dump valves and liquid levels on the inlet scrubber more closely.			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 128479

# **ACKNOWLEDGMENTS**

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	128479
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

### **ACKNOWLEDGMENTS**

V	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be <b>a complete</b> C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
V	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
V	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 128479

# **CONDITIONS**

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	128479
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

#### CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	7/25/2022