Constitution Copy to Appropriate Distille: 41 An	State of New Mexico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-44660
District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Salita Pe, NWI 67505	6. State Oil & Gas Lease No.
87505		
	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	S TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	ION FOR PERMIT" (FORM C-101) FOR SUCH	Cornado State
PROPOSALS.) 1. Type of Well: Oil Well Ga	s Well Other	8. Well Number 1H
2. Name of Operator	5 Wen Cuter	9. OGRID Number
Nitro (Oil & Gas	7. OGRID Tumber
3. Address of Operator		10. Pool name or Wildcat
•	Con Antonio TV 70257	
4. Well Location	San Antonio TX 78257	
	2458 feet from the East line and	400 feet from the West line
	icct it out the into the	
Section 28	Township 28 Range 11W	NMPM County Lea
1	1. Elevation (Show whether DR, RKB, RT, GR, etc.	.)
12. Check App	propriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTE	OUT	OCCUPAT DEPOST OF
NOTICE OF INTE		SSEQUENT REPORT OF:
	PLUG AND ABANDON 🔲 REMEDIAL WOR	_
 -		RILLING OPNS. PAND A
	MULTIPLE COMPL	^{IT JOB} □ PNR
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTHER:	☐ OTHER:	
	d operations (Clearly state all pertinent details as	nd give pertinent dates, including estimated date
13. Describe proposed or complete		
of starting any proposed work)	. SEE RULE 19.15.7.14 NMAC. For Multiple Co	
	. SEE RULE 19.15.7.14 NMAC. For Multiple Co	
of starting any proposed work) proposed completion or recom	. SEE RULE 19.15.7.14 NMAC. For Multiple Copletion.	ompletions: Attach wellbore diagram of
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment	. SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' N	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR	. SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NUMBER OF SET OF	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to such that is Class C @ 3900' POOH to	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300'	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to such that the complex Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870'	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to such that see the second	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion. MIRU Plugging Equipment From Pool Mire Setting tool Mire Right to 3900' Mix & spot 32 sx @ 3300' Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' POOH to 2382' POOH to	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 4	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' 2870 POOH to 2382' POOH to POOH	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 4	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' POOH to 2382' POOH to	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion of the proposed work) and proposed work of the prop	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' 2870 POOH to 2382' POOH to POOH	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recomply MIRU Plugging Equipment FOOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sy MIx & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 64 sys Class C @ 4	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' 2870 POOH to 2382' POOH to POOH	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recomply MIRU Plugging Equipment FOOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sy MIx & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 32 sys Class C @ 2 Mix & spot 64 sys Class C @ 4	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' 2870 POOH to 2382' POOH to POOH	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recomply MIRU Plugging Equipment FOOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 4 POOH w/ tbg RD equipment	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to 2382' POOH to Surface Csg shoe Cut and cap head clean location RDI	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 4	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' 2870 POOH to 2382' POOH to POOH	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion of the proposed work) pro	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to 2382' POOH to Surface Csg shoe Cut and cap head clean location RDI	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300'
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 2 POOH w/ tbg RD equipment Spud Date:	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to sure as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to Reference Csg shoe Cut and cap head clean location RDI	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 2 POOH w/ tbg RD equipment Spud Date:	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to su as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to 2382' POOH to Surface Csg shoe Cut and cap head clean location RDI	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 2 POOH w/ tbg RD equipment Spud Date:	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to sure as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to Reference Csg shoe Cut and cap head clean location RDI	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO
of starting any proposed work) proposed completion or recompletion of the proposed completion of t	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MUWL RIH w/ bond; log Log back to sure set Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to 2382' POOH to 2382' POOH to Cut and cap head clean location RDI Rig Release Date:	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 2 POOH w/ tbg RD equipment Spud Date:	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to sure as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to Reference Csg shoe Cut and cap head clean location RDI	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO
of starting any proposed work) proposed completion or recom MIRU Plugging Equipment POOOH w/ Setting tool MIR RIH to 3900' Mix & spot 32 sx MIx & spot 32 sxs @ 3300' Mix & sqz 50 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 32 sxs Class C @ 2 Mix & spot 64 sxs Class C @ 2 POOH w/ tbg RD equipment Spud Date: I hereby certify that the information about	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MUWL RIH w/ bond; log Log back to sure class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to POOH to 2382' POOH to POOH to Case' POOH to Pooh to Surface Csg shoe Cut and cap head clean location RDI Rig Release Date: Rig Release Date: TITLE Field Rep	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO ge and belief. DATE 9-18-23
of starting any proposed work) proposed completion or recompletion of the proposed completion of the proposed	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' MUWL RIH w/ bond; log Log back to sure class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to POOH to 2382' POOH to POOH to Case' POOH to Pooh to Surface Csg shoe Cut and cap head clean location RDI Rig Release Date: Rig Release Date: TITLE Field Rep	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO
of starting any proposed work) proposed completion or recomproposed completion of the proposed completion of the propos	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to sure as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to 2382' POOH to 2382' POOH to Eso' to Surface Csg shoe Cut and cap head clean location RDI Rig Release Date: Rig Release Date:	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO ge and belief. DATE 9-18-23 7@outlook.comPHONE: 903-738-2923
of starting any proposed work) proposed completion or recomproposed completion of the proposed	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. RIH w/ tbg to 4900' set CIBP @ 4900'' NU WL RIH w/ bond; log Log back to sure as Class C @ 3900' POOH to POOH to 2800' Perf csg @ 2870' 870' POOH to 2382' POOH to 2382' POOH to Eso' to Surface Csg shoe Cut and cap head clean location RDI Rig Release Date: Rig Release Date:	ompletions: Attach wellbore diagram of lix & spot10 sxs on plug rface 3300' 2382' 450' MO ge and belief. DATE 9-18-23 7@outlook.comPHONE: 903-738-2923

JW Well Service

Cornado State 1H API # 30-025-44660

Day 1, Date: 09/14/2023

MIRU Plugging Equipment – Trip in hole with CIBP to 4900', set CIBP, mix & spot 10 sxs cement on plug, TOOH with setting tool.

Day 2, Date: 09/15/2023


RIH with bond log, log back to surface. TIH with tubing to 3900', mix & spot 35 sxs cement. TOOH to 3300', mix & spot 35 sxs cement at 3300'. TOOH to 2800'


Day 3, Date: 09/16/2023

Perf casing at 2870', mix & squeeze 50 sxs cement at 2870', mix & spot 35 sxs cement at 2870', TOOH to 2382', mix & spot 35 sxs cement at 2382', TOOH to 450', mix cement & circulate to surface.

Day 4, Date: 09/17/2023

Top cement off at surface and rig down plugging equipment. Cut & cap well.





TOC: <u>surface</u> Hole Size: <u>12-1/4"</u>

Formation Tops
Santa Rosa 1100
Anhydrite 2300

Production Casing Size: <u>5-1/2"</u>


 Wt.:
 20

 Depth:
 9600

 Sxs Cmt:
 1480

Circulate: <u>yes</u>
TOC: surface

Hole Size: <u>7-7/8"</u>



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 266131

COMMENTS

Operator:	OGRID:
Nitro Oil & Gas, LLC	330754
223 W. Wall Street	Action Number:
Midland, TX 79701	266131
	Action Type:
	[C-103] Sub. Plugging (C-103P)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM.	10/31/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 266131

CONDITIONS

Operator:	OGRID:
Nitro Oil & Gas, LLC	330754
223 W. Wall Street	Action Number:
Midland, TX 79701	266131
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Need C103Q and marker photo to release	10/31/2023