

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

AUG 26 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1524039752 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 105 Flowline	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 3001527895
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	36	24S	30E	660		1980		Eddy

Latitude: 32.18573 Longitude: 103.83154

NATURE OF RELEASE

Type of Release: Crude Oil -Produced Water	Volume of Release: 3 barrels oil, 3 barrels PW	Volume Recovered: 1 barrel oil
Source of Release: Flowline	Date and Hour of Occurrence: 8-10-15 @ 11:30am	Date and Hour of Discovery: 8-10-15 @11:49am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* BOPCO EHS was notified of a release that occurred on the PLU 105 Flowline due to corrosion. Contract crew installed an emergency repair clamp until the line can be replaced. **Originally reported as the PLU 84 (2RP-3199), once the flowlines were exposed it was determined that the PLU 105 was the line that leaked**		
Describe Area Affected and Cleanup Action Taken.* A vacuum truck was called to the location and was able to recover 1 barrel oil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By <i>M. H. [Signature]</i> Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 8/28/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date: 8-26-15 Phone: 432-214-3704	Attached <input type="checkbox"/>	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: **9/28/15**

2RP-3225

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Wednesday, August 26, 2015 10:11 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: FW: Initial C-141 2RP-3199
Attachments: doc04529720150826090644.pdf

Mike, Heather

Please find the correct C-141 for the PLU 105 flowline release. I made reference in the C-141 to the miss communication as to 84/105 release notification. If you need further info please let me know.

Thank you.

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Monday, August 24, 2015 2:37 PM
To: Blevins, Bradley; Patterson, Heather, EMNRD
Subject: RE: Initial C-141 2RP-3199

Brad,

Just send a new Initial C-141 with some mention of the current 2RP-3199 sent in error, and we can fix the rest on our end, or you can send a Final C-141 for the 84 and an Initial for the 105.

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Blevins, Bradley [mailto:BBlevins@BassPet.Com]
Sent: Monday, August 24, 2015 1:16 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: Initial C-141 2RP-3199

Mike, Heather

Upon further investigation the PLU 84 was not the line that leaked. The PLU 105 was the actual well that had the flowline fail. These lines are buried and the pumper turned in the wrong well, Do I need to file an additional C-141 or can changes be made to the original? Thank you.

API for the PLU 105 is 3001527895

Brad Blevins

Remediation Foreman (PLU)
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com