


Occidental Permian Limited Partnership

July 10, 2007

New Mexico Oil Conservation Division District I 1625 N. French Drive Hobbs, New Mexico 88240



Attn: Environmental Engineering

RE: Remediation Plan

South Hobbs Unit #33 3" Steel Injection Line

UL 'G', Sec. 4, T-19-S, R-38-E

Leak occurred on 02/26/2007, at approximately 12:00 PM. A 3" steel injection line used to transfer water from South Hobbs Unit Injection Building #1 to the South Hobbs Unit Well #33 developed a hole causing spill. Valves on both ends of the line were shut to isolate leak. The normal rate for the South Hobbs Unit well #33 is approximately 1600 bbls/day at a pressure of about 1000 psig. The area affected by this spill is an area measuring approximately 60' wide and 300' long, at the widest points, to the south of South Hobbs Unit #33. An estimated 35 barrels of injection water was spilled. Approximately 21 bbls of water was recovered via vacuum truck. Occidental Permian LTD. is the surface owner and utilizes for the sole purpose of oil and gas production. The area consists of sand, rocks and normal vegetation. Depth to ground water according to State Engineers Office is an average of 48', for all wells in the area, giving this spill site a ranking of 20. Remediation of the spill site was as follows:

- 1. Piping was excavated and is awaiting replacement.
- 2. Affected area was excavated and soil removed was disposed of at Sundance Services, Parabo Faciltiy near Eunice, NM. Approximately 228 yards were disposed of.
- 3. Soil samples were gathered from affected area. Area was sampled on 06/28/2007 see attached map for sample points.
- 4. NMOCD guidelines were used to insure entire site is in compliance with guidelines.
- 5. Any soils removed will be replaced with clean fresh soils, where needed.

6. Soil analysis data is attached with this final closure letter. See attached Cardinal Lab soil analysis data dated 6/29/2007 and 7/03/2007.

Soil analysis shows BTex and TPH is non- detect. Chloride levels show slight elevation over background, but there is excellent growth of native vegetation over the entire area. We feel there will be no further impact of this area due to this spill and no further work is planned for this site. The flow line was not repaired and will be replaced at a later date.

If you have any questions, or if I can be of further assistance, please contact me at (505) 397-8251.

Steven M. Bishop

HES Tech/WSAH RMT Steven Bishop@oxy.com

Steven M. Bisty

(505) 397-8251

Attachments: Final C-141

Cardinal Lab soil analysis data dated 6/29/07 and 7/03/07 Hand drawn map of spill area showing sample points

Latest South Hobbs Unit Water Analysis taken at South Hobbs Unit Central T/B

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form

					OPERATOR Initial Report (Fin				Final Re	epoji			
					Contact Steven M. Bishop								
					Telephone No. (505) 397-8251								
Facility Name South Hobbs Unit #33					Facility Type Production								
Surface Owner Occidental Permian LTD. Mineral Owner								Lease N	lo.				
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		n/South Line	Feet from the	East/V	Vest Line	County			
'G'	4	19-S	38-E							LEA			
Latitude 32°41'15.90" Longitude 103°10'49.40"													
NATURE OF RELEASE													
Type of Rele						Volume of Release Volume Recov 35 bbls water 21 bbls water				_			
Injection water Source of Re						Date and Hour of Occurrence Date and Hour				scovery			
3" steel inject		3: 0				02/26/2007 12.00 PM 02/26/2007 12:00 PM If YES, To Whom?							
Was Immedia	ite Notice (Yes [] No 🔲 Not Re	equired		perton via Voice	Mail					
By Whom? Steven M B	ishop				-	Date and Hour 02/26/2007 02:53 PM							
Was a Watero			Yes 🛛	No		If YES, Volume Impacting the Watercourse. N/A							
If a Watercou	ırse was İm												
Tru Waterbou	ise was in	pacica, Descr	oc runy.										
Describe Cau	Describe Cause of Problem and Remedial Action Taken.*												
Operators discovered a leak just south of South Hobbs Unit Injection Well #33. Shut valves on injection header inside building #1 going													
to South Hobbs Unit Injection Well #33, and wellhead valves to stop leak. Recovered 21 bbls of injection water via vacuum truck.													
Describe Are	Describe Area Affected and Cleanup Action Taken.*												
				south of South I	Hobbs	Unit Well #3	33. Fluid ran ac	ross sa	ndy pastur	e and acci	umulate	ed in a	
				est of the spill s									
	and is used primarily for oil and gas production. Area was remediated to NMOCD spill guidelines. Flowline was not repaired and will be replaced at a later date.								e i				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health	or the envi	ronment. The	acceptance	e of a C-141 repo	rt by tl	he NMOCD m	arked as "Final Re	eport" d	oes not reli	eve the ope	erator of	liability	
				investigate and restance of a C-141									th
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
CA um Real-					OIL CONSERVATION DIVISION								
Signature: TEVON M, Sistley					Endie- Tian A								
Printed Name: Steven M. Bishop					Approved by District Supervisor.								
Title. HES Technician A					Approval Dat	e: 7,18,0	7	X Expiration	Date:				
					Conditions of Approval			Attached					
Date: 07/10/2007 Phone: (505) 397-8251									Audolieu 🔲				
		Sheets If Ne		10. (303) 391-023	1	٠ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ		· · ·		1	لمرم		$\overline{\Omega}$
			•			APITE	8025076°	W D 00	0	[[]	2074	W.	51



PHONE (325) 673-7001 - 2111 BEECHWOOD - ABILENE TX 79603

PHONE (505) 393-2326 - 101 E. MARLAND - HOBBS, NM 88240

ANALYTICAL RESULTS FOR BBC INTERNATIONAL, INC. ATTN: CLIFF BRUNSON P.O. BOX 805

HOBBS, NM 88241 FAX TO: (505) 397-0397

Receiving Date: 06/28/07

Reporting Date: 06/29/07

Project Owner: OXY

Project Name: SOUTH HOBBS UNIT WELL #33

Project Location: HOBBS, NM

Sampling Date: 06/28/07

Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: AB

Analyzed By: AB


LAB NUMBE	R SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENE\$ (mg/Kg)
ANALYSIS D	ATE	06/29/07	06/29/07	06/29/07	06/29/07
H12832-1	SAMPLE POINT 1	<0.002	<0,002	<0.002	<0.006
H12832-2	SAMPLE POINT 2	<0.002	<0.002	<0,002	<0.006
H12832-3	SAMPLE POINT 3	<0.002	<0.002	< 0.002	<0.006
H12832-4	SAMPLE POINT 4	<0.002	<0.002	<0.002	<0.006
H12832-5	BACKGROUND	<0.002	<0.002	<0.002	<0.006
Quality Contr	ol	0.112	0.105	0.105	0.322
True Value C	C	0.100	0.100	0.100	0.300
% Recovery		112	105	105	107
Relative Perc	ent Difference	1.2	2.8	3.0	3.1

METHOD: EPA SW-846 8021B

ywofd Cooke

Dete





ANALYTICAL RESULTS FOR BBC INTERNATIONAL, INC. ATTN: CLIFF BRUNSON P.O BOX 805 HOBBS, NM 88241

FAX TO: (505) 397-0397

Receiving Date: 06/28/07 Reporting Date: 07/03/07

Project Owner: OXY

Project Name: SOUTH HOBBS UNIT WELL #33

Project Location: HOBBS, NM

Sampling Date: 06/28/07 Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: AB Analyzed By: LB/HM

GRO DRO
(C₆-C₁₂) (>C₁₂-C₂₆) CI*

LAB NUMBER SAMPLE ID (mg/Kg) (mg/Kg) (mg/Kg)


ANALYSIS [DATE	06/29/07	06/29/07	06/29/07	
H12832-1 SAMPLE POINT 1		<25.0	<25.0	0 320	
H12832-2	SAMPLE POINT 2	<25.0	<25.0	528	
H12832-3	SAMPLE POINT 3	<25.0	<25.0	\ 400	
H12832-4	SAMPLE POINT 4	<25.0	28.7	464	
H12832-5	BACKGROUND	<25.0	<25.0	48	
Quality Cont	rol	1130	870	500	
True Value (1C	1000	1000	500	
% Recovery		113	87.0	100	
Relative Per	cent Difference	11,4	9.9	<0.1	

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl*: Std. Methods 4500-Cl*B *Analyses performed on 1;4 w:v aqueous extracts.

Chemist

Date

H12832A BBC



CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

101 East Marland, Hobbs, NM 88240 2111 Beechwood, Abilene, TX 79603 (505) 393-2326 FAX (505) 393-2476 (325) 673-7001 FAX (325)673-7020 Company Name: 🌶 **ANALYSIS REQUEST** BILL TO Project Manager: P.O. #: Address: Company Attn: Address: Project #: City: Project Name: State: Zip: Project Location: Phone #: Sampler Name: Fax #: FOR LAB USE ONLY MATRIX PRESERV. SAMPLING (G)RAB OR (C)OMP GROUNDWATER # CONTAINERS WASTEWATER Sample I.D. Lab I.D. ACID/BASE ICE / COOI SLUDGE OTHER: OTHER: SOIL 등 DATE TIME H1283-1 PLEASE NOTE. Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim anxing whether based in contract or fort, shall be limited to the amount paid by the client for the analyses. All claims including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service in no event shall Cardinal be liable for incidental or consequental damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise Relinguished By: □ No Received By: ☐ Yes Add'l Phone #: Phone Result: □ No Fax Result: ☐ Yes Add'I Fax #: REMARKS: Relinguished By: Date: Received By: Time's 45 Delivered By: (Circle One) Sample Condition CHECKED BY: Cool Intact
X Yes X Yes (Initials) Sampler - UPS - Bus - Other:

[†] Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476

Pat Capo, 1, 1 2.53PM SPILL MAP 2/26/07 PLEASE DRAW SKETCH OF SPILL AND INDICATE WHERE SPILL ORIGINATED. INSECTION WHITER SPILL 416 G' See 4 T-19-5 R-38-E Sp.11 0 x 35 BW SHU#33 INSECTION LOAX W 1030 OF 00.90" N 320 41, 54.10. Recox 21 BW x Sample point #4 ANCHOR XXXSAMPLE POUNTY 10 X BACK Ground SAMPLE 970 1 4 s

< 1/

(1/4)

MITCHELL ANALYTICAL LABORATORY

2638 Faudree Odessa, Texas 79765-8538 561-5579

Company:	Nalco	Energy	Services

Well Number: Lease:

SHU T-Pump

OXY

Date Run: Lab Ref #:

Location:

5/18/2007 07-may-n34696 Sample Temp:

Date Sampled: Sampled by:

5/14/2007 Kevin Chiles

70

Employee #:

DOM Analyzed by:

		Dis	ssolved G	Eases	M = /1	F 14/4	MF~ /I			
Hydrogen Sulfide Carbon Dioxide Dissolved Oxygen	(H2S) (CO2) (O2)		OT ANAL		Mg/L 259.00	Eq. Wt. 16.00	MEq/L 16.19			
	Cations									
Calcium	(Ca++	·)			450.24	20.10	22.40			
Magnesium	(Mg+-	•			156.16	12.20	12.80			
Sodium	(Na+)				2,752.45	23.00	119.67			
Barium	(Ba++		OT ANALY	/7ED						
Manganese	(Mn+)		JI ANALI	IZED	.06	27.50	.00			
			Anions							
Hydroxyl	(OH-)				.00	17.00	.00			
Carbonate	(CO3=	:)			.00	30.00	.00			
BiCarbonate	(HCO3				1,490.84	61.10	24.40			
Sulfate	(SO4=	:)			450.00	48.80	9.22			
Chloride	(Cl-)				4,304.73	35.50	121.26			
Total Iron	(Fe)				0.14	18.60	.01			
Total Dissolved So	lids				9,863.62					
Total Hardness as CaCO3					1,765.86					
Conductivity MICR	OMHOS/	CM			13,180					
pH 7.79	0			Specific	Gravity 60/	60 F.	1.007			
CaSO4 Solubility @ 80 F.				MEq/L,	CaSO4 s	cale is unlikel	У			
CaCO3 Scale Index										
70.0	L.440	100.0	1.790	130.0	2.30	00				
	1.570	110.0	2.030	140.0	2.30	00				
90.0	L.790	120.0	2.030	150.0	2.53	30				