# GW - 028

# INSPECTIONS & DATA

# 2006 - Present

# Chavez, Carl J, EMNRD

To: Subject: Chavez, Carl J, EMNRD Artesia Refinery (GW-028) Note to File "Inspections"

Director announced that travel was being restricted for inspections with no overnights allowed until further notice.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

## Chavez, Carl J, EMNRD

From: Sent: To: Cc:	Chavez, Carl J, EMNRD Tuesday, September 08, 2009 5:04 PM 'Moore, Darrell'; Lackey, Johnny VonGonten, Glenn, EMNRD; Monzeglio, Hope, NMENV; Cobrain, Dave, NMENV
Subject:	Navajo Refining Company- Artesia Refinery (GW-028) OCD Refinery Inspection March 13, 2008
Attachments:	REFINERY INSPECTION 3-13-08.pdf

### Darrell & Johnny:

Good afternoon. Please find attached the OCD's inspection items from the above subject inspection date. I apologize for the tardiness in getting these to the Navajo Refining Company (NRC) based on my workload and orders. Regardless, this e-mail with attached inspection items serves to notify of the NRC of OCD concerns at the facility during the inspection and after the February 19-20, 2007 OCD Inspection of the facility. You may have notes from the close-out meeting on March 13, 2008 with the OCD concerns, but there may be new concerns based on a review of all of the photos, field notes, and a review of the February 19-20, 2007 OCD Inspection items.

The OCD does want to put NRC on notice that the automated free-product recovery system at KWB-8 was never placed on-line from the February 20, 2007 OCD Inspection close out meeting. To allow a point source of contamination to expand and continue to migrate eastward into the pecan orchard with an increasing volume of dissolved phase contaminants impacting fresh ground water and potentially impacting agricultural resources, nearby pumping agricultural wells and nearby pumping water wells is a serious violation of the WQCC Regulations. The OCD recommends that NRC install the free-product recovery system soon for the protection of the drinking water supply and downgradient water users (general public and agricultural water users) that stand to be impacted by the dissolved phase portion of the plume from the emanating point source of contamination- phase separated hydrocarbons (PSH) on the water table. NRC may also want to explore installing these systems along the axis of the PSH plumes to speed up the removal of free-product and cleanup of the ground water contamination. In addition, any spill locations identified for cleanup should be promptly cleaned up and investigated for the upcoming facility inspection.

I recommend that you review the inspection notes and respond to the OCD within 30 days with a status or update on any noted items and what the NRC has done to address them. The OCD will be going over your C-141 reporting forms to ensure that you have properly reported any releases that were brought to your attention during the OCD inspections and from past reported releases as the facility. You may also comment on any photos with imprecise information for the record.

Thank you and I look forward to our upcoming facility inspection where we will follow-up with NRC from its inspections.

Please contact me if you have questions.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

# **REFINERY TANK CONSTRUCTION INSPECTION**



New Rose Unit installed at the former Tank 437 area to treat heavier Canadian Crude (~18K bbl/day)



Rose Unit



Rose Unit



Pitch Tank 814 Built 3 yrs old (10K bbl)




Pitch Tank 814 w/ temperature gauge




Pitch Tank 814 concrete base ring w/ pig tail design and high temp liner



Pitch tar piping leak evident



Pitch Tank 814 Investigate leaking bottom?



Pitch Tank 814 Overflow pitch tar spill needs cleanup here




Pitch Tank 814 close up of tar contained on ground in berm area



Pitch Tank 814



Pitch Tank 814



Pitch Tank 814 Tank gauging station at tank



Pitch Tank 814 Close up on tank gauging station



Pitch Tank 814 Overflow spill evident on walls where tank gauging station is located



Pitch Tank 814 Overflow evident on tank where gauging station is located



Pitch Tank 814 insulated lines into tank



Pitch Tank 814 pig tail




Pitch Tank 814





Tank 814 Built in 2005 w/ high-temp liner within concrete base ring w/ tattle tail drains at 180° orientation



Pitch Tank 814 Insulated



Central chemical storage sump w/ leak detection system



Central chemical storage pad w/ drainage sump location to control spills



Close-up of recently constructed central chemical storage area



Close-up of sump w/ leak detection system location on pad in central chemical storage area



Chemical totes stored in centralized chemical storage area



Centralized chemical storage area



Area set aside for construction



Area set aside for construction




Empty totes stored outside of centralized pad area



Empty totes stored outside of centralized storage area




Older tanks constructed on top of ground w/o liner or concrete base ring design



Tank 402 constructed on ground w/o concrete base ring construction, liner & pig tail drainage system



Older (> 4 yrs) tank construction



Older tank constructed on ground



Mild hydro cracking & hydrogen unit (3M/ft3/day) construction in progress to process Canadian crude (heavy oil at Rose Unit)



Close-up mild hydro cracking & hydrogen unit



Close-up mild hydro cracking & hydrogen unit ( $\sim 3M/ft3/day$ )



Tank 815 (80K bbl) Built ~ 2 yrs. ago. Ultra-low sulfur diesel leak needs cleanup and investigation to determine if fractured ring base has caused a leak in the tank?



Tank 815 Fluid level at 17.4 ft.



Tank 815 Fluid Level Indicator reading 17.4 ft. of fluid in tank



Tank 815 Concrete ring break (tank installed off-center) & w/o liner underneath, but w/ pigtail drains



Tank 815 Water draw



Tank 815 Perimeter concrete ring



Tank 815



Tank 815 Fractured concrete ring base



Tank 815 Perimeter concrete ring fracture w/ pigtail drain @ 90° angles



Tank 815 Fractured concrete ring base



Tank 815 Fractured concrete ring base



Tank 815 Concrete base ring fracture




Tank 815 Concrete base ring damage



Tank 815 water draw leak location close-up



Tank 815 low-sulfur diesel leak from water withdrawal location



Tank 815 leak need cleanup and investigation



New Tank 1225 Crude tank (100K bbls) construction of concrete base ring w/ subliner (~120 ft. Dia.)



Tank 1225 Concrete ring 1.5 dia. w/ 5 min. pressure test on double welded seam at 30 psi on 60-mil HDPE liner system



Tank 1225 Double heat seamed liner 60-mil HDPE



Tank 1225 Thermal welded liner to inner perimeter of concrete base ring



New Tank 437 location w/ 60-mil HDPE liner N of Tank 450



Tank 437 double weld seams w/ pressure test results in white chalk



Tank 437 pressure test results in white chalk



Tank 437 One inch tattle tale leak detection system pipe oriented at 90° angles



Tank 437 pressure test results near perimeter



Tank 437 Sump area ~ 5ft x 7 ft some pressure loss noted on E side thought to be heat related (Matrix Services, Inc. John Dyring 282-458-8781)



Cut dirt from construction areas stockpiled on site near new tanks



New Tank 437 Matrix Services, Inc. overseeing construction of liner w/ testing



Tank 437 pressure up 30 psi for 5 min. between double thermal seams.



Tank 437 perimeter close-up



Tank 437 Thermal seaming machine tool



Tank 437 Pressure test in progress w/ pressure gauge between liner seams holding pressure



Tank 437 Pressure test in progress between seams w/ test results recorded on liner w/ white chalk



Tank 437 between seam pressure test record in progress: on 3/13/08 @ 13:38 at 37 psi awaiting 5 min. pressure reading



Tank 437 Side seaming tool



Tank 437 Heating element for side seaming tool



Tank 437 Sump w/ water draw collection area




Tank 437 60-mil HDPE liner double seamed



Tank 437 in. pig tail drain @ 90° orientation



Tank 437 Close-up of one inch pig tail drain pipe



Tank 437 Pigtail along outer perimeter



Tank 437 liner appears to be sandwiched into the top of concrete base ring



Tank 437 Pressure gauge set into double seam



Tank 437 Close-up of pressure gauge between seams from different angle



Thermally welded seam against concrete ring



Tank construction area



Tank 437 pressure testing



Looking S along S. Bolton Rd. at flush mount MWs E of roadway- wells unlocked



S Bolton Rd. flush mount MW at recovery well area to stop migration of GW contamination from moving further SE



Looking W-NW from N Bolton Rd at refinery in background



Looking W-NW across agricultural lands toward refinery from E Main St. or Hwy. 82



Looking E-SE from S Bolton Rd Agricultural fields in distance



Looking SE across intersection of Main & N Bolton Rd at agricultural farm field



S Bolton Rd Recovery Well power grid



Looking NW from S Bolton Rd toward refinery from RW-11 area



Looking W-NW from S Bolton Rd through agricultural farm field toward refinery (plume spur migrating SE from facility)



Looking W-SW from Adams Ave. toward refinery



Dirt removed & stockpiled from construction activity



Construction dirt stockpiles



Looking W-NW from Main & N. Bolton Rd



Looking E from N Bolton Rd. at Eagle Draw- no oily sheen visible



Looking W at Eagle Draw looking from N Bolton Rd- good physical appearance



Looking W-SW Eagle Draw in foreground in good physical appearance & condition



Looking W-SW from N. Bolton Rd. Pecan Orchard in background



Zoom in from S. Bolton Rd. looking W



Looking due W from N Bolton Rd.



Looking due W at refinery from N Bolton Rd

Notes (action items highlighted in yellow):

1) Flush mount recovery and monitor wells were not locked and were accessible to public. Locks were not installed from

2/19/2007 Close Out Inspection Meeting.

2) Cleanup and investigate source of leak on Tank 815.

3) Tank 814 leak needs to be cleaned up and investigated.

4) Certify Tank 815 w/ fractured concrete ring base is fit for continued service by PE or decommission tank due to safety and environmental hazard risk.

5) Gary Davis (NRC Engineer) states that tanks built within last 6 yrs. include the liner w/ pig tail drainage design. Unlike Tank 815, new tanks will be properly centered on concrete base ring to prevent tank base failure from occurring.

John Dyring of Camerino San Juan
281-458-8781 7021 Gregdale Rd., Houston TX 77049 subcontracted by Matrix Services, Inc. for liner construction & testing.

7) Camerino will ensure that sub liner systems pass all pressure testing before tank is constructed over concrete base ring.

8) Pitch tanks consist of Tanks 410,
418, and 431. New tanks consist of Tanks
450, 815, 850 (96-98) w/ Tank 858 rebuilt.

9) New Sulfur Recovery Units are located E of Tank 57, but OCD was not notified under a "Modification" to the permit.

10) Five RWs on S Bolton Rd. tied into KWB-8 recovery system with activation expected within next quarter?

11) Automatic 24/7 free-product recovery system to remove the source of ground water contamination required from 2/19/07 inspection has not been installed yet.

12) Former Tank 437 moved to new location and oil contamination from leaky crude oil transfer pump cleaned up from OCD 2/19/2007 Close-Out Meeting Inspection?

13) Centralized chemical storage area was constructed per 2/19/2007 OCD Close-Out Meeting to store containers with chemicals and any non-rinsed chemical containers.

14) Triple rinse process being incorporated into discharge permit renewal.

15) Secondary containment under crude oil transfer pumps status?

16) Cat fine drums in bundle cleaning area need to be stored in the newly constructed chemical storage area.

17) Hazardous waste container storage area requires similar impermeable pad storage area.

18) Inspected RCRA pond area W of Pecos River contaminated with arsenic, selenium, benzene in ground water.
Background conditions exist N of ponds.
Benzene plume emanating from well in pond area NW toward Pecos River.
19) Visited UIC Class I WDW-3

Disposal Well & discussed public notice procedures.

# Chavez, Carl J, EMNRD

From:	Chavez, Carl J, EMNRD
Sent:	Tuesday, September 08, 2009 4:46 PM
То:	'Moore, Darrell'; Lackey, Johnny
Cc:	VonGonten, Glenn, EMNRD; Monzeglio, Hope, NMENV; Cobrain, Dave, NMENV
Subject:	Navajo Refining Company- Artesia Refinery (GW-028) OCD Refinery Inspection February
	20-21, 2007
Attachments:	REFINERY INSPECTION 2-19-20-07.pdf
Cc: Subject:	VonGonten, Glenn, EMNRD; Monzeglio, Hope, NMENV; Cobrain, Dave, NMENV Navajo Refining Company- Artesia Refinery (GW-028) OCD Refinery Inspection February

Darrell & Johnny:

Good afternoon. Please find attached the OCD's inspection items from the above subject inspection dates. I apologize for the tardiness in getting these to the Navajo Refining Company (NRC) based on my workload and orders. Regardless, this e-mail with attached inspection items serves to notify of the NRC of OCD concerns at the facility during the inspection. You may have notes from the close out meeting on February 20, 2007 with the OCD concerns, but there may be new concerns based on a review of all of the photos and field notes.

I recommend that you review the inspection notes and respond to the OCD within 30 days with a status or update on any noted items and what the NRC has done to address them. You may also comment on any photos with imprecise information for the record.

Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>CarlJ.Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")


# **REFINERY INSPECTION**



Looking south on S. Bolton Rd going to MWs



Flush mount wells along S Bolton Rd-unlocked



Unlined West Storm Water Retention Pond sample location



Cooler w/ ice, sample containers, chain-ofcustody forms, etc.



Sample location West Storm Water Pond



Cooler w/ samples in containers under ice



Chain-of-Custody form paperwork in the field during sample event- QA/QC



Samples collected in stored following DQOs & EPA QA/QC Procedures



Looking south inlet to storm water retention pond & sample location



Line w/ pump to use fresh water in storm water retention pond when necessary.



Samples contained within baggies placed in ice w/ labels marked in waterproof ink



OCD Chain-of-Custody form- sample record



Looking south at storm water retention pond inlet



SE of farm field ~ KWB-13



KWB-13 Milky turbidity appearance of GW w/ SWL  $\sim$  22 ft.




KWB-13 Disposable Bailer farm field in background



KWB-13 Using New Disposable Bailer



Looking north from recovery well field located SE of refinery w/ flat topography in background Agricultural area.




GW from KWB-9



KWBs 12A & 12B locations: no PSHs present in GW at KWB-12B & 12A was a dry well



KWB-9 no PSHs present in GW



KWB-3R location



Sample cooler stored in locked vehicle




Vehile storage area



KWB-3R no PSH present in GW



KWB-8 in pecan orchard in-line w/ GW plume.



KWB-8 Approx. 16-18 in. PSHs in GWoperator currently bailing to remove product



KWB-8 Gas odor touch bottom of well, pure product in well



KWB-P2 no PSHs in GW



WWTP API used as settling basin for FCC fines



WH 5 drum storage pad catchment system full of sand w/ berm needed for containment




WH 5 Chemical drum storage pad-improper secondary containment




Warehouse 5 chemical drum storage padissue #1




Tank 18 Steam leak at based of Carbon Black Oil tank.



The Bullring-storage area for empty totes and drums on ground w/o secondary containment.




The Bullring-storage area for empty totes and barrels



Tank# 815-new tank built on concrete ring w/o modification request to OCD



Tank# 439 release form tank due to overflow



Tank# 61 signs of Carbon Blk. Oil leaks



Tank# 59 CBO leak



Tank# 58 signs of CBO leaks



Tank# 58 CBO leaks



South Plant API



South Gasoline pump area sump



South Gasoline pump area sump



South Gasoline pump area sump



South bundle pad-FCC fine storage



Small leak in one of the Carbon Black Oil lines beside slurry oil treatment area



Small leak in one of the Carbon Black Oil lines beside slurry oil treatment area



Small leak in one of the Carbon Black Oil lines beside slurry oil treatment area



Small leak in carbon black oil line beside Tank# 58



Slurry Oil Treatment area - steel tanks placed in existing concrete containment



Slurry Oil Treatment area - Back of building-NMED investigation plan



Pumps at WWTP



Old evaporation ponds-fugitive waste barrels



Old evaporation ponds-fugitive waste barrels



Old evaporation ponds-fugitive waste barrels




Old evaporation ponds




Old evaporation ponds



North Plant API



New small leak in carbon black oil line beside Tank# 58



New ROSE Unit - installed over old API removal area



New Dual API Unit



Recovery well storage tank labeled



Slurry oil treatment unit



Issue 11 repair of small leak in carbon black oil line



Issue 9 - South Plant tank #419 repair, leak, and cleanup



Issue 6- gas-oil pumps sump - area not in service




Improper storage of totes (no 2nd containment) WWTP




Improper storage of totes (no secondary containment) WWTP



Improper storage of totes (no secondary containment) WWTP



Improper storage of totes (no secondary containment) WWTP



Improper storage of totes (no secondary containment) WWTP




Improper storage of totes (no secondary containment) WWTP



Improper storage of materials without secondary containment-rail yard loading area for CBO




Hazardous waste containers (no secondary containment) - TEL impoundment



Gas Company of NM yard - improper storage, no secondary containment




Gas Company of NM yard - improper storage of spent material



Gas Company of NM yard - improper storage of spent material




Gas Company of NM yard improper storage of spent material



Gas Company of NM yard improper storage of spent material



Gas Company of NM Pipeline Group yard improper storage, no 2nd containment



Gas Company of NM Pipeline Group yard improper storage, no 2nd containment



Gas Company of NM Pipeline Group yard improper storage, no 2nd containment



Gas Company of NM Pipeline Group yard improper storage, no 2nd containment



FCC no secondary containment (concrete pad) of totes



Effluent from RO system to farm (~7K bbls/day)




Effluent from RO system discharge for irrigation (alfalfa & chile farming)




Crude oil pump area near Tank 437 and LACT area- secondary containment not provided for all pumps, but needed badly




Crude LACT unloading area- concrete poured between pads per last OCD requirement during inspection.



Crane Shaft Fueling Area-saddle tanks w/ secondary containment



Contamination on ground from leaky crude oil transfer pump in need of cleanup & secondary containment.




Open vessel container of lube oil w/ soil staining around pump in background



Closed solid waste landfill-TEL impoundment in background




Closed solid waste landfill



Closed solid waste landfill



Closed solid waste landfill



Central containment area -secondary containment not present



Central containment area -secondary containment not present



Central containment area – secondary containment not present

Notes (action items highlighted in yellow):

 Required automated free-product recovery system at KWB-8 location to remove point source of contamination from GW 24/7 & prevent expansion of plume into pecan orchard at 2/19/2007 Close Out Inspection Meeting.

2) Flush mount recovery and monitor wells were not locked and were accessible to public. Need locks to prevent access.

3) KWBs 7, 11A&B had no PSHs in GW

4) Nine recovery wells hooked up to RW-11 system for pump back to API separator and treatment, and to capture the plume spur moving SE toward MW-57 into the farm field and separate from the plume moving E toward KWB-8. Did not check free-product at these RWs, but PSHs are known to be present there.

5) Tank 437 oil leakage to ground on E side from crude oil transfer pump w/ cleanup & secondary containment needed under pump. Cleanup needed (see photos).

6) Old API Separator at S. Plant removed and replaced w/ Rose Unit (32.84402 -104.39280), which OCD was not notified of a modification for new process area. Permit modification request violation of permit.

7) Tank 419 Flow back repaired from last permit inspection.

8) Chemical totes and drums (1993;
3264; 3261; 3265, 1993; 2924; 3266 &
2693) stored on ground throughout refinery in violation of permit. Operator claims construction of impermeable centralized dual storage area in progress to address this violation.

 Gas Company of NM Yard stored drums of FCC dispersant, spent catalysts, T610 Solvent; spent catalyst prop media stored > 180 days is a waste storage

violation. Empty chemical totes stored on ground is a violation. Operator claimed they were triple rinsed before storage.

Incorporate triple rinse into permit renewal to store rinsed empty containers in impermeable areas?

10) North plant API out of service during inspection.

11) S plant OAPI Separator removed & Rose Unit installed. Failure by operator to notify OCD of Rose Unit installation as "Modification" request under permit.

12) OCD inquired about diesel treatment area fire on 11/1/2006 at 13:30 that was not reported as a major release under a C-141 Form to the OCD. This is a violation to reporting under the permit.

13) Tank 419 flow-back not repaired per last OCD inspection requirement.

14) Chemical drums and totes containing chemicals were not stored in impermeable pad(s). Operator indicated centralized chemical storage area was under construction to facilitate storage & inquired about triple-rinse cleaning procedure on empty drums and totes to store on ground for new discharge permit.

15) Slurry slinger centrifuge shed installed steel box into cement vault to contain slurry received as carbon black oil.

16) There was a pipeline leak noticed SW of Tank 63 (32.85097 -104.39596) that needs to be cleaned up and fixed. It appears to be contaminated steam water. Fix source and cleanup spill. 17) Steam line leak at Carbon Black Oil
Tank 18 in need of repair.
18) Leaky pump between Tanks 58 & 59
with stained soils in need of cleanup &
pumps in need of repair. Noticed open
vessel with oil near pump (32.85028 104.39606).
19) Leak stains noticed on Tanks 58

sidewall & 59 leaky bottom needs cleanup & investigation.

20) Hazardous wastes casks/dumpster noticed on ground- no secondary containment. Secondary containment needed in the hazardous waste storage area.
21) Secondary containment needed around all crude oil transfer pump locations without secondary containment.

### Chavez, Carl J, EMNRD

From:	Chavez, Carl J, EMNRD
Sent:	Tuesday, September 08, 2009 4:46 PM
То:	'Moore, Darrell'; Lackey, Johnny
Cc:	VonGonten, Glenn, EMNRD; Monzeglio, Hope, NMENV; Cobrain, Dave, NMENV
Subject:	Navajo Refining Company- Artesia Refinery (GW-028) OCD Refinery Inspection February
	20-21, 2007
Attachments:	REFINERY INSPECTION 2-19-20-07.pdf

#### Darrell & Johnny:

Good afternoon. Please find attached the OCD's inspection items from the above subject inspection dates. I apologize for the tardiness in getting these to the Navajo Refining Company (NRC) based on my workload and orders. Regardless, this e-mail with attached inspection items serves to notify of the NRC of OCD concerns at the facility during the inspection. You may have notes from the close out meeting on February 20, 2007 with the OCD concerns, but there may be new concerns based on a review of all of the photos and field notes.

I recommend that you review the inspection notes and respond to the OCD within 30 days with a status or update on any noted items and what the NRC has done to address them. You may also comment on any photos with imprecise information for the record.

1


Thank you.

Carl J. Chavez, CHMM New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division, Environmental Bureau 1220 South St. Francis Dr., Santa Fe, New Mexico 87505 Office: (505) 476-3490 Fax: (505) 476-3462 E-mail: <u>Carl J. Chavez@state.nm.us</u> Website: <u>http://www.emnrd.state.nm.us/ocd/</u>index.htm (Pollution Prevention Guidance is under "Publications")

# **REFINERY INSPECTION**




Looking south on S. Bolton Rd going to MWs



Flush mount wells along S Bolton Rdunlocked




Unlined West Storm Water Retention Pond sample location




Cooler w/ ice, sample containers, chain-ofcustody forms, etc.




Sample location West Storm Water Pond




Cooler w/ samples in containers under ice




Chain-of-Custody form paperwork in the field during sample event- QA/QC




Samples collected in stored following DQOs & EPA QA/QC Procedures




Looking south inlet to storm water retention pond & sample location




Line w/ pump to use fresh water in storm water retention pond when necessary.



Looking south at storm water retention pond inlet




Samples contained within baggies placed in ice w/ labels marked in waterproof ink



OCD Chain-of-Custody form- sample record




SE of farm field ~ KWB-13



KWB-13 Milky turbidity appearance of GW w/ SWL ~ 22 ft.



KWB-13 Disposable Bailer farm field in background




KWB-13 Using New Disposable Bailer




Looking north from recovery well field located SE of refinery w/ flat topography in background Agricultural area.

a and a second a second se




KWB-3R location


KWBs 12A & 12B locations: no PSHs present in GW at KWB-12B & 12A was a dry well







KWB-8 in pecan orchard in-line w/ GW plume.




KWB-8 Approx. 16-18 in. PSHs in GWoperator currently bailing to remove product




KWB-8 Gas odor touch bottom of well, pure product in well





KWB-P2 no PSHs in GW




WWTP API used as settling basin for FCC fines








WH 5 Chemical drum storage pad-improper secondary containment




Warehouse 5 chemical drum storage padissue #1




Tank 18 Steam leak at based of Carbon Black Oil tank.




The Bullring-storage area for empty totes and drums on ground w/o secondary containment.




The Bullring-storage area for empty totes and barrels




Tank# 815-new tank built on concrete ring w/o modification request to OCD



Tank# 439 release form tank due to overflow




Tank# 59 CBO leak




South Plant API

......


South Gasoline pump area sump




South Gasoline pump area sump




South Gasoline pump area sump




South bundle pad-FCC fine storage




Small leak in one of the Carbon Black Oil lines beside slurry oil treatment area




Small leak in one of the Carbon Black Oil lines beside slurry oil treatment area




Small leak in one of the Carbon Black Oil lines beside slurry oil treatment area




Small leak in carbon black oil line beside Tank# 58




Slurry Oil Treatment area - steel tanks placed in existing concrete containment




Slurry Oil Treatment area - Back of building-NMED investigation plan




Pumps at WWTP




Old evaporation ponds-fugitive waste barrels



Old evaporation ponds-fugitive waste barrels




Old evaporation ponds-fugitive waste barrels




Old evaporation ponds




Old evaporation ponds




North Plant API




New small leak in carbon black oil line beside Tank# 58



Issue 11 repair of small leak in carbon black oil line




Issue 9 - South Plant tank #419 repair, leak, and cleanup




Issue 6- gas-oil pumps sump - area not in service



Improper storage of totes (no 2nd containment) WWTP



Improper storage of totes (no secondary containment) WWTP



Improper storage of totes (no secondary containment) WWTP




Improper storage of totes (no secondary containment) WWTP




Improper storage of totes (no secondary containment) WWTP




Improper storage of totes (no secondary containment) WWTP




Improper storage of materials without secondary containment-rail yard loading area for CBO



Hazardous waste containers (no secondary containment) - TEL impoundment




Gas Company of NM yard - improper storage, no secondary containment




Gas Company of NM yard - improper storage of spent material




Gas Company of NM yard - improper storage of spent material



Gas Company of NM yard improper storage of spent material





Gas Company of NM Pipeline Group yard improper storage, no 2nd containment

