1R - A D T D D

WORKPLANS

Date:

1R427-180

Tel: 432-634-9257 E-mail: lpg@texerra.com

June 11th, 2010

2010 JUN 21 A 11: 00

Mr. Edward Hansen

New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division, Environmental Bureau 1220 S. St. Francis Drive Santa Fe, New Mexico 87504

RE: Investigation and Characterization Plan Rice Operating Company – EME SWD System EME N-18 <u>Junction</u>: UL N Sec 18 T 20S R 37E

Sent via E-mail & U.S. Certified Mail w/ Return Receipt No. 7007 0710 0003 0305 3873

Mr. Hansen:

RICE Operating Company (ROC) has retained Texerra to address potential environmental concerns at the above-referenced site located in the EME SWD system. ROC is the service provider (agent) for the EME SWD System and has no ownership of any portion of the pipeline, well, or facility. The System is owned by a consortium of oil producers, System Partners, who provide all operating capital on a percentage ownership/usage basis. Environmental projects of this magnitude require System Partner AFE approval, and work begins as funds are received. In general, project funding is not forthcoming until NMOCD approves the work plan. Therefore, your timely review of this submission would be greatly appreciated.

For all such environmental projects, ROC will choose a path forward that:

- protects public health,
- provides the greatest net environmental benefit,
- complies with NMOCD Rules, and
- is supported by good science.

Each site shall generally have three submissions, as described below:

- 1. This <u>Investigation and Characterization Plan</u> (ICP) is proposed for data gathering and site characterization and assessment.
- 2. Upon evaluating the data and results from the ICP, a recommended remedy will be submitted in a <u>Corrective Action Plan</u> (CAP) if this is warranted.
- 3. Finally, after implementing the remedy, a <u>Closure Report</u> with final documentation will be submitted.

Rice Operating Company - EME N-18 Junction

Background and Previous Work

The site is located approximately 3.7 miles south of Monument, New Mexico (Figure 1). The topography is gently sloping toward the southeast. Soils on the location are characterized in the Lea County Soil Survey as moderately deep to deep sandy soils that are underlain by hard caliche. NM OSE records indicate that groundwater is likely to be encountered at a depth of 30+/- feet in unconsolidated Tertiary alluvium of the Ogallala Formation.

ROC removed a wooden junction box at this location in August of 2004 as part of its facility maintenance and upgrade program. (See Figure 2: Rice Junction Box Disclosure Report). As the original wood junction box was removed soils were sampled using a backhoe, creating a 35 by 25 by 12 ft deep excavation (Figures 3 & 4). The excavated soils were blended and then backfilled into the excavation to a depth of 6 ft bgs where a one foot thick compacted clay barrier was installed (Figure 5). The remaining excavated soil material was backfilled into the excavation above the clay barrier to the existing ground surface (Figure 6). The disturbed surface was then seeded with a native vegetation mix (Figure 7).

It should be noted that there is no longer a threat of continued, compounded impact at this site as the former junction box has been removed and a clay barrier installed to impede the downward migration of chlorides.

Elevated soil chloride concentrations were found at depth 10 ft south and east of the former junction box (Figure 2). Insignificant concentrations (< 100 ppm) of gasoline (GRO) and diesel range organics (DRO) were encountered in the excavated soil and in the sidewalls and bottom of the excavation (Figure 2). Petroleum hydrocarbons were therefore ruled out as a potential constituent of concern.

ROC proposes additional investigative work to determine if there is the potential for groundwater degradation from residual soil chlorides, which are the constituent of concern, as outlined below.

Proposed Work Elements

- 1. Summarize information and data collected by ROC to date.
- 2. Summarize additional, publicly available regional and local hydrological information.
- 3. Conduct vertical and lateral delineation of soil <u>chlorides</u>. If warranted, install a monitor well to provide a direct measurement of potential groundwater impact. [All monitoring wells will be constructed per NM Dept. Environment standards].
- 4. Evaluate the risk of groundwater impact in light of the information obtained.

Rice Operating Company – EME N-18 Junction

If the evaluation demonstrates that residual constituents pose no threat to ground water quality, then only a surface restoration plan will be proposed to OCD. If this work indicates that there is a present or future risk of impacting groundwater quality from past operations at this location, then a corrective action plan (CAP) will be developed and proposed to OCD.

I appreciate the opportunity to work with you and your staff on these projects. Please call either myself, at the number below, or Hack Conder (ROC) at 575-393-9174, if you have any questions or wish to discuss these matters.

Thank you for your consideration.

Sincerely,

L. Peter (Pete) Galusky, Jr. Ph.D., P.G.

Principal

Copy: Rice Operating Company




Figure 1 – EME N-18 Junction location on USGS 1:100,000 topographic base map

				PERATING BOX DISCLO	_					
				BOX LOCAT	BON					
SWD SYSTEM J	YSTEM JUNCTION UNIT				COUNT		IMENSIONS - FEET			
EME	N-18	N	18	208	37E	Lea	Length 11	Width 7	Depth 5	-
				<u> </u>	1		1	<i>:</i> l		٢
LAND TYPE: BLM	STATE	EFE	E LAND	OWNER	Jenny T. C	cooper	OTHER			_
Depth to Groundw	etter <u>35</u>	5fee	対	NMOCD	SITE ASSE	SSMEN	IT RANKING S	CORE:	20	
Date Started 8/9/2004 Date Completed 8/27/2004						00	CD Witness No			
Soil Excavated	389	_aubic yards	Ex	cavation Le	ngth35	w	7olth25	Depth	12	feei
Soil Disposed	0	_cubic yards	Of	ffsite Facility	n	/a	Location	 	n/a	
FINAL ANALYTI	CAL RESI	H TS:	Samn	de Date	8/23/20	Y04	Sample De	enth	12 ft	
LINVE VIVE I II	OAL REGU	LIO.	Gaziip		<u> </u>			.p.c		
Procure 5-point cor excevation sidewalls.							CHLOR	IDE FIELD	TESTS	
an approved lab										
	l oin	1 000		DBC	(Alleria)		LOCATION	DEPTH (pm Fo
Sample Location	PID	GRO mg/kg		<u>DRO</u> mg/kg	Chloride mg/kg	·]		6_	-	<u>59</u>
	ррт 0.0	<10.0	<u> </u>	<10.0	255			7		30
4-WALL COMP.	0.0	<10.0		<10.0	425		vertical at	8		20
BOTTOM COMP.	0.0	<10.0		<10.0	404		junction	9		<u>30</u>
REMED. BACKFILL	0.0	1 (10.5		- 10.0	1			10		00
								11	-	60 09
General Description of	f Remedial Ac	tion: Th	rie iumelios	n how eite were d	followater			12 6		10
General Description of Remedial Action: This junction box site was defineated using a packhoe while PID field screenings and chloride field tests were conducted at regular							10 ft south of junction	7		69
intervals. All PID readings were relatively low and lab results confirmed TPH concentrations well								8		32
below NA/OCD guidelines. Although chloride concentrations declined laterally throughout the								9		 90
35 x 25 x 12-ft-deep excavation, chloride concentrations did not decline with depth in								10)50
some areas. The excavated soil was blended on site and backfilled into the excavation up to								11	16	520
6 ft BGS. At 6 ft, a 1-ft-trick compacted clay barrier was installed to inhibit further downward								12		60
migration of chloride. The remained soils were backfilled on top of the clay. A new watertight							10 ft east of junction	6		50
Junction pox was built over this location. On 10/18/2004, the disturbed surface was seeded with								8	10	119
a bland of native vegetation and is expected to return to productive capacity at a normal rate.								10		89
A identification plate has been placed on the surface for future environmental considerations								12		69
and to mark the presence	of clay below. NN	IOCD has bee	n notified	of potential gro	undwater imp	act_	4-wail comp.	n/a	 -	90
ADDITIONAL EVALUATION IS HIGH PRIORITY							bottom comp.	12	50	09
enclosures: chloride graph	s, photos, lab res	uits, PID lield	screening	s, clay test, dia	yrem		remed. backfill	n/a	20	69
	· · · · · · · · · · · · · · · · · · ·		****							
I HEREBY (CERTIFY THA	T THE INFO	KNOV	WLEDGE AN	IS TRUE AI ID BELIEF. allable		MPLETE TO TH			x
	P	_			1/	一. ~	· /	`	~wester 1.	
REDOOT ASSEMBLED BY		n Englis har-		CIONATIO	20	101 2) V.	00	
REPORT ASSEMBLED BY		n Famis Pope 5/27/2005		SIGNATURE	#n	11/1) Vais	(D) J 6	DR_	_

Figure 2 – EME N-18 Junction Box Disclosure Report



Figure 3 – Initial excavation during replacement of junction box at EME N-18.



Figure 4 – Excavation of former junction box at EME N-18.

Rice Operating Company – EME N-18 Junction



Figure 5 – Installation of subsurface clay barrier at EME N-18 Jct.



Figure 6 – New/replacement junction box at EME N-18.

Rice Operating Company – EME N-18 Junction



Figure 7 – Seed of surface w/ native vegetation mix at EME N-19 Junction.