

**Eclipse Oil & Gas Inc.
API # 30-025-36171
State D SWD # 1
UL I, Sec 9, T14S, R33E
Plugging Procedure**

**8 5/8" casing set in 12 1/4" hole at 373 ft. Cement with 200sx . Cmt Circulated
5 1/2' casing set in 7 7/8" hole at 4337 ft. Cmt with 775 sx. Cmt Circulated
Open hole from 4337 – 5480 ft
PSA at 4324ft on 2 7/8" IPC tbg**

- 1. Move in plugging rig**
- 2. Bled down pressure on tbg and casing as needed**
- 3. NU BOP**
- 4. Release pkr and pull tbg and pkr**
- 5. Run and set CIBP at 4300ft**
- 6. Cap CIBP with 35ft of cmt by dump bailer**
- 7. Run tbg open ended and tag cmt cap at 4265ft**
- 8. Displace well with gelled brine water**
- 9. Pull tbg to 1680ft**
- 10. Spot 25 sx cement plug**
- 11. Pull tbg to 425ft**
- 12. Circulate cmt to surface, Estimated 35 sx cmt**
- 13. Pull tbg**
- 14. Cut off well head and install PA marker**
- 15. Rig down move out plugging rig**
- 16. Cut off anchors, Clean location**
- 17. Remove tank and pump at disposal facility**
- 18. Clean and level location and battery site**

BEP 7/22/03

**Before the OCD
Case 13456
OCD Ex. 10**