

Charles E. Yancura  
State 43-35 # 1  
~~30-025-02180~~ 02910  
UL I, Sec 35, T16S, R35E 1980FSL 660FEL  
Plugging Procedure

13 3/8" CSA 337 feet, Cement Circulated  
9 5/8" CSA 4980 feet, Cemented with 3400 sacks cement, Unknown TOC, Calculated volume should have circulated..  
5 1/2" CSA 12801 feet, Cemented with 500 sacks cement, Unknown TOC  
Well fluids will circulated to steel pit or plastic lined pit

Well side tracked from 9668 feet to 10150 feet??

1. Move in rig up plugging rig
2. Nipple up BOP
3. Pull production equipment
4. Run and set CIBP at 9620 feet
5. Run tubing open ended and tag CIBP
6. Displace well with 25lb/bbl gelled brine water
7. Spot 25 sack cement plug
8. Pull tubing to 8330 feet
9. Spot 25 sack cement plug
10. Pull tubing to 6312 feet
11. Spot 25 sack cement plug
12. Pull tubing
13. Weld on pull nipple and stretch 5 1/2" casing
14. Cut and pull 5 1/2" casing from freepoint
15. Run tubing to 50 feet inside of 5 1/2" casing stub
16. Spot 40 sack cement plug
17. Pull tubing and WOC
18. Run tubing and tag cement plug, Maximum depth is 50 feet about 5 1/2" casing stub.
19. Pull tubing to 5030 feet
20. Spot 40 sack cement plug
21. Pull tubing and WOC
22. Run tubing and tag cement plug, Maximum depth is 4930 feet
23. Pull tubing to 2060 feet
24. Spot 40 sack cement plug
25. Pull tubing to 387 feet
26. Spot 40 sack cement plug
27. Pull tubing and WOC
28. Run tubing and tag cement plug, Maximum depth is 287 feet
29. Pull tubing to 60 feet
30. Circulate cement to surface
31. Pull tubing
32. Cut off well head and install PA marker
33. Rig down move out plugging rig
34. Cut off service unit anchors and clean location

