## M&G Oil, Inc Santa Fe # 1 API # 30-025-04980 UL C, Sec 30, T9S, R37E Plugging Procedure

13 3/8" casing set at 403 feet, Cement Circulated 9 5/8" casing set at 4351 feet, Cemented with 2900 sacks, Temp survey TOC 1320 feet 5 ½" casing set at 12188 feet, Cemented with 1000 sack, Temp survey TOC 9050 Perfs 12173-12183 feet

## All fluids will be circulated to steel pit or plastic lined dirt pit

1.	Move	in	rig	up	plugging	unit
----	------	----	-----	----	----------	------

- 2. Nipple up BOP
- 3. Fish production equipment
- 4. Run gauge ring and junk basket to 12125 feet
- 5. Run and set CIBP at 12125 feet
- 6. Cap CIBP with 35 feet of cement by dump bailer
- 7. Run tubing and tag cement plug at 12090 feet
- 8. Displace well with 9.5 ppg gelled brine
- 9. Pull tubing to 9335 feet
- 10. Spot 25 sack cement plug
- 11. Pull tubing
- 12. Weld on pull nipple and stretch casing
- 13. Cut and pull casing from free point
- 14. Run tubing to 50 feet inside casing stub
- 15. Spot 35 sack cement plug
- 16. Pull tubing and WOC
- 17. Run tubing and tag cement plug, Maximum depth 50 feet above casing stub
- 18. Pull tubing to 7755 feet
- 19. Spot 35 sack cement plug
- 20. Pull tubing 5628 feet
- 21. Spot 35 sack cement plug
- 22. Pull tubing to 4401 feet
- 23. Spot 40 sack cement plug
- 24. Pull tubing and WOC
- 25. Run tubing and tag cement plug, Maximum depth 44301 feet
- 26. Pull tubing to 2270 feet
- 27. Spot 35 sack cement plug
- 28. Pull tubing
- 29. Weld pull nipple on 9 5/8" casing and stretch
- 30. Cut and pull casing from 403 feet if free
- 31. Run tubing open ended to 453 feet
- 32. Spot 40 sack cement plug
- 33. Pull tubing and WOC
- 34. Run tubing and tag cement plug, Maximum depth 353 feet
- 35. Pull tubing to 60 feet
- 36. Circulate cement to surface
- 37. Pull tubing
- 38. Cut off well head and install PA marker
- 39. Rig down move out plugging rig
- 40. Cut off service unit anchors and clean location

