

COMPLETION PROCEDURE
DAN TRIGG NO. 2
CO₂ BRAVO DOME AREA
103' FEL & 3820' FNL
SECTION 32, TWP 15N
RGE 30E, SAN MIGUEL CO.
NEW MEXICO
AFE NO. 72398

October 14, 1980

Page 4

29. GIH and set permanent-drillable bridge plug at 1950' ±.
30. GIH w/2-3/8" tbg & RBP to 1900' ±. Set RBP spot 1 sack sand. Spot 100 gals of 10% Acetic acid from 1850' to 1700'. POH.
31. RU Dresser Atlas. Run 3½" select fire gun w/Jumbo Jet charges, perforate Santa Rosa w/ 1 JSPF, 180° phasing at following depths: 1800, 1802, 1809, 1813, 1816, 1823, 1830, 1835, and 1842 (9 Holes) RD Dresser Atlas.
32. GIH w/ 2-3/8" tbg w/ pkr to 1650' ±.
33. Set pkr and displace perf acid into formation at 2-3 BPM. SD for 2 hours.
34. RU swab and recover loads plus formation fluids. Catch samples of all recovered formation fluids. Productivity tests and gas analysis are to be made.
35. Release pkr and POH. GIH w/2-3/8" tbg and retrieving head. Wash sand off of RBP and reset at 1850' ±. Test to 1000# and spot 1 sack sand.
36. Spot 100 gals of 10% Acetic acid from 1722' to 1575' ±. POH.
37. RU Dresser Atlas. Run 3½" select fire gun w/Jumbo Jet charges, perforate at following depths from top down: 1669, 1672, 1675, 1684, 1691, 1698, 1703, 1710, 1714, 1720 and 1722 (11 holes) RD Dresser.
38. GIH w/2-3/8" tbg w/pkr to 1500' ±.
39. Set pkr and displace perforating acid into formation at 2-3 BPM. SD for 2 hours.
40. RU swab and swab back loads plus formation fluids. Catch samples of all recovered formation fluids. Productivity tests and gas analysis are to be made.
41. Release Pkr and POH. GIH w/2-3/8" tbg w/retrieving head. Wash sand off of RBP and POH.
42. GIH and set permanent-drillable bridge plug at 1600' ±.
43. GIH w/2-3/8" tbg and RBP to 800' ± set RBP, test to 1000# and spot 1 sack of sand on RBP.