

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐GAS WELL ☐

OTHER- Carbon Dioxide

Name of Operator

Texaco, Inc.

Address of Operator

P. O. Box 728, Hobbs, New Mexico 88240

1. Location of Well

UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM

THE West LINE, SECTION 29 TOWNSHIP 30N RANGE 30E

15. Elevation (Show whether DF, RT, GR, etc.)

6410' (GR)

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Form of Lease Name

H. R. Brown NCT-1

9. Well No.

10. Field and Pool, or Wildcat

Undesignated

12. County

Union

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐REMEDIAL WORK ☐ALTERING CASING ☐TEMPORARILY ABANDON ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☐PULL OR ALTER CASING ☐CHANGE PLANS ☐CASING TEST AND CEMENT JOBS ☐OTHER Perforate, Treat & P & A Well ☒OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOTAL DEPTH 2998'

PLUG BACK TOTAL DEPTH 1753'

9 5/8" OD 32.3# H-40 Csg Set @ 821'

7" OD 20# K-55 Csg Set @ 1402'

4 1/2" OD 10.5# K-55 Csg Screwed Into Drill Pipe @ 1758'

1. Perforate 4 1/2" Csg. w/2-BPF from 1480'-1494', 1532'-1540', 1556'-1564', 1608'-1616', 1654'-1666', 1684'-1694' & 1735'-1749'.
2. Acidize perms. 1480'-1749'-w/6000 gals. 7 1/2% MSR-100 60 Quality Nz Foamed acid & 144 Ball Sealers.
3. Set CIBP @ 1330' & Spot 40' (4Sx) Cement on plug. PBID 1290'.
4. Perforate 4 1/2" Csg. w/2 Bullets PF from 940'-960', 1016'-1024', 1076'-1086', 1103'-1120', 1127'-1140', 1160'-1168', 1177'-1180', 1183'-1192', & 1202'-1212'.
5. Acidize perms. 940'-1212' w/7000 gals. 7 1/2% MSR-100 60 Quality Foamed Acid w/120 Ball Sealers. Flush w/Nitrogen.
6. Set CIBP @ 850' & Dump 40' Cement on plug to 810'.
7. Set 5 Sx. Cement plug from 50'-Surface.
8. Set Dry Hole Marker & Clean Up. Well P & A, 12/6/80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Asst. Dist. Supt.

DATE 12/10/80

APPROVED BY

TITLE

SENIOR PETROLEUM GEOLOGIST

DATE

3/23/81

CONDITIONS OF APPROVAL, IF ANY: