

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals, and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-059-20130

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL  
WELL ☐

GAS  
WELL ☐

OTHER

CO2

2. Name of Operator

AMOCO PRODUCTION COMPANY

3. Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

8. Well No.

2433-351G

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

4. Well Location

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
Section 35 Township 24N Range 33E NMPM Union County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
5185 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

2. Describe Proposed or Completed Operations

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103.

10-6-99

MIRUSU, kill well with fresh water, NUBOP, release packer. Pull and lay down 2 3/8" production tubing and packer. Run cast iron bridge plug on wireline, set CIBP at 2492 feet. Run 2 3/8" workstring and tag CIBP, displace casing with fresh water with corrosion inhibited fluid, pressure test casing to 500 psi, ok. Spot 5 sacks of Class C cement from 2492' - 2442', pull workstring to 2116', spot 10 sacks of cement from 2116' - 2020', pull workstring to 30 feet, SDON.

10-7-99

Spot 5 sacks of cement from 30' - 3', NDBOP, cut off wellhead. install PXA marker, RDMOSU, cut off well anchors and clean location.

2/8/00 OK Ref

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE DJ Holcomb TITLE Field Foreman DATE 10-13-99

TYPE OR PRINT NAME Danny J. Holcomb TELEPHONE NO. (505) 374-3010

This space for State Use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 2/10/00

CONDITIONS OF APPROVAL, IF ANY