

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.
30-059-20249

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

1. Type of Well
OIL WELL GAS WELL OTHER CO2

8. Well No.
1834-301G

2. Name of Operator
AMOCO PRODUCTION COMPANY

9. Pool name or Wildcat
BRAVO DOME CO2 GAS UNIT

3. Address of Operator
P.O. Box 303, AMISTAD, NEW MEXICO 88410

4. Well Location
Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line
Section 30 Township 18N Range 34E NMPM Union County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103.

8-25-97
Rig up wire line with tubing cutter. Run in hole and cut 2-3/8" fiberglass tubing @ 2341'. Pull up 2-3/8" workstring. Run in hole and spot 50 sacks of class C cement @ 2408' - 2115'.

8-26-97
Tag top of cement @ 2341'. Pressure tested 7" casing to 500# for 15 minutes. Held. Circulated well with 9.5 gelled brine water. Spot 15 sacks class C cement @ 1918' - 1831'. Spot 5 sacks class C cement @ 30' - 3'. Cut off wellhead and anchors 3' below ground level. Weld steel plate on well. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Operations Specialist DATE 8/9/97

TYPE OR PRINT NAME Billy E. Prichard TELEPHONE NO. (505) 374-3053

(This space for State Use)
APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 9-25-97

CONDITIONS OF APPROVAL, IF ANY: