

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Shell Oil Company	8. Farm or Lease Name Santa Fe
3. Address of Operator 1700 Broadway, Denver, Colorado 80202	9. Well No. Two
4. Location of Well UNIT LETTER L 1650 South 660 FEET FROM THE LINE AND FEET FROM West 29 6N 1W THE LINE, SECTION, TOWNSHIP, RANGE, NMPM.	10. Field and Pool or Wildcat Santa Fe South Block Cactus Area (WC)
15. Elevation (Show whether DF, RT, GR, etc.) 5216 KB, 5194 GL	12. County Valencia

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure:

1. Spot 75 sx at 14,000'
2. Spot 30 sx at 11,300' (to cover 7" shoe)
3. Salvage 7" csg
4. Spot 75 sx at cut-off point
5. If 7" is cut off below 9-5/8" shoe, spot 75 sx across 9-5/8" shoe. (If 7" is cut off above 9-5/8" shoe, 75-sk plug in step 4 should seal the top of the 7" and the 9-5/8"-7" annulus)
6. Spot 10 sx at surface
7. Cut csg off below surface. Weld plate on csg stub.
8. Install dryhole marker. Marker to be "a steel marker at least 4" in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (section, township, range) shall be welded, stamped, or otherwise permanently engraved into the metal of the marker." (Rule 202(a), Section D, State of New Mexico, Oil Conservation Commission, Rules and Regulations.

VERBAL APPROVAL RECEIVED FROM MR. R. L. STAMETS 9/20/74 TO MR. R. D. GRAHAM

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED T.S. Mize TITLE Division Operations Engr. DATE 9/24/74

APPROVED BY Carl Ulvog TITLE SENIOR PETROLEUM GEOLOGIST DATE 10/8/74

CONDITIONS OF APPROVAL, IF ANY: