

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NMAP1825639448
District RP	2RP-4969
Facility ID	fMAP1825638850
Application ID	pMAP1825639110

Release Notification

Responsible Party

Responsible Party Breitburn Operating, LP	OGRID: 370080
Contact Name: Thomas Haigood	Contact Telephone: (432) 701-7802
Contact email: Thomas.haigood@breitburn.com	Incident # (assigned by OCD)
Contact mailing address: Po Box 678 Andrews, TX 79772	

Location of Release Source

Latitude: 32.72083 N Longitude: 104.16500 W
(NAD 83 in decimal degrees to 5 decimal places)

Site Name State 647-711	Site Type: Tank Battery
Date Release Discovered: 09/08/2018, 11:00am	API# (if applicable)

Unit Letter	Section	Township	Range	County
B	27	18S	28E	Eddy

Surface Owner: State Federal Tribal Private (Name)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 7	Volume Recovered (bbls) 5
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 63	Volume Recovered (bbls) 45
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:

3-inch check valve on flow line failed due to inner corrosion, resulting in a small pinhole on the bottom of the valve. The spill occurred early morning on 9/8/2018, and found when the lease operator made his site visit at 11:00am. The line was isolated and a vacuum truck was dispatched to recover all freestanding fluid. Delineation as conducted and submitted for analyticals. A backhoe removed all saturated soil and replaced with fresh soil.

