Submit 3 Copies To Appropriate District Office <u>District I</u>		State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004	
1625 N. French Dr., Hobbs, NA	M 88240		·	WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, N	NM 88210	OIL CONSERVA	TION DIVISION	30-015-33436	
District III		1220 South S	t. Francis Dr.	5. Indicate Type of Least STATE	se FEE
1000 Rio Brazos Rd., Aztec, NI District IV	M 87410	Santa Fe, 3	NM 87505	6. State Oil & Gas Leas	
1220 S. St. Francis Dr., Santa F 87505	e, NM			V5660	
SUND		S AND REPORTS ON V		7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM F DIFFERENT RESERVOIR. U	OR PROPOSALS USE "APPLICATIO	TO DRILL OR TO DEEPEN ON FOR PERMIT" (FORM C-	OR PLUG BACCENEL 101) FOR SUCH	PANDA BEAR	
PROPOSALS.)  1. Type of Well: Oil Well:	ell  Gas	s Well 🛛 Other	DEC - 6 2004	8. Well Number	1
2. Name of Operator OGRID Number					
3. Address of Operator	MURCHI	SON OIL & GAS, INC.		10. Pool name or Wildo	015363
3. Mudiciss of Operator	1100 MIR	A VISTA BLVD., PLA	NO, TX. 75093-4698	CROW FLATS M	
4. Well Location					
Unit Letter	<u>D</u> ::	1280 feet from the	NORTH line and	feet from the	WEST line
Section	2	Township 17	7-S Range 28-E	NMPM	County EDDY
	11		er DR, RKB, RT, GR, e	tc.)	
Pit or Below-grade Tank Appli	cation 🔲 or Clos	3678 GF ure □			
	o Groundwater_		fresh water well Di	istance from nearest surface water	
Pit Liner Thickness:	mil B	elow-Grade Tank: Volume	bbls; Co	onstruction Material	
12	Check Appr	onriate Box to India	ate Nature of Notice	e, Report or Other Data	
		^	4	•	
	OF INTE			BSEQUENT REPORT	
PERFORM REMEDIAL V		.UG AND ABANDON			RING CASING 🔲
TEMPORARILY ABANDO PULL OR ALTER CASIN	_	_	COMMENCE DI CASING/CEME	RILLING OPNS.⊠ PAND NT JOB ⊠	) А
FULL OR ALTER CASIN	G L WIC	DETIFIE COMPL [	_ CASING/CEIVIE	M JOB E	
OTHER:			OTHER:		
13. Describe proposed	d or completed	operations. (Clearly sta	te all pertinent details, a	and give pertinent dates, inch	ading estimated date
13. Describe proposed of starting any pro	d or completed oposed work).	operations. (Clearly sta SEE RULE 1103. For	te all pertinent details, a	and give pertinent dates, inch Attach wellbore diagram of p	ading estimated date proposed completion
13. Describe proposed of starting any proof or recompletion.	oposed work).	SEE RULE 1103. For	te all pertinent details, a Multiple Completions:	Attach wellbore diagram of p	proposed completion
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H	oposed work). IRS 11/7/04. (	SEE RULE 1103. For Contacted Phil Hawkins	te all pertinent details, a Multiple Completions:	and give pertinent dates, inche Attach wellbore diagram of p spud. Drill 17-1/2" hole to a	proposed completion
13. Describe proposed of starting any proof or recompletion.	oposed work). IRS 11/7/04. (	SEE RULE 1103. For Contacted Phil Hawkins ing as follows:	te all pertinent details, a Multiple Completions: with NMOCD prior to s	Attach wellbore diagram of popular properties and a prill 17-1/2" hole to a	proposed completion
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H	oposed work). IRS 11/7/04. (	SEE RULE 1103. For Contacted Phil Hawkins ing as follows:  1 Texas Patte	te all pertinent details, a Multiple Completions: with NMOCD prior to s	Attach wellbore diagram of p	proposed completion
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H	oposed work). IRS 11/7/04. (	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collai	te all pertinent details, a Multiple Completions: with NMOCD prior to s rn Shoe #/FT K-55 BT&C	Attach wellbore diagram of popud. Drill 17-1/2" hole to a	proposed completion
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H	oposed work). IRS 11/7/04. (	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collar 8 Jts 13-3/8" 68	te all pertinent details, a Multiple Completions: with NMOCD prior to some street of the some street with K-55 BT&C to some street with the some street with the some street of the some street with the some street with the some street with the some street of the some street with the	Attach wellbore diagram of popul. Drill 17-1/2" hole to a  1' 41' 1' 265'	proposed completion
13. Describe proposed of starting any proof or recompletion.  Spud well 1000 H 13-3/8" 68#/FT K	oposed work). IRS 11/7/04. ( -55 BT&C cas	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collar 8 Jts 13-3/8" 68 TOTAL	te all pertinent details, a Multiple Completions: with NMOCD prior to some street of the some street with K-55 BT&C to some street with the some street with the some street of the some street with the some street with the some street with the some street of the some street with the	Attach wellbore diagram of popud. Drill 17-1/2" hole to a	proposed completion
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K	oposed work).  IRS 11/7/04. ( -55 BT&C cas  noe Jt, 2 <sup>nd</sup> Jt, 4	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collar 8 Jts 13-3/8" 68 TOTAL	te all pertinent details, a Multiple Completions: with NMOCD prior to s rn Shoe #/FT K-55 BT&C r #/FT K-55 BT&C	Attach wellbore diagram of popul. Drill 17-1/2" hole to a  1' 41' 1' 265' 308'	proposed completion depth of 308'. Ran
13. Describe proposed of starting any proof or recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ Sh Cement with 100 to surface. Bump	oposed work).  IRS 11/7/04. (Complete St., 2 <sup>nd</sup> Jt., 4 <sup>th</sup> SXS Thixotropplug. Floats h	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Colla: 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas	te all pertinent details, a Multiple Completions:  with NMOCD prior to s  rn Shoe #/FT K-55 BT&C  #/FT K-55 BT&C  XS Premium Cmt + 2%  mperature survey. Ran	Attach wellbore diagram of popul. Drill 17-1/2" hole to a  1' 41' 1' 265' 308'  CaCl. No returns while cent 1" pipe to 85' and tagged. C	depth of 308'. Ran nenting. No cement
13. Describe proposed of starting any proof or recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX	oposed work).  IRS 11/7/04. (Complete St., 2 <sup>nd</sup> Jt., 4' SXS Thixotropolog. Floats hereign Seremium + 3	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Colla: 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Te: 19% CaCl. Circulate 5 Sizelds.	with NMOCD prior to s multiple Completions: with NMOCD prior to s m Shoe #/FT K-55 BT&C  #/FT K-55 BT&C  XS Premium Cmt + 2% mperature survey. Ran XS to surface. Wait 15 1	Attach wellbore diagram of property of pro	depth of 308'. Ran  menting. No cement Cement through 1"  c 14". Cut off 13-
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3 3/8" casing and in	oposed work).  IRS 11/7/04. (c55 BT&C cas  noe Jt, 2 <sup>nd</sup> Jt, 4' SXS Thixotroplug. Floats h S Premium + 3 astall wellhead.	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Colla: 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 1 Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 5 Sizeld.	with NMOCD prior to s  multiple Completions:  with NMOCD prior to s  m Shoe  #/FT K-55 BT&C   XS Premium Cmt + 2%  mperature survey. Ran  XS to surface. Wait 15 m  PSI for 15 minutes. Ni	Attach wellbore diagram of property of part of	depth of 308'. Ran depth of 308'
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3 3/8" casing and in	oposed work).  IRS 11/7/04. (c55 BT&C cas  noe Jt, 2 <sup>nd</sup> Jt, 4' SXS Thixotroplug. Floats h S Premium + 3 astall wellhead.	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Colla: 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 1 Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 5 Sizeld.	with NMOCD prior to s  multiple Completions:  with NMOCD prior to s  m Shoe  #/FT K-55 BT&C   XS Premium Cmt + 2%  mperature survey. Ran  XS to surface. Wait 15 m  PSI for 15 minutes. Ni	Attach wellbore diagram of property of pro	depth of 308'. Ran depth of 308'
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3 3/8" casing and in	oposed work).  IRS 11/7/04. (c55 BT&C cas  noe Jt, 2 <sup>nd</sup> Jt, 4' SXS Thixotroplug. Floats h S Premium + 3 astall wellhead.	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Colla: 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 1 Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 5 Sizeld.	with NMOCD prior to s  multiple Completions:  with NMOCD prior to s  m Shoe  #/FT K-55 BT&C   XS Premium Cmt + 2%  mperature survey. Ran  XS to surface. Wait 15 m  PSI for 15 minutes. Ni	Attach wellbore diagram of property of part of	depth of 308'. Ran depth of 308'
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3 3/8" casing and in	oposed work).  IRS 11/7/04. (c55 BT&C cas  noe Jt, 2 <sup>nd</sup> Jt, 4' SXS Thixotroplug. Floats h S Premium + 3 astall wellhead.	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Colla: 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 1 Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 5 Sizeld.	with NMOCD prior to s  multiple Completions:  with NMOCD prior to s  m Shoe  #/FT K-55 BT&C   XS Premium Cmt + 2%  mperature survey. Ran  XS to surface. Wait 15 m  PSI for 15 minutes. Ni	Attach wellbore diagram of property of part of	depth of 308'. Ran depth of 308'
13. Describe proposed of starting any proof or recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3 3/8" casing and in 600 PSI. Wait on	ince Jt, 2 <sup>nd</sup> Jt, 4' SXS Thixotroplug. Floats h S Premium + 3 stall wellhead.	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collar 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Si held. TOC @ 78' by Te 1% CaCl. Circulate 5 Si Test wellhead to 1000 hof 21 hrs. Drill cemen	with NMOCD prior to some shoe #/FT K-55 BT&C  XS Premium Cmt + 2% mperature survey. Ran : XS to surface. Wait 15 in PSI for 15 minutes. Nit t float collar and shoe. I	Attach wellbore diagram of property of part of	nenting. No cement depth of 308'. Ran depth of 308'. Ran depth of 308'. Ran depth of 308'. Ran depth of 308'. Ran dement through 1" k 14". Cut off 13- PSI. Test casing to ith 12-1/4" bit.
13. Describe proposed of starting any proof or recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3/8" casing and in 600 PSI. Wait on	noe Jt, 2 <sup>nd</sup> Jt, 4' SXS Thixotroplug. Floats h S Premium + 3 stall wellhead. cement a total	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collar 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Si held. TOC @ 78' by Te 19% CaCl. Circulate 5 Si Test wellhead to 1000 1 of 21 hrs. Drill cemen	with NMOCD prior to s multiple Completions: with NMOCD prior to s m Shoe #/FT K-55 BT&C  #/FT K-55 BT&C  XS Premium Cmt + 2% mperature survey. Ran XS to surface. Wait 15 n PSI for 15 minutes. Ni t float collar and shoe. I	Attach wellbore diagram of property of part of	depth of 308'. Randenting. No cement dement through 1" to 14". Cut off 13-PSI. Test casing to ith 12-1/4" bit.
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3/8" casing and in 600 PSI. Wait on	noe Jt, 2 <sup>nd</sup> Jt, 4' SXS Thixotroplug. Floats h S Premium + 3 stall wellhead. cement a total	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collar 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Si held. TOC @ 78' by Te 19% CaCl. Circulate 5 Si Test wellhead to 1000 1 of 21 hrs. Drill cemen	with NMOCD prior to s multiple Completions: with NMOCD prior to s mr Shoe #/FT K-55 BT&C  #/FT K-55 BT&C  XS Premium Cmt + 2% mperature survey. Ran XS to surface. Wait 15 n PSI for 15 minutes. Ni t float collar and shoe. I	Attach wellbore diagram of property of part of	depth of 308'. Randenting. No cement dement through 1" to 14". Cut off 13-PSI. Test casing to ith 12-1/4" bit.
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3/8" casing and in 600 PSI. Wait on	ince Jt, 2 <sup>nd</sup> Jt, 4 SXS Thixotropplug. Floats hes Premium + 3 install wellhead cement a total	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Collar 8 Jts 13-3/8" 68 TOTAL th Jt and 6th Jt. pic followed with 340 Steld. TOC @ 78' by Texas Patte 10% CaCl. Circulate 5 St. Test wellhead to 1000 of 21 hrs. Drill cemen e is true and complete to according to NMOCD guidely.  GHERTY E-1	with NMOCD prior to s  multiple Completions:  with NMOCD prior to s  m Shoe  #/FT K-55 BT&C   XS Premium Cmt + 2%  mperature survey. Ran  XS to surface. Wait 15 n  PSI for 15 minutes. Ni  t float collar and shoe. I  the best of my knowled  ines \( \subseteq \), a general permit \( \subseteq \)  the best of my knowled  ines \( \subseteq \), a general permit \( \subseteq \)  LE \( \subseteq \subseteq \)	Attach wellbore diagram of property of part of	depth of 308'. Randenting. No cement dement through 1" to 14". Cut off 13-PSI. Test casing to ith 12-1/4" bit.
13. Describe proposed of starting any proor recompletion.  Spud well 1000 H 13-3/8" 68#/FT K  Centralizers @ St Cement with 100 to surface. Bump pipe with 100 SX3 3/8" casing and in 600 PSI. Wait on	ince Jt, 2 <sup>nd</sup> Jt, 4 SXS Thixotropplug. Floats hes Premium + 3 install wellhead cement a total	Contacted Phil Hawkins ing as follows:  1 Texas Patte 1 Jt 13-3/8" 68 1 Float Colla: 8 Jts 13-3/8" 68 TOTAL  th Jt and 6th Jt. pic followed with 340 Sizeld. TOC @ 78' by Texas Patte 5 Sizeld. Toc with 340 Sizeld. Test wellhead to 1000 of 21 hrs. Drill cement according to NMOCD guidely.	with NMOCD prior to s  multiple Completions:  with NMOCD prior to s  m Shoe  #/FT K-55 BT&C   XS Premium Cmt + 2%  mperature survey. Ran  XS to surface. Wait 15 n  PSI for 15 minutes. Ni  t float collar and shoe. I  the best of my knowled  ines \( \subseteq \), a general permit \( \subseteq \)  the best of my knowled  ines \( \subseteq \), a general permit \( \subseteq \)  LE \( \subseteq \subseteq \)	Attach wellbore diagram of property of part of	depth of 308'. Randenting. No cement through 1" to 14". Cut off 13-PSI. Test casing to ith 12-1/4" bit.  that any pit or below-approved plan

Conditions of Approval (if any):