				act	- Artesia
Form 3160-5 , (August 2007)	UNITED ST DEPARTMENT OF T		-	F	ORM APPROVED MB NO 1004-0135
	BUREAU OF LAND N			Ex 5. Lease Serial	kpires: July 31, 2010
	NDRY NOTICES AND F			NMLC056	
Do not abandon	use this form for propos and well. Use form 3160-	als to drill or to re 3 (APD) for such	-enter an proposals.	6. If Indian, All	ottee or Tribe Name
. SUBMIT	IN TRIPLICATE - Other in	nstructions on rev	verse side.	7. If Unit or CA	/Agreement, Name and/or No.
1. Type of Well Gas Well	Other			8. Well Name a KENNEDY	nd No A JOHNSON 1
2. Name of Operator EXXONMOBIL CORPO	Cor	ntact. JACQUELIN ne.p.davis@exxonmo		9. API Well No 30-015-05	
3a. Address HOUSTON, TX 77210	0-4358	3b Phone No Ph: 281-65 Fx: 281-65		e) 10 Field and P GRAYBUF	ool, or Exploratory RG
	e, Sec., T., R., M., or Survey Des		1 1010	11 County or I	Parish, and State
Sec 35 T16S R31E SE	NW 1980FNL 1980FWL	-		EDDY CO	UNTY, NM
	. F	Υ.			
12 CHEC				NOTICE, REPORT, OR O	
			E NATURE OF	NOTICE, REPORT, OR O	
TYPE OF SUBMISSIO	PN .		TYPE O	F ACTION	
□ Notice of Intent			epen	Production (Start/Resur	ne) U Water Shut-Off
8			cture Treat	Reclamation	□ Well Integrity
Subsequent Report		_	w Construction	Recomplete	□ ^{Other}
□ Final Abandonment N			g and Abandon	Temporarily Abandon	
	Convert to Inj	-	g Back	☐ Water Disposal ng date of any proposed work and	
determined that the site is re	being submitted to report c		-	iding reclamation, have been com nnedy Johnson A	
Attachment: Regulatory Detail Rep Wellbore Sketch	ort	RECE	IVED	Accepted as to plug Liability under bon Surface restoration	ging of the well bore. d is retained until is completed.
A) 8/4/20 #		AUG	4 2011	Surface restoration	
\$ \$1,7/0°				REC	LAMATION
Accepted for r NMOCD			ARTESIA	DUE	12-10-11
14. Thereby certify that the for	Electronic Submis	sion #113160 verific ONMOBIL CORPOR	d by the BLM We	ell Information System	
Name (Printed/Typed) JA	Committed to AFMSS f	or processing by Kl	RT SIMMONS or	07/20/2011 (11KMS1072S) ORT STAFF TECHNICAL A	SST
Signature (El	ectronic Submission)		Date 07/18/2		
	· · · · · · · · · · · · · · · · · · ·	CE FOR FEDER			
	DTEN		JAMES A	AMOS	
Approved By			TitleSUPERV	ISOR EPS	Date 07/25/2011
Conditions of approval, if any, a certify that the applicant holds le which would entitle the applicant	gal or equitable title to those right		Office Carlsba	, ad	
Title 18 USC Section 1001 and States any false, fictitious or fr	d Title 43 U S.C. Section 1212, r audulent statements or represent	nake it a crime for any ations as to any matter	person knowingly ar within its jurisdiction	nd willfully to make to any depart n.	ment or agency of the United
** BI	M REVISED ** BLM RF	VISED ** BLM R	EVISED ** BI	M REVISED ** BLM RE	VISED **
52				PA 0408/24	

PA 04/08/2011

•

ExxonMobil Production Company

Printed: 7/14/2011 Page #1 of 5 Page(s)

Well Hea																		
Lease KENNEDY-J	OHNSFE	DA		Count Eddy	y/Distric	*		Territor New Me		<u></u>			face Loca C650B3B1		100144F4A	Critical Lease/	Well	
Wellbor	e <i>Data</i> ction		(ameter (in)		Actual To	p MD (ftKB)		ottom M	D (ftKB)		I Top (T)	/D) (ftKB)		ct Btm (TVD) (1	ek(P)	Act End	ЭнДта
						Actual To				4,259.0	AL	1000						
Deviatio	n Sur		S: cription		· ·		Definitive?	L Cupu			· · ·			· ·				
		Dest	cripaon				Jenniuve?	Surve	ey Dt/Tm						mmenis			
Casing					. 1	1												
<des>@s</des>	аертпр	un?	Ргор	r∠ <prop< td=""><td></td><td>un> Bottom ML</td><td>) (ftKB)</td><td></td><td></td><td><u></u></td><td>t Depti</td><td>h TVD (ft)</td><td><u>ка</u>за. КВ)</td><td>माएउसाल २ </td><td>Run Date/Time</td><td></td><td></td><td></td></prop<>		un> Bottom ML) (ftKB)			<u></u>	t Depti	h TVD (ft)	<u>ка</u> за. КВ)	माएउसाल २	Run Date/Time			
Desc	ription		N	Jominal OD		Nom	inal Weight	(lb/ft)		Grade		ten	igth (ft)	L	Top MD (ft)	(8)	Bottom M	
					<u>, , , , , , , , , , , , , , , , , , , </u>								igui (iy		100 1100 (10		Cottoni ini	
Cement				Shizze							uliuk						्र स्थायम् व	
Description		Earte			ent Job	Туре	String			Start Date	πε	End Date/	Time Eva	luation M	ethod Eva	aluation		
Product	ion Tu	ıbin	g Sti	rings		3						·····;···;						
<des> set Tubing Desci</des>		thbi	m>fit	<b on="" td="" ≤0<=""><td>ttimpel</td><td>2</td><td></td><td>Bottom or</td><td>ALL Set Der</td><td></td><td></td><td></td><td></td><td>Dete Ma</td><td>· · · · · · · · · · · · · · · · · · ·</td><td>IIII</td><td></td><td></td>	ttimpel	2		Bottom or	ALL Set Der					Dete Ma	· · · · · · · · · · · · · · · · · · ·	IIII		
		-					IVIE doui eu		Sei Dep				ru	Date/Tin				
Item i	Des		OD (i	in)	Wt (16/	ft)	Grade	Mak	e	Model	Та	op (fIKB)	Btm	(ftKB)	Top (TVD) (ftKB)	Btm (T) (ftKB		Len (ft)
Perforat	ions	1 2 4.	الله الم															1,15
				<u> </u>			Btm			1] _]						`·
Interval Type	Date/T	ime		ṫKB) Btm (ftKB)	fop (TVD) (ftKB)	(TVD) (ftKB)	Shot Dens (shots/ft)				ın Size (in)	Phasing (°)		Com	Cur Stat Date	Currer	at Status
Open Hole		6463	3,44	43.9 4,2	258.9 12.0	12913 1 -1-1-				Stati Korantiari	-	alementa		1				
Open Hole			3,91		58.9	255511161	a pieże negłą		Tereni			r Hili		5914900 3	FERE			
Stimulat		2 01	ther	Treatm	ents													
Туре	U 11072	Div	ersion I	Method	! ISP	(psi)	Pi	rop in Forr	noose. 1 (Ib)	Comment				BERGE AND			Date/Time	
		<u> </u>		·····										· · · · · · · · · · · · · · · · · · ·				
Flui	id Name				Fluid		Der	ns Fluid (°/	API)					·····	Com		·	
					·		L			_		<u> </u>						
Stg #	Stag	е Тур		Top (ftKB)	B	m (ftKB)	Top (TVI (ftKB)		n (TVD) ftKB)	Avg Casir Pres (psi		Avg Tubir Pres (psi		reak (psi)	Avg Pump Rate (gpm)		Com	
				·····		1 (13(0)	(<u> </u>			1100 (poi		eak (psi)				
Other In Des			e/Time		(in)	Top	(ftKB)	Btm (ftK		fop (TVD) (ftK		m /TVD) /	ffKB\	Ass'td Str	ing instandarstan Ministrations All	<u></u>	nents	
					<u>()</u>			Sun (un						13310 50	8	Com	nents	
Job Plug and A	bando		· · · · ·	ly 5/18/	2011 0	0.00 - <	lttmend>	· · · · ·		р -			· · · · · · · · · · · · · · · · · · ·					<u> </u>
Job Category Permanent			Pri	imary Job ug and Aba	Гуре		Job Subca			Job Start D)ate/Tir 5/18/20		Job	End Date	/Time	Job Sum	mary	
Daily Op			2. 			one only				Tary	or rolZl						3 2	
5/18/2011 Management			2011	00:00														
RWI moved in			id bega	in building	location							. .						
shutdown for	night.						<u></u>		. Co	mmenis								
RWI building i	location	•																
				····												·····]

ExxonMobil Production Company

Printed: 7/14/2011 Page #2 of 5 Page(s)

ExxonMobil Production Company

Printed: 7/14/2011 Page #3 of 5 Page(s)

Break circulation, pumped 25 SXS	Comments
POOH, lay down 6 jts tubing, stood	I back 10 stands.
Reverse out 15 bls.	
Walting on cement.	
RIH and tagged cement at 3371'. (Contacted Richard with BLM for status update.
Break circulation, pumped 40 bls br	nne water.
Pumped 25 SXS cement at 3371', o	
POOH, layed down 6 jts, stood bac	x 10 stands.
Reverse out 15 bis brine, secured w	well for night.
Crew travel.	
Shut down for night.	
5/26/2011-00-00 - 5/27/2011	
Management Summary	
Tag TOC @3242', unable to load h	ole. pump 75 SXS cmt, tag @ 2980', pump 35 SXS cmt, WOC.
Shut down for night.	Comments
÷	ICA serves you tested LIOC monitors
	JSA, source gas tested H2S monitors.
Opened well with 0 psi shut in. TIH	
-	t pressure up. Contact Richard with BLM. He approved pumping 75 SXS cmt at 3242'.
Break circulation, pumped 75 SXS	
POOH, layed down 13 its of tubing,	, stood back10 stands
Reverse out 15 bls brine water.	
Waited on cement.	
TIH, tagged TOC at 2980'.	· · · · · · · · · · · · · · · · · · ·
	sure up. Pumped 10 bls brine at 2 bpm / 100 psi. Contact Richard with BLM for status update. Received approval to pump additional 35 SXS cmt.
Pumped 35 SXS cmt at 2980', disp	
POOH, layed down 6 its of tubing, s	
Reverse out 15 bls brine water., se	cured well for night.
Crew travel.	
Shut down for night.	
5/27/2011 00:00 5/28/2011	00:00
Management Summary	
ray 100 @ 2130, 100K 0 bis 10 mm	hole, was unable to pressure up, circulated salt gell, circulated 35 SXS CMTfrom 2000'. Comments
Shut down for night.	COMINICITIS
•	JSA, source gas tested H2S monitors.
Opened well with 0 psi shut in. TIH	
Load casing and tested, would not i	
Mix 25 SXS salt gell with 65 bls brin	
POOH, layed down 24 jts of 2-3/8" I	
Transfered cement.	inoud.
Lunch break for crew, reviewed BJS	84
Break circulation, pumped 35 SXS in POOH, lowed down 6 its and stood by	
	back 10 stands of 2-3/8" tubing. Reverse out 10 bls of brine. Secured well for night.
Crew travel.	
Crew travel. Shut down for night.	
Crew trave). Shut down for night. 5/31/2011-00:00-6/1/2011-01	
Crew trave). Shut down for night. 5/33/2011-00-00-6/1/2011-0. Management Summary	
Crew travel. Shut down for night. 5/3372011500500 - 6/1/201150. Management Summary Tag TOC @ 1815', Load & test, woi	uld not psi up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug, No tag until 1815. Attempt to circ & pump 70
Crew travel. Shut down for night. 5/33/2011-00-00-0/1/2011-0. Management Summary Tag TOC @ 1815', Load & test, woi	uld not psi up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag until 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down.
Crew travel. Shut down for night. 5/33/2011-00:00-6/4/2011-0 Management Summary Tag TOC @ 1815', Load & test, wou sks cement at 1815, unable to circ,	uld not psi up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug, No tag until 1815. Attempt to circ & pump 70
Crew travel. Shut down for night. 5/37/2011-00:00 - 6/1/2011-0 Management Summary Tag TOC @ 1815', Load & test, woi sks cement at 1815, unable to circ, sdon	uld not psi'up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag untill 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down. Comments
Crew travel. Shut down for night. 5/37/2011 00:00 - 6/1/2011 0 Management Summary Tag TOC @ 1815', Load & test, woi sks cement at 1815, unable to circ, sdon Travel to loc Rbjsa test H2s Monitor	uld not psi up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag untill 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down. Comments
Crew travel. Shut down for night. 5/37/2013 00:00 - 6/1/2011 o. Management Summary Tag TOC @ 1815', Load & test, woi sks cement at 1815, unable to circ, sdon Travel to loc Rbjsa test H2s Monitor Check psi 0 open well, Tih taged pl	uld not psi'up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag untill 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down. Comments
sks cement at 1815, unable to circ, sdon Travel to loc Rbjsa test H2s Monitor Check psi 0 open well, <u>Tih taged pl</u> Toh id 26 jts tbg.	uld not psi'up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag untill 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down. Comments r. lug at 1815, Load& test, would not psi up. Contact Richard with BLM.
Crew travel. Shut down for night. 5/31/2013_00:00 - 6/1/2011 0. Management Summary Tag TOC @ 1815', Load & test, wou sks cement at 1815, unable to circ, sdon Travel to loc Rbjsa test H2s Monitor Check psi 0 open well, Tin taged pl Toh Id 26 jts tbg. Break circ, pumped 35 sks cement	uld not psi'up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag untill 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down. Comments r. lug at 1815, Load& test, would not psi up. Contact Richard with BLM.
Crew travel. Shut down for night. 5/31/2014_00/200_6/1/2014_0/ Management Summary Tag TOC @ 1815', Load & test, wou sks cement at 1815, unable to circ, sdon Travel to loc Rbjsa test H2s Monitor Check psi 0 open well, Tih taged pl Toh Id 26 jts tbg. Break circ, pumped 35 sks cement Toh Id 7 jts tbg, std back 11 stds.	uld not psi'up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag untill 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down. Comments r. lug at 1815, Load& test, would not psi up. Contact Richard with BLM.
Crew travel. Shut down for night. <u>5/37/2011_00:00</u> _6/1/2011_0. Management Summary Tag TOC @ 1815', Load & test, woi sks cement at 1815, unable to circ, sdon Travel to loc Rbjsa test H2s Monitor Check psi 0 open well, Tih taged pl	uld not psi'up. Contact Richard with BLM. Break circ, pumped 35 sks cement at 961 disp to 761. Tih taged plug ,No tag untill 1815. Attempt to circ & pump 70 due to cement bridge Toh std back tbg, close well shut down. Comments r. lug at 1815, Load& test, would not psi up. Contact Richard with BLM.

ExxonMobil Production Company

Printed: 7/14/2011 Page #4 of 5 Page(s)

Comments
Attempt to circ & pump 70 sks cement at 1815, unable to circ, due to cement bridge.
Toh std back tbg, close well shut down. Crew travel
sdon
5772014-00-00-56722014-00-00
Management Summary
Pick up 43/4 bit tih taged at 790, rotate down with to 830. Circ 30 bbls brine water. Rotate down with tongs to 850. Baker Cil Tool does not have a power swivel available. Toh std back tbg, close
well.
Comments
sdon Travel to los Dhino tot h/2
Travel to loc Rbjsa test H2s monitor.
Check psi 0 open well. Pickup 43/4 bit tih taged at 790, rotate down withto 830. Contact Richard with BLM
Circ 30 bbls brine water.
Rotate down with tongs to 850.
Wait on orders, Toh std back tbg, close well. Lunch break
Maintain equipment, shut down. Crew travel.
sdon
6/2/2011/00:006/3/2011/00:00
Management Summary Check pig 0 coop woll. The back pig we available of a summary will be a summary with the second state of th
Check psi 0 open well. Tih to 830 ft. Tie back, rig up snub line. Wait on power swivel. Rig up power swivel Break arc, drill from 850 to 960. Circ 40 bbls BW. Lay down power swivel, remove striper rubber. Contact Richard with BLM Tih to 1815 taged plug, toh std back 27 std, ld 5 jts tbg. Load out power swivel, close well, shut
down.
Comments
sdon
Travel to loc Rbjsa Test H2s monitor. Check psi 0 open well.
Tih to 830 ft.
Tie back , ríg up snub line.
Wait on power swivel.
Rig up power swivel
Break circ, drill from 850 to 960.
Circ 40 bbls BW.
Lay down power swivel, remove striper rubber. Contact Richard with BLM
The to 1815 taged plug, toh std back 27 std, id 5 its tbg.
Load out power swivel, close well, shut down. Crew travel
sdon
6/3/2011 00:006/4/2011 00:00
Wanagement Summary
RIH to 1815, circulate salt gel, circulate 70 sacks of cement, displace to 1415, WOC, RIH tag at 1460, break circulation, circulate 50 sacks of cement at 961, displace to 661, WOC
Comments
Shut down for night
Travel to location, review JSA, test H2S monitor, open well with 0 shut-in pressure
Tie back, RIH to 1815, mix 20 sacks salt gel with 50 bbls BW
Pumped 70 sacks of cement at 1815, displaced to 1415, TOH ld 11 jts tbg, std back 22 stds
Waiting on Cement
TIH, tagged plug at 1460, and contact Richard with BLM
POOH, laid down 15 jts tbg
Circulate 50 sacks of cement at 961, displaced to 661
POOH, laid down 9 jts tbg, stood back 10 stds, secured well for night. Crew Travel
Shut down for night.
nangement Summary
Tih taged plug at 590'. Pumped 70 sks cement at 565' disp to 165'. WOC. Tih taged plug at 590'. Pumped 45 sks cement at 165 disp to surface. WOC
Shut Down For The Night
-
Travel to well site.
Check psi 0 open well.
Tih taged plug at 590.
Load & test, would not psi up.
Contact Richard with BLM

ExxonMobil Production Company

Printed: 7/14/2011 Page #5 of 5 Page(s) -

Pumped 70 sks cement at 565 disp to 165. Toh ld 17 jts tbg. WOC Tih taged plug at 590. Contact Richard with BLM Pumped 45 sks cement at 165 disp to surface. Toh ld 5 jts tbg, wash out bop & tbg, close well ,shut down. Crew travel Shut Down For The Night <u>677/2011 00:00 - 6/8/2011 00:00</u> Management Summary Tih taged plug at 40 ft toh ld tbg. Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. T <u>ih to 40 ft, pumped 20 sks cement</u> to surface, ld tbg, top oft well.
WOC Tin taged plug at 590. Contact Richard with BLM Pumped 45 sks cement at 165 disp to surface. Toh ld 5 jts tbg, wash out bop & tbg, close well ,shut down. Crew travel Shut Down For The Night 6/7/2011 00:00 - 6/8/2011 00:00 Management Summary Tin taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. T <u>ih to 40 ft, pumped 20 sks cement</u>
Tih taged plug at 590. Contact Richard with BLM Pumped 45 sks cement at 165 disp to surface. Toh ld 5 jts tbg, wash out bop & tbg, close well ,shut down. Crew travel Shut Down For The Night 6/7/2011 00:00 - 6/8/2011 00:00 Management Summary Tih taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. T <u>ih to 40 ft, pumped 20</u> sks cement
Contact Richard with BLM Pumped 45 sks cement at 165 disp to surface. Toh ld 5 jts tbg, wash out bop & tbg, close well ,shut down. Crew travel Shut Down For The Night 6/7/2011 00:00 - 6/8/2011 00:00 Management Summary Tih taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. T <u>ih to 40 ft, pumped 20</u> sks cement
Pumped 45 sks cement at 165 disp to surface. Toh ld 5 jts tog, wash out bop & tog, close well ,shut down. Crew travel Shut Down For The Night <u>6/7/2011 00:00 - 6/8/2011 00:00</u> Management Summary Tih taged plug at 40 ft toh ld tog . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. T <u>ih to 40 ft, pumped 20</u> sks cement
Toh ld 5 jts tbg, wash out bop & tbg, close well ,shut down. Crew travel Shut Down For The Night 6/7/2011 00:00 - 6/8/2011 00:00 Management Summary Tih taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. T <u>ih to 40 ft, pumped 20</u> sks cement
Crew travel Shut Down For The Night 6/7/2011 00:00 - 6/8/2011 00:00 Management Summary Tih taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. Tih to 40 ft, pumped 20 sks cement
Shut Down For The Night 6/7/2011 00:00 - 6/8/2011 00:00 Management Summary Tih taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. Tih to 40 ft, pumped 20 sks cement
6/7/2011 00:00 - 6/8/2011 00:00 Management Summary Tin taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, ld cutter. ND bop. Pull csg stub. Tih to 40 ft, pumped 20 sks cement
Management Summary Tih taged plug at 40 ft toh ld tbg . Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. Tih to 40 ft, pumped 20 sks cement
Tin taged plug at 40 ft toh ld tbg. Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. Tin to 40 ft, pumped 20 sks cement
Tin taged plug at 40 ft toh ld tbg. Load well and check for bubbles. Wait on csg cutter. Pick up csg cutter, cut 7 inch csg, td cutter. ND bop. Pull csg stub. Tin to 40 ft, pumped 20 sks cement to surface, td tbg, top off well.
Comments
Shut Down For The Night
Drove crew to location. HSM - Review BJSA. Check H2S monitors.
Check psi D open well.
Tih laged plug at 40 ft toh ld tbg .
Load well psi test, psi up to 500 bleed down slowly, check for bubbles, no bubbles.
Wait on csg cutter. Contact Richard with BLM
Pick up csg cutter, cut 7 inch csg, ld cutter.
Rig down tbg tong, raise floor.
ND bop.
Pull csg stub.
Tih to 40 ft, pumped 20 sks cement to surface, ld tbg, top off well.
Wash up equip & tbg, shut down.
Crew travel
Shut down for the night
6/17/2011 00:00 - 6/18/2011 00:00
Management Summary
Dig up anchors, backfill and dress location

ExconMobil

WELL SKETCH - WTX AREA

WELL/LEASE: Kennedy Johnson A 3

FIELD: Grayburg Jackson

COUNTY/STATE: Eddy, New Mexico

ELEVATIONS:

KB Elevation: 4041' MD

LOCATION:

1980' FSL & 660' FWL Unit: L Section: 35 Township: 16S Range: 31 Lease Serial #: LC 056302A

> Surface Casing: 12 ½"(0' - 56' MD) 14" hole ? ETOC @ Surface

Production Casing: 7" (0'-3444' MD) ETOC @ Surface 8 ¾" hole ?

Open Hole: 3444' - 4259' MD



 CURRENT COMPLETION DATE:
 PA – 6/30/2011

 PREPARED BY/DATE:
 JA Allen 7/2011

 API NUMBER:
 3001505010

Current