							OCD.	Aites	i a		
Form 3160-5 (August 2007)								FORM APPROVED OMB NO 1004-0135 Expires: July 31, 2010			
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						5. Lease Serial No NMLC056302A				
D ab							6 If Indian, Allottee or Tribe Name				
SL	BMIT IN TRIF	PLICATE - Other ins	tructions	on reverse sid	le.		7. If Unit or CA/Agre	ement, Name	e and/or No.		
1. Type of Well	as Well 🔲 Oth	er					8. Well Name and No. KENNEDY JOHN				
2 Name of Operator EXXONMOBIL C	ORPORATIO	Conta N E-Mail: jackie.		UELINE DAVIS	3		9. API Well No. 30-015-05008-0				
3a. Address HOUSTON, TX	77210-4358		I Ph:	Phone No (include 281-654-1913 281-654-1940	area code)		10. Field and Pool, or GRAYBURG	Exploratory			
4. Location of Well	4. Location of Well (Footage, Sec., T, R., M, or Survey Description)						11 County or Parish, and State				
Sec 35 T16S R3	1E SENW 19	80FNL 1980FWL					EDDY COUNT	Y, NM			
12. 0	CHECK APPR	ROPRIATE BOX(ES	) TO INE	DICATE NATU	RE OF N	IOTICE, RE	PORT, OR OTHE	R DATA			
TYPE OF SUBN	AISSION			,	TYPE OF	ACTION					
□ Notice of Inten	, t	□ <sup>Acidize</sup>		Deepen		Producti	on (Start/Resume)	U Wate	r Shut-Off		
🗖 Subsequent Re		□ Alter Casing		Fracture Trea					Integrity		
-				■ New Construction ■ Plug and Abandon ■				□ <sup>Othe</sup>	□ <sup>Other</sup>		
Final Abandon		Change Plans Convert to Injec	vert to Injection		g Back		rily Abandon isposal				
If the proposal is to Attach the Bond un following completio testing has been con determined that the	deepen directiona der which the wor n of the involved ipleted Final Ab site is ready for fi	eration (clearly state all pe ally or recomplete horizon ck will be performed or pri operations. If the operati andonment Notices shall inal inspection ) ubmitted to report dat	tally, give si ovide the Bo on results in be filed only	ubsurface locations and No. on file with a multiple complet after all requireme	and measur BLM/BIA ion or reco nts, include	red and true ve Required sub mpletion in a n ing reclamatior	rtical depths of all perti sequent reports shall b lew interval, a Form 310 i, have been completed on A	nent markers e filed withii 60-4 shall be	s and zones. 1 30 days 5 filed once		
Attachment: Regulatory Deta Wellbore Sketch	il Report	Γ		EIVED 4 2011			RECLAMA	TION			
A 8/4/2011	epted for r	ecord		D ARTESIA		Liabil	ted as to plugging ity under bond is ro restoration is co	etained un	ll bore. til		
14. Thereby certify that		true and correct.		·····	·		`	mpietea.			
	Cor	Electronic Submissi For EXXO nmitted to AFMSS for	NMOBIL C	orporation, s	sent to the	e Carlsbad	5°				
Name (Printed/Type				Title			ECHNICAL ASST		r.		
Signature	(Electronic S	Submission)		Date	07/18/20	011					
		THIS SPACE	E FOR FI	EDERAL OR S	STATE (	OFFICE US	SE				
Approved By AC		ED		JA 	MES A A	AMOS SOR EPS		Dat	e 07/25/2011		
	holds legal or equ	d. Approval of this notice utable title to those rights act operations thereon		ct lease	Carlsbad						
Title 18 U.S.C. Section 1 States any false, fictitio	001 and Title 43 ous or fraudulent	U.S.C. Section 1212, mal statements or representation	ke it a crime ons as to any	for any person kno matter within its ju	wingly and urisdiction.	willfully to ma	ake to any department of	or agency of	the United		

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

## ЕxconMobil

### WELL SKETCH - WTX AREA

WELL/LEASE: Kennedy Johnson A 1

14" hole ?

FIELD: Grayburg Jackson

COUNTY/STATE: Eddy, New Mexico

#### **ELEVATIONS:**

KB Elevation: 4068' MD

#### LOCATION:

1980' FNL & 1980' FWL Unit: F Section: 35 Township: 16S Range: 31E Lease Serial #: LC 056302A







#### Current

PREPARED BY/DATE:

CURRENT COMPLETION DATE: PA - 7/11/2011

JA Allen 7/2011

3001505008

#### Regulatory Detail Report Well: Kennedy-Johnsfed A - 1

## ExxonMobil Production Company

Printed: 7/15/2011 Page #1 of 4 Page(s)

Field: GRAYBURG JACKSON

•

Well He Keimedic																mey-r
Lease KENNEDY-J		) A	4	County/Di: Cddy	strict			ory/State Nexico		-		ation D4344E044		Critical Lease/Well 144F4A		
Wellbor Se	e Data		Diamete	Diameter (in) Actual Top MD (ftKB)		B)	Bottom MD (ftKB) Ac		Act Top (	t Top (TVD) (ftKB)		t Btm (TVD) (	ftKB)	Act End Dt/Tm		
							<u></u>		3,871.0		<u> </u>		<u> </u>			
Deviatio		Descript	tion			Definitive?	Surv	/ey Dt/Tm			<u> </u>	Cor	nments			
Casing	Strings		-	· . •												
<b>≤des≥@</b> Description	sdepthbt	m≥, Pi	<i>ор7 &lt;</i> р	ropose		MD (ftKB)				Depth TVD (	fiKB)	<u>- 1848 - 5</u> [R	un Date/Time			
Desc	ription		Nomina	al OD (in)	) N	ominal Weig	ht (Ib/ft)		Grade	·	ength (ft)		Top MD (ft)	tKB) Bottom MD (ftKB)		(ftKB)
Cement	1.		-	N .1						) 						
< <b>des&gt;, <c< b=""> Description</c<></b>	ementlyj	⊳ <u>,</u> ≪di		≥ Cement J	lob Type	String			Start Date/	Ti End Dat	e/Time Ev	aluation Me	thod Eva	aluation		
Product					in Sile											
Tubing Desci						Measure	ed Bottom o	r Set Dept	h (ftKB)		R	in Date/Tim	9		<u> </u>	
ltem l	Des	0	D (in)	Wt (	lb/ft) _	Grade	Mal	œ	Model	Top (ftKB	) Btn	n (ftKB)	Top (TVD) (ftKB)	Btm (T (ftKB		en (ft)
Perforat	ions		, i											· · · · · · · ·		44 4 4 1
Interval Type Open Hole	Date/Tin		o (ftKB) E 8,476.0	3tm (ftKB) 3,871.1	Top (TVI (ftKB)	D) (TVD) (ftKB)	Shot Den (shots/ft)			Gun Size (in)	Phasing (°)	(	Com	Cur Stat Date	Current	Status
open Hole Stimulat		.: BB	47610	3,871-1	ALL PROPERTY AND INC.							, 213128				
<b>≤typ&gt; on ≤</b> Type		Diversio	on Method	1  15	SP (psi)		Prop in Forr	n (Ib)	Comment						Date/Time	
	d Name			Fluid	÷	- <u> </u>	ens Fluid (°		1				om	·····		
						<u> </u>					· · · · · · -					
Stg #	Stage	Туре	Top (ft	KB)	Btm (ftKB)	Top (T (ftKB	VD) Bta i)	m (TVD) (ftKB)	Avg Casing Pres (psi)	Avg Tub Pres (p		Break (psi)	Avg Pump Rate (gpm)		Com	
Other In												1		· · · ·		
Des	Run	Date/Ti	me	OD (in)	T	op (ftKB)	Btm (ft)	(B) T	op (TVD) (ftKB	) Btm (TVD)	(ftKB)	Ass'td Strg	_	Com	Comments	
Job Plug and A	bandon	ment (		26/2011		6/17/2011	00.00								· · · · · · · · ·	, .
Job Category Permanent			Primary J	lob Type	ment Only	Job Sub	category		Job Start Da 4/	<i>te/Time</i> 26/2011	Jot	End Date/ 6/17	lime /2011	PA Com	lob Summary PA Complete - Well Cut and Capped	
Daily Op	4:52 - 5/		1-14-52											,		
<i>Management</i> est guyline ar	Summary															<u></u>
								Con	ments	·						
														·		
										<u></u>						

## Regulatory Detail Report

Well: Kennedy-Johnsfed A - 1

.

#### ExxonMobil Production Company

Printed: 7/15/2011 Page #2 of 4 Page(s)

#### Field: GRAYBURG JACKSON

Daily Operations
5/20/2011/14:52-5/21/2011 14:52
Management Summary
cost update
Comments
5/31/2011 00 00 = 6/1/2011 00 00
Management Summary
Dröve rig to location, LO/TO,dig out cellar. spotted rig.
Comments
sdon
drive rig and equipment to loc. isa, safty inspection, loto, check pressures Opsi
dig cellar, spot pipe racks, slide, and rig mats spot rig
look for dead man with fork lift and buy shovel, secure well
sdon
6///2011.00.00 6/2/2011.00.00
Management Summary Unhang well head and unseat pump. Chang over tools. Lay down rods 7/862, 3/480, and pump with 2ft sub.
Comments
sdon
Drive to loc. isa, safty inspection, and h2s mon. look for dead man anchor with metal dect.
Rig up pulling unit.
Unhang well head and unseat pump. Change over tools.
fix key view
Lay down rods 7/8- 62, 3/4- 80, and pump with 2ft sub.
secure well drove crew home.
sdon -
6/2/2011/00/00 6/3/2011/00:00
Management Summary
Change over tools 2 3/8 to 2 7/8 and rams on bop. Rig up pump and half moon, circulate 133bbls b/w well starting gassing pumped anoter 50bbls. b/w.
Comments
sdon . Drave seaw to locker ing softwingestion him marity softwards was a set
Drove crew to loation, jsa, safty inspection, h2s monitor, cofo, check pressures 0 psi. Change over tools 2 3/8 to 2 7/8 and rams on bop.
Rig up pump and half moon.
Waite on brine water.
Circulate 133bbls. b/w,well starting gassing pumped 50bbls. b/w
Circulate Tobbis. Dw, well statuting gassing putriped bobbis. Dw Momitor well, secure well and drove crew home.
Nichtigen weit and drove crew notifie. Sdon
6/3/2011/00/00# 6/4/2011/00/00
Management Summary
Kill well, NUBOP, POOH witbg and BHA. TIH picking up work string leaving killstring
Comments
Shut down for night.
Crew traveled to location
JSA, Safety inspection, H2S monitors, COFO, Check pressures, tog vac and casing 10psi.
nipple down wellhead and nipple up BOP, had trouble with flange on BOP
Test BOP to 500 psi
rig up floor and tbg tongs
POOH w/ tbg and lay down 118 jts of 2 7/8
Change over tools, pipe rams and move tbg and rods with forklift
pick up pipe 25 jts of work string for kill string
secure well for night
Change clothes and drive crew home
shut down for night.
56/2011-00:00 +6/7/2011-00:00
Management Summary R/J and TH w/work string. Circums W/ 120 bbls of R/M. Rums and at 2575' w/ 25 size of anti-DOOV and touchand a touchand a size of a string.
P/U and TiH w/ work string. Circ well w/ 130 bbls of BW. Pump cmt at 3576' w/ 35 sks of cmt. POCH and lay down 8 jts and stand back 20 stands. Reverse circulate 25 bbls. WOC.
•

## Regulatory Detail Report Well: Kennedy-Johnsfed A - 1

## ExxonMobil Production Company

Printed: 7/15/2011 Page #3 of 4 Page(s)

FINH GRAVELING IACKSON

Comments
Shut Down For The Night
Safety Meeting at the Key Yard
Drove crew to location. HSM - Review BJSA. Check H2S monitors.
P/U and TiH w/ workstring.
Circulate well w/ 130 bbls
Pump cmt at 3576' w/ 35 sks of cmt.
POOH lay down 8 its and stand back 20 stands
Reverse circulate 25 bbls
Nait on cement. Drive crew to Lovington, N M.
Shut Down For The Night
6/7/2014 00:000 6/8/2014 00:000
Vanagement Summary
Pump 40 bbls of brine to get circulation and 40 bbls to clean up. Pump 70 sks at 3576'. Poh w/ 30 stands, WOC, RIH and tag at 3400'. Test plug hole in casing. Confirmed casing problem. Called and Informed BLM. Pump 25 sks cmt at 3012'. Lay down 6 and poh w/15 stands.
Comments Shut Down For The Night
Drove crew to location.
sa, safty inspection, cofo, h2s monitors, check pressures 0psi
ih w/ tbg no fill
alk to blm richard pump 70 sks at 3576
bump 40 bbls of brine to get circulation and 40 bbls to clean up
bump 70 sks at 3576
bóh w/ 30 stands
Nait on cement.
ih and tag at 3400
est plug hole in casing
all blm richard go to next plug
pump 25 sks at 3012 lay down 6 poh w/15 stands
secure welf, drove crew home.
;hut down for the night
x8/2011 00:00 - 6/9/2011 00:00 - FEET ALL TALLER AND BEET AVERAGES FEIT 2011 FEET ALL TALLER AND AN AND AND
Aanagement Summary
TH and tag at 2,901'. Pressure test plug - leaked off. Spot additional 25 sk cmt plug at 2,901'. WOC. TiH and tag plug at 2,775'. TOH. Pump 40 sks cmt at 2,028'. WOC.
Comments
Shut Down For The Night
Drove crew to location. HSM - Review BJSA. Checked h2S monitors.
TH and tag plug at 2901'.
Pressure test plug. Casing leaked off.
Spot additional 25 sk cmt plug at 2,855'. Talked w/ Richard w/ BLM.
ay down 6 jts. POOH w/ 10 stands.
Vait on Cement
TH and tag cmt plug at 2,775'. Pressure test csg. Still leaking off.
Lay down 21 jts. Spot 40 sks at 2028'.
ay down 8 its and stand back 15 stands. WOC. SWFN
ay down 8 jis and stand back 15 stands. WOC. SWEN
×9/2011:00:00 = 6/10/2011:00:00
Management Summary RIH and tag at 1830'. Pressure up and test plug. Hole in casing. BLM on location. Circulate 26 sks of salt jell at 1830'. Mix and pump 40 sks of cmt at 982'. POOH w/ 12 stands. WOC. RIH and tag at 944'. Cement not completely cured. POOH w/ 10 stands and rose circulate 25 bbls of brine.
Comments
Drove crew to location. HSM - Review BJSA. Check H2S monitors.

# Regulatory Detail Report Well: Kennedy-Johnsfed A - 1

### ExxonMobil Production Company

Printed 7/15/2011 Page #4 of 4 Page(s)

Field: GRAYBURG JACKSON

Comments
RIH and tag at 1830'. Pressure test csg. Still bleeding off. Hole in casing.
CALL BLM and spoke to Legion Brumley.
Circulate 26 sks of salt jell at 1830'.
Mix and pump 40 sks of cmt at 982' POOH w/ 12 stands.
Break for lunch. Wait on cement.
RIH and tag at 944'.
POOH w/ 10 stands and reverse circulate 25 bbls of brine.
SWFN. Drove crew back to Lovington, NM.
Shut Down For The Night
6/10/2011 00:00 - 6/11/2011 00:00
Management Summary RIH and tag cmt at 834'. Pressure Test. Casing still leaks off. PUH and pump 60 sks cmt at 300', WOC. NDBOP Tag TOC at 15'. No casing leak off. Remove wellhead swedge.
Comments
Shut Down For The Night
Drove crew to tocation. HSM - Review BJSA. Check cofo. Check H2S monitors. Check pressure on well - Zero.
RIH and tag TOC at 834'. Pressure test plug. Leaked off. Hole in casing.
Called Legion Brumley w/ BLM on job status. Approval granted to spot next plug.
PUH and spot 60 sk cmt plug at 300'. Additional interval added to isolat casing leak.
Wait on cement. Break for lunch.
NDBOP
RIH and tag cmt at 15'. Call Legion Bruley w/ BLM and notified on tag depth. No casing leak off.
Remove 5 1/2" by 8 5/8" swedge.
Secure well site. Begin driving crew back to Andrews, Tx.
Secure wearsher begin uniting crew back to Palatews, rx.
6/13/2011 00:00 - 6/14/2011 00:00
Management Summary
Call BLM and notified Legion Brumley of intent to cut 7" casing. R/U casing cutter and cut casing. POH w/ cutter and P/U spear. Pull casing stub and top off casing w/ 5 sks of cmt. Wash out half moon tank. R/D WSU and R/D pump and lines. Move rig and equipment to next location.
Comments
Shut Down For The Night.
Drove crew to location. HSM - Review BJSA and check H2S monitors.
Call and notify Legion Brumley w/ BLM of intent to cut 7" casing. P/U casing cutter and cut 7" casing.
Wait on part for casing spear.
Clean out half moon tank and get ready to move.
Pump 5 sks of cmt to surface.
R/D pump and equipment.
R/D WSU.
Move equipment to Kennedy Johnson A#2
Work on another well. Shut Down For The Night.
6/14/2011 00:00 - 6/15/2011 00:00
Management Summary
cost added
Comments
6/16/2011 00:00 - 6/17/2011 00:00 Management Summary
Weld caps to P&A well
Comments

740