

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
 accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Lime Rock Resources II-A, LP	Contact: Michael Barrett
Address: 1111 Bagby St. Suite 4600, Houston, TX 77002	Telephone No. 575-623-8424
Facility Name: Falcon 3 G Federal #7	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-29126 (LC 065478-B)
------------------------	------------------------	---------------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	3	18S	27E	1450	N	2310	E	Eddy

Latitude 32.779365 Longitude -104.265335

**NATURE OF RELEASE**

Type of Release: Mixed Fluids	Volume of Release: 30bbls Oil 20bbls PW	Volume Recovered: 24 bbls Mixed Fluids
Source of Release: Heater Treater	Date and Hour of Occurrence: 12/28/2015	12/28/2015 and Hour of Discovery:
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
 A heater treater malfunctioned causing a release of 20bbls of produced water and 30bbls of oil. The heater treater was taken out of service and repaired. A vacuum truck was dispatched to the location and recovered 24bbls of fluid. Talon mobilized personnel to the location for emergency spill response and to contain the release due to adverse weather conditions. Recovery of fluid continued as the snow melted.

Describe Area Affected and Cleanup Action Taken.\*  
 The impacted area encompassed the location downhill of the battery, the county road, and the pasture on the south side of the road. Initial response activities included building berms to contain the fluid and snow melt, steam cleaning the road (fluid was recovered with a vacuum truck), and scraping the heavily impacted soil from the surface. Once Talon personnel conducted a site assessment and performed soil sampling at the site a remediation work plan was drafted and subsequently approved by NMOCD and BLM. The remediation was conducted to the scope laid out in the approved work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Michael Barrett	Approved by Environmental Specialist:	
Title: Production Supervisor	Approval Date: 1/29/2016	Expiration Date: N/A
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 1/27/2016 Phone: 575-623-8424		

\* Attach Additional Sheets If Necessary