

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Juneau 31 Fee Com
2. Name of Operator BOPCO, L.P.	8. Well Number 1
3. Address of Operator P O Box 2760 Midland, Tx 79702	9. OGRID Number 260737
4. Well Location Unit Letter P : 1980 feet from the South line and 660 feet from the West line Section 31 Township 21S Range 28E NMPM County Eddy	10. Pool name or Wildcat WildcatG-02 S212831L; Delaware
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

**Notify OCD 24 hrs. prior
To any work done.**


13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

BOPCO, L.P. respectfully requests permission to plug and abandon the subject wellbore as follows:

1. MIRU pulling unit and plugging equipment. Set open top steel pit for plugging. ND WH & NU 3,000 psi manual BOP for 2-3/8" tubing.
2. Test 2-7/8" x 5-1/2" annulus to check tubing integrity.
3. RIH with bit and drill out 5 1/2" CIBP with 35# cement cap @ 7749#.
4. RIH with WL and set 5 1/2" CIBP @ 9306#. Dump bail 100# Class H cement on top.
5. RIH with WL and set 5 1/2" CIBP @ 7774#. Dump bail 35# Class H cement on top.
6. RIH with WL and set 5 1/2" CIBP @ 5528#. Dump bail 35# Class H cement on top.
7. RIH with jet cutter. Cut and pull 5 1/2" casing at 2600#. POOH with WL.
8. RIH with tbg. to 2800#. Circulate 202 bbls 9.5# Salt Gel to surface.
9. Spot 50 sxs CI C cement from 2830# to 2550#. WOC & TAG. POOH with tbg. Plugs 10 thru 15 continued on attachment

Spud Date:

Rig Release Date:



**SEE ATTACHED
CONDITIONS OF
APPROVAL**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Sandra J. Belt

TITLE Sr. Regulatory Clerk

DATE 01/19/2012

Type or print name Sandra J. Belt ext. 7379

E-mail address: sjbelt@basspet.com

PHONE: (432)683-2277

For State Use Only

APPROVED BY:

P. H. Harkin

TITLE

Approval Granted providing work
is complete by 4/25/2012

DATE 1/25/2012

Conditions of Approval (if any):

Juneau 31 Fee Com #1

30-015-32705

Plug and Abandon

1.19.12

10. RIH with WL and set 9 5/8" (40#) CIBP @ 1740'. Dump bail 35' Class C cmt on top. POOH with WL.
11. RIH with tbg and spot 130 sxs Class C cement from 890' to 500'. WOC & TAG.
12. PUH to 100' and spot 35 sxs Class C cement from 100' to surface.
13. ND BOP and cut off wellhead 5' below surface.
14. Set P&A marker and remediate location.
15. Use steel tank and haul all fluids.