Office	State of New Mex		Form C-103
District I	Energy, Minerals and Natura	l Resources	May 27, 2004
1625 N French Dr , Hobbs, NM 88240 HOBBS OCD District II			L API NO.
District II	OIL CONCEDUATION D		15-22051
1301 W Grand Ave, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd, Aztec, NM 8741 DEC	30 20111220 South St. Franc	is Dr.	dicate Type of Lease STATE FEE
1000 Rio Brazos Rd, Aztec, NM 87410) CO	Santa Fe, NM 875	05	rate Oil & Gas Lease No.
1220 C. Ct. Enomous Dr. Comto Eo. NIM	ECEIVED	0. 50	ate off & das Lease No.
SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. L	ease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		BACK TO A	suse Nume of One rigidement Nume
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		SUCH	Empire Abo Unit "K"
1. Type of Well: Oil Well Gas Well Other		8. W	'ell Number
1. Type of well. On well 2	Gas Well Gulei G		141A
2. Name of Operator		9. O	GRID Number
Apache Corporation 3. Address of Operator		10 1	873 Pool name or Wildcat
3. Address of Operator 303 Veterals Airpark Lane, STE. 3000, Midland, TX. 79705		10. 1	Empire Abo
4. Well Location	. 2000, Middle 10, 121, 13, 10		Empire Abo
Unit Letter K: 137	0 feet from the S line and	2445 feet from the	ne W line
Section 2 Township	18S Range 27E NMPM		Eddy
	3521 ft. GR.	(KD, KI, OK, etc.)	
Pit or Below-grade Tank Application or Closure			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water_N/A			
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction M	laterial
12 Check At	opropriate Box to Indicate Nat	ure of Notice Repor	t or Other Data
12. Check H	propriate Box to maleute rut	are of Notice, Repor	t of Other Bata
NOTICE OF IN	FENTION TO:	SUBSEC	QUENT REPORT OF:
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. □ P AND A ⊠
TEMPORARILY ABANDON DULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPL	COMMENCE DRILLING CASING/CEMENT JOE	_
·			_
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple	MULTIPLE COMPL ted operations. (Clearly state all per	CASING/CEMENT JOE OTHER: rtinent details, and give	pertinent dates, including estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work	MULTIPLE COMPL ted operations. (Clearly state all per	CASING/CEMENT JOE OTHER: rtinent details, and give	
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion.	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple	CASING/CEMENT JOE OTHER: rtinent details, and give	pertinent dates, including estimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple fl pent. Set 5 ½ CIBP @ 5625 ft.	CASING/CEMENT JOE OTHER: rtinent details, and give p Completions: Attach we	pertinent dates, including estimated date ellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 13	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions of the comp	pertinent dates, including estimated date ellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 s	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. tubing. Circulate 5 ½ casing W/ 13 sacks cement. (240 ft.) Spot 30 sacks.	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we complete the complete of mud lader the complete from 3251 ft.	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid.
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 9 Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153	MULTIPLE COMPL ted operations. (Clearly state all perk). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 1. sacks cement. (240 ft.) Spot 30 sack of the WOC 4 ft. Perforate @ 1056 ft. 28 ½ Page	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we can be completed as a second sec	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. 1. (289 ft.)
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 5 Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 1. sacks cement. (240 ft.) Spot 30 sack of t WOC 4 ft. Perforate @ 1056 ft. 25 ½ Page 60 sacks cement. Displace to 900	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we see that the completions of the completion o	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft.
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 9 Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/1. Sacks cement. (240 ft.) Spot 30 sact 0 ft WOC 4 ft. Perforate @ 1056 ft. 23 ½ Pac on 60 sacks cement. Displace to 900 ½ Packer @ 30 ft. Pump 40 sacks cement.	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we see that the completions of the completion o	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft.
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 9 Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 13 sacks cement. (240 ft.) Spot 30 sack of ft WOC 4 ft. Perforate @ 1056 ft. 23 ½ Pac of 60 sacks cement. Displace to 900 ½ Packer @ 30 ft. Pump 40 sacks company to the	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we can be completed as a second of the complete complete the complete	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface.
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 9 Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/13 sacks cement. (240 ft.) Spot 30 sacl 0 ft WOC 4 ft. Perforate @ 1056 ft. 28 ½ Page 60 sacks cement. Displace to 900 2 Packer @ 30 ft. Pump 40 sacks complete in the sacks comple	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we can be completed as a second of the complete complete the complete	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface.
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 s Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91	MULTIPLE COMPL ted operations. (Clearly state all perk). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/12 sacks cement. (240 ft.) Spot 30 sack of t WOC 4 ft. Perforate @ 1056 ft. 25 ½ Pack of 25 packs cement. Displace to 900 performed with 9 sacks complete to 10 pent. Fill 5 ½ wellbore with 9 sacks complete to 10 pent. Install dry-hole marker.	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we can be completed as a second of the complete complete the complete	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface.
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 s Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91 12-21-2012 Anchors. Clean location	MULTIPLE COMPL ted operations. (Clearly state all perk). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/12 sacks cement. (240 ft.) Spot 30 sack of t WOC 4 ft. Perforate @ 1056 ft. 25 ½ Pack of 25 packs cement. Displace to 900 performed with 9 sacks complete to 10 pent. Fill 5 ½ wellbore with 9 sacks complete to 10 pent. Install dry-hole marker.	CASING/CEMENT JOE OTHER: rtinent details, and give process of the completions: Attach we can be completed as a second of the complete complete the complete	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface.
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 % Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91 12-21-2012- Anchors. Clean location 12-21-2013- RDMO plugging equip	MULTIPLE COMPL ted operations. (Clearly state all perk). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 1. Sacks cement. (240 ft.) Spot 30 sacl 0 ft WOC 4 ft. Perforate @ 1056 ft. 23 ½ Pace 10,60 sacks cement. Displace to 900 ½ Packer @ 30 ft. Pump 40 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft. Fill 5 ½ wellbore with 9 sacks complete to 10 ft.	CASING/CEMENT JOE OTHER: rtinent details, and give properties. Attach we see that the completions of mud lader and the completion of the c	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface. rface. Cut-off wellhead and
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 9 Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91 12-21-2012- Anchors. Clean location 12-21-2013- RDMO plugging equip	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 1. Sacks cement. (240 ft.) Spot 30 sack 0 ft WOC 4 ft. Perforate @ 1056 ft. 23 ½ Pace 1056 sacks cement. Displace to 900 ½ Packer @ 30 ft. Pump 40 sacks complete to 1056 ft. Fill 5 ½ wellbore with 9 sacks complete to the best pove is true and complete to the best	CASING/CEMENT JOE OTHER: rtinent details, and give properties. Attach we completions: Attach we also be completed at the complete of mud lader which we can be completed at the complete of th	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface. rface. Cut-off wellhead and
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 % Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2012- Anchors. Clean location 12-21-2012- RDMO plugging equipment of the property of	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 13 sacks cement. (240 ft.) Spot 30 sack of ft WOC 4 ft. Perforate @ 1056 ft. 25 ½ Packer @ 30 ft. Pump 40 sacks cement. Displace to 900 ½ Packer @ 30 ft. Pump 40 sacks cement. Fill 5 ½ wellbore with 9 sacks cement. Install dry-hole marker. ment.	CASING/CEMENT JOE OTHER: rtinent details, and give process of mudical completions: Attach we shall be a general permit or an (a	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) circulation down plug @ 901 ft. Casing to surface. rface. Cut-off wellhead and elief. I further certify that any pit or belowttached) alternative OCD-approved plan .
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 % Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91 12-21-2012- Anchors. Clean location 12-21-2013- RDMO plugging equipm I hereby certify that the information of grade tank has been/will be constructed or clean location of the start of the sta	MULTIPLE COMPL ted operations. (Clearly state all perk). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 13 sacks cement. (240 ft.) Spot 30 sack of ft WOC 4 ft. Perforate @ 1056 ft. 25 ½ Packer @ 30 ft. Pump 40 sacks cement. Displace to 900 2 Packer @ 30 ft. Pump 40 sacks complete to the best of in. Install dry-hole marker. Ment. TITLE	CASING/CEMENT JOE OTHER: rtinent details, and give process of mudical completions: Attach we shall be a general permit or an (a	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface. rface. Cut-off wellhead and
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 % Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91 12-21-2012- Anchors. Clean location 12-21-2012- RDMO plugging equipm I hereby certify that the information of grade tank has been/will be constructed or clean location of the start of the sta	MULTIPLE COMPL ted operations. (Clearly state all per k). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 13 sacks cement. (240 ft.) Spot 30 sack of ft WOC 4 ft. Perforate @ 1056 ft. 25 ½ Packer @ 30 ft. Pump 40 sacks cement. Displace to 900 ½ Packer @ 30 ft. Pump 40 sacks cement. Fill 5 ½ wellbore with 9 sacks cement. Install dry-hole marker. ment.	CASING/CEMENT JOE OTHER: rtinent details, and give p Completions: Attach we 31 barrels of mud lade ks cement from 3251 ft cker @ 630 ft. Establish 0 ft. WOC. Tag cement cement down 5 ½ x 8 5/c ement from 91 ft. to su of my knowledge and b a general permit or an (a	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) circulation down plug @ 901 ft. Casing to surface. rface. Cut-off wellhead and elief. I further certify that any pit or belowttached) alternative OCD-approved plan .
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 % Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91 12-21-2012- Anchors. Clean location 12-21-2013- RDMO plugging equipm I hereby certify that the information of grade tank has been/will be constructed or clean location of the start of the sta	MULTIPLE COMPL ted operations. (Clearly state all perk). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 13 sacks cement. (240 ft.) Spot 30 sack of ft WOC 4 ft. Perforate @ 1056 ft. 25 ½ Packer @ 30 ft. Pump 40 sacks cement. Displace to 900 2 Packer @ 30 ft. Pump 40 sacks complete to the best of in. Install dry-hole marker. Ment. TITLE	CASING/CEMENT JOE OTHER: rtinent details, and give p Completions: Attach we 31 barrels of mud lade ks cement from 3251 ft cker @ 630 ft. Establish 0 ft. WOC. Tag cement cement down 5 ½ x 8 5/c ement from 91 ft. to su of my knowledge and b a general permit or an (a	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface. rface. Cut-off wellhead and elief. I further certify that any pit or belowttached) alternative OCD-approved plan .
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 12-15-2011- MIRU Plugging Equipm 12-16-2011- Tag 5 ½ CIBP w/ 2 3/8 12-19-2011- Cap 5 ½ CIBP with 25 % Spot 35 sacks from 186 12-20-2011- Tag cement plug @ 153 5 ½ x 8 5/8 casing. Pum Perforate @ 150 ft. 5 ½ Displace to 100 ft. WO 12-21-2011- Tag cement plug @ 91 12-21-2012- Anchors. Clean location 12-21-2012- RDMO plugging equipm I hereby certify that the information of grade tank has been/will be constructed or clean location of the start of the sta	MULTIPLE COMPL ted operations. (Clearly state all perk). SEE RULE 1103. For Multiple pent. Set 5 ½ CIBP @ 5625 ft. Tubing. Circulate 5 ½ casing W/ 13 sacks cement. (240 ft.) Spot 30 sack of ft WOC 4 ft. Perforate @ 1056 ft. 25 ½ Packer @ 30 ft. Pump 40 sacks cement. Displace to 900 2 Packer @ 30 ft. Pump 40 sacks complete to the best of in. Install dry-hole marker. Ment. TITLE	CASING/CEMENT JOE OTHER: rtinent details, and give p Completions: Attach we 31 barrels of mud lade ks cement from 3251 ft cker @ 630 ft. Establish 0 ft. WOC. Tag cement cement down 5 ½ x 8 5/c ement from 91 ft. to su of my knowledge and b a general permit or an (a	pertinent dates, including estimated date ellbore diagram of proposed completion in fluid. (289 ft.) a circulation down plug @ 901 ft. 8 casing to surface. rface. Cut-off wellhead and elief. I further certify that any pit or belowttached) alternative OCD-approved plan .

-

don