Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I – (575) 393-6161	gy, Minerals and Natural-Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 RECEN District II - (575) 748-1283	ED RECEIVED	.30-015-40842
<u>District III</u> – (505) 334-6178 SEP 05 2	CONSERVATION DIVISION 20220 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505 ESIA	6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, MMOCD AR 87505	TESIA	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		West Shugart 2 19 30 State
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other		8. Well Number
2. Name of Operator		3H 9. OGRID Number
Chevron USA Inc		4323
3. Address of Operator		10. Pool name or Wildcat
15 Smith Rd Midland, TX 79705	·	Benson Bone Spring (5200)
4. Well Location		
		50 feet from the West line
Section 2	Township 19S Range 30E ation (Show whether DR, RKB, RT, GR, etc.	<u>NMPM</u> County Eddy
11. Elevation (Show whether DR, RRD, RT, OR, etc.)		
12. Check Appropria	te Box to Indicate Nature of Notice,	Report or Other Data
		SEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE	= 1	
	· · ·	
OTHER: 13. Describe proposed or completed operation	tions (Clearly state all pertinent details an	etion of New well 🛛 🖂 Id give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Completion Procedures:	•	
08/07/13 MIRU pulling unit and RU reverse Un	nit. Move in Lay down machine. NU tubing	hanger & check valve & install. ND Frac
Valve, NU 10 K X 5k spool & BOP & torque u	p all bolts to specs. Pressure up on BOP bli	nd Rams & Pipe Rams to 250 psi Low & 500
PSI high & Held Okay. RU Rig Floor and pull Tubing Hanger with 2 7/8' Pump, Joint w/ no Pressure on well.		
08/08/13 Off load 2 7/8' Tubing & strap for tally, No pressure on the well. TIH with Peak TAC BHA & Desander. Test tubing to 6000 ps below the slips. Set peak 5 ½ x 2 7/8 45K shear TAC w/ 10 K Tension & SO & set @ 7851. 25 ft released from TAC & lay down 5 jts to		
facilitate TIH w/Sub pump BHA. Circulate well		
Night cap & close.		
		· · · · · · · · · · · · · · · · · · ·
Spud Date: 05/06/2013	Rig Release Date: 08/10/2013	
•		
· · · · · · · · · · · · · · · · · · ·		
I hereby certify that the information above is tru	ie and complete to the best of my knowledge	ge and belief.
SIGNATURE (Indy Henna-M	WILD TITLE Permitting Specialist	DATE 09/04/2013
Type or print name Cindy Herrera-Murillo	E-mail address: Cherreramurillo@cl	hevron.com PHONE: 575-263-0431
For State Use Only		
Conditions of Approval (if any):		

West Shugart 2 19 30 State #3H Completion Procedures

08/08/13 Turn Well over to production Department.

08/09/13 No pressure on well. Unlock Pipe Rams, Open BOP, ND TIW valve.

TOH with 2 7/8' tubing and On/Off Tool

RU Cable equipment and pick up Sub Pump BHA and start in the hole

Continue in hole with 2 7/8' tubing with Sub Pump BHA binding electrical cable to tubing

08/10/13 NU QCI tubing hanger and install

ND BOP Stack and Load on Trailer

Complete NU of Prod tree and install Sub Pump Cables & Tech connected to Power Lines as designed RU Pump Line to wellhead and do function test on Sub Pump and worked as designed

DO Rig move check list. RD Pulling Unit.