

Submit 1 Copy To Appropriate District	State of New	/ Mexico	Form C-103	
Office District 1 – (575) 393-6161	Energy, Minerals and	Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-10843 5. Indicate Type of Lease	
District III - (505) 334-6178	1220 South St. Francis Dr.		STATE STEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NI	M 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ICES AND REPORTS ON WE		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		COTTON DRAW UNIT		
1. Type of Well: Oil Well	Gas Well Other SWD		8. Well Number 65	
2. Name of Operator			9. OGRID Number	
Devon Energy Production Company, LP 3. Address of Operator		6137 10. Pool name or Wildcat		
333 W. Sheridan Avenue, Oklahoma City, OK 73102			SWD; CHERRY CANYON	
4. Well Location				
	1980 feet from the	North line and 198	0 feet from the East line	
Section 2	Township 25S	Range 31E	NMPM County Eddy	
	11. Elevation (Show whether			
	3476 KB; 3455 GL			
12 Check	Appropriate Box to Indica	te Nature of Notice	Penart or Other Data	
•			•	
	ITENTION TO:		SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	_	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	I JOB 🗀	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM		OTUED.	· 🗖	
OTHER:	leted operations (Clearly stat	OTHER:	d give pertinent dates, including estimated date	
			mpletions: Attach wellbore diagram of	
proposed completion or rec		ı	Approved for plugging of well bore only.	
			Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)	
Proposed P&A:	0))	01)	which may be found at OCD Web Page under	
1. MIRU. Spot 30 sx cmt (120') @ 7,500'. (DV tool @ 7,478').			Forms, www.cmnrd.state.nm.us/oed.	
 Circulate 9.5 mud between plugs. Set CIBP @ 5,300'. Spot 30 sx cmt (120') on top. (Open Cherry Canyon SWD perfs @ 5326-5714). 				
4. Spot 45 sx cmt (180') @ 4,415'. Tag TOC. (Calc. PBD @ 4,235'. 13-3/8" shoe @ 4,365'. Top of Delaware @ 4,370').				
5. Spot 60 sx cmt (240') @ 4,150'. (Calc. PBD @ 3,910'. Base of salt @ 4,115').				
6. Spot 40 sx cmt (160') @ 950'. (Calc. PBD @ 790'. Top of salt @ 950').			RECEIVED	
7. Spot 40 sx cmt (160') @ 650'. Tag TOC. (Calc. PBD @ 490'. 20" shoe @ 600')			/·	
8. Spot 30 sx cmt from 120' to surface.9. Cut wellhead off 3' BGL. Set dry hole marker.			OCT 3 0 2013	
CONDITIONS OF APPRO			1	
			NMOCD ARTESIA	
Spud Date: Completed by	oviding work is ig Relea	se Date:		
- Combletea by	30,2014	se Date.		
<u>ver</u>	20,0019			
I hereby certify that the information	above is true and complete to	the best of my knowledg	ge and belief.	
0.	Λ Α		_	
SIGNATURE Romme	Space TITLE	_Production Technologi	stDATE	
Type or print nameRonnie Slack	E-mail address:Ro	nnie.Slack@dvn.com	PHONE:405-552-4615	
For State Use Only	1.			
APPROVED BY:	CL TITLE L)157 II Dysel	U(S) DATE 10/30/2013	
Conditions of Approval (if any): SEE ATTAChes	(POA'S		, ,	
Patt HIACKE				





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Devon	
Well Name & Number: Cotton DRAW Unt 6	25
API#: 30-015-108\$3	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.

10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/30/13

APPROVED BY: Albelo

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).