Form 3160 5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

		ļ,,,, c.s.	Ju
Lease Seri	al N	۱o.	_
NIMI COC	140	200	

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMLC061862  6. If Indian. Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. 891005247E			
Type of Well			8. Well Name and No. COTTON DRAW UNIT 86				
2. Name of Operator Contact: TRINA C COUCH DEVON ENERGY PRODUCTION CO EMail: trina.couch@dvn.com					9. API Well No. 30-015-29850-	00-S1	
3a. Address 1 333 WEST SHERIDAN AVE Ph: 405-228-7203 OKLAHOMA CITY, OK 73102					10. Field and Pool, or Exploratory PADUCA		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	·· <u>-</u>		• 1	11. County or Parish.	and State	
Sec 12 T25S R31E NWSE 2600FSL 1500FEL					EDDY COUNT	Y, NM	
12. CHECK APPR	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF N	OTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION			TYPE OF	ACTION			
Notice of Intent	Acidize Deepen		ng Production	☐ Production (Start/Resume) ☐ Water Shut-Off			
<del>-</del> .	Alter Casing	☐ Frac	ture Treat	☐ Reclamate	tion	■ Well Integrity	
☐ Subsequent Report.	Casing Repair	_	Construction	□ Recompl		☐ Other	
☐ Final Abandonment Notice ☐ Change Plans ☐ Convert to Injectio		☐ Plug and Abandon ☑ Plug Back		☐ Temporarily Abandon ☐ Water Disposal			
Devon Energy Production Cor reference the attachment for p Attachments: Procedure Wellbore Schematics	npany, L.P. respectfully recorded thank you.  need fim  perato	e line	e & plan	ns for	well af	ferwards.	
	Assantad to		 I			I CONOTTO	
			7-14		A	L CONSERVATION	
	NIMIOC	0 76	7 27-14			OCT 2 7 2014	
14. I hereby certify that the foregoing is  Com  Name (Printed/Typed) TRINA C	true and correct. Electronic Submission #25 For DEVON ENERG mitted to AFMSS for process	50742 verifie	d by the BLM Wel TON CO LP, sent NIFER MASON on	to the Hobbs	System s 4JAM0060SE)	RECEIVED	
Signature (Electronic S	Pubminging \	. ,	Date 06/25/20	04.4			
. (Incume t	THIS SPACE FOR	R FEDERA			EF S		
DEST	-1-1+ N						
Approved By		<u> </u>	Title /	w/w	11191	Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equal which would entitle the applicant to condu-	aitable title to those rights in the s		Office		10/23/1	4	
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a cr statements or representations as to	rime for any pe o any matter w	rson knowingly and ithin its jurisdiction.	willfully to mal	ke tó any department o	r agency of the United	

## **CDU 86 Recompletion Activities**

## Michael Markmiller

Sundry #1 – Plugback Devonian and prep well for CBL.

Procedure to Plug Devonian Zone and Test Mechanical Integrity of Remaining Wellbore

- 1. Notify BLM a minimum of 24 hrs prior to: Rigging up WSU; Setting CIBPs; Cementing/Tagging plugs operations and MIT testing for witnessing if necessary.
- 2. MIRU WSU.
- 3. Top kill tubing with 10 ppg Brine.
- 4. ND wellhead and NU 10K BOPE and test to rating.
- 5. Release seal assembly from 5-1/2", 20# Baker Model "DB" packer (packer is a permanent set packer).
- 6. TOH with existing 3 ½", 12.95#, L-80 (AB mod) & 2-7/8", 6.5#, BTS-8 production tubing and seal assembly.
- 7. RU WL w/full lubricator; Make round trip GR/JB run to 5-1/2" Baker packer (Packer reported @ 16,365' KBM).
- 8. Set 10K CIBP on top of 5 1/2" Baker Packer @ 16,365' KBM or depth found in step 7. RD WL.
- 9. TIH with production tubing with tubing collar on bottom (hydro test tubing below slips while TIH) to 2' above CIBP.
- 10. Load and balance hole with 2% KCL.
- 11. Set 25 sack Class H cement (16.4 ppg) plug on top/above CIBP @ 16,365' (calc cement plug from 16,365' KBM to ~ 16,155' KBM 210'). Pull tbg to 15,900' and reverse circ clean with 2% KCL. WOC
- 12. Drop down and tag TOC.
- 13. If ok, pick up 2'. Spot & balance in (150 bbls) 9 ppg mud from TOC ~ 16,155' KBM to ~ 12,055' KBM 4,100')
- 14. Pull bottom of tubing to 14,875' KBM. Set a 101 sack Class H cement (16.4 ppg) plug. (calc cement plug from 14,875' KBM to 14,250' KBM 625'; note top of Morrow at 14,405'). Will need to displace cement plug in place with a flush consisting of 9 ppg mud and 2% KCL to balance. Pull tubing to 12,000' KBM and reverse circ clean with 2% KCL. WOC
- 15. Drop down and tag TOC.
- 16. If ok, pull bottom of tubing to 12,500' KBM. Set a 115 sack Class H cement (16.4 ppg) plug. (calc cement plug from 12,500' KBM to 12,050' KBM 450'). Displace cement with 2% KCL. Pull tubing to 11,500' KBM and reverse circ clean with 2% KCL. WOC.
- 17. Drop down and tag TOC.
- 18. If ok, pick up 2'and reverse circ and balance hole with 2% KCL.
- 19. Pressure test 9-5/8", 47# & 53.5#, P-110 casing to 1,000 psi @ surface for 30 min. (chart record the 30 min pressure test).
- 20. TOH with production string.
- 21. Roundtrip 8-3/8" bit & casing scraper for 9-5/8" (47# to 53.5#) casing to ~ 12,000' KBM.
- 22. RU WL with packoff. Run radial CBL from current PBTD to surface. Make two passes with CBL. One pass with 0 psi and the second pass with 1,000 psi @ surface. RD WL.
- 23. RDMO WSU. Follow up work with a subsequent report to including test chart and logs to BLM.



