Submit 1 Copy To Appropriate District Office District I – (575) 393-6161 1625 N. French Dr., Hobbi, NM 88240 ESIA DISTRICT District II – (575) 748-1283 District II – (575) 748-1283	Form C-103
District 1 – (575) 393-6161 and OIL CONSEE thereby, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88249 ESIA DISTIN	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 MAR 0 9 2015 CONSERVATION DIVISION District III - (505) 334-6178	30-015-29345
1220 South St. Flancis D1.	5. Indicate Type of Lease STATE FEE □
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr. Santa Fe, NM RECEIVED Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State On & Gas Least No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	COTTON DRAW UNIT
1. Type of Well: Oil Well Gas Well Other-SWD	8. Well Number 81
2. Name of Operator Devon Energy Production Company, LP	9. OGRID Number 6137
3. Address of Operator	10. Pool name or Wildcat
333 W. Sheridan Avenue, Oklahoma City, OK 73102	SWD;DELAWARE
4. Well Location	
Unit LetterL:1650'_feet from theSouth line and660'	feet from theWestline
Section 02 Township 25S Range 31E	NMPM Eddy County, NM
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3455' KB; 3437'GL; 18' KB to GL	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMESIAE WORK TESSANDARY TREMESIAE WORK	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR	LLING OPNS. □ PAND A 🛛
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMEN	T JOB 🔲
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	•
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs)	mpletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bonder) 	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445')
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. mud circulated between plugs) 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445')
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. mud circulated between plugs) 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 Spot 30 sx Cl C cmt @ 5,341' - 5,531'. 	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445')
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. mud circulated between plugs) 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445')
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. mud circulated between plugs) 2/3/15-MIRU. Set CIBP @ 8,700°. Spot 30 sx Cl H cmt. Tagged @ 8,487°. (Bon 2. Spot 30 sx Cl H cmt @ 7,634°. No tag. Spot 30 sx Cl H @ 7,634°. Tagged @ 7,44 Spot 30 sx Cl C cmt @ 5,341° – 5,531°. Spot 60 sx Cl C cmt @ 4,561°. Tagged @ 4,199°. (B.Salt @ 4,296°. T.Bell Canyo interval @ 4,556°-5,360°) Cut 7" csg @ 3,712° twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, 	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. mud circulated between plugs) 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bom 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 Spot 30 sx Cl C cmt @ 5,341' - 5,531'. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyon interval @ 4,556'-5,360') Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712)
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. mud circulated between plugs) 2/3/15-MIRU. Set CIBP @ 8,700°. Spot 30 sx Cl H cmt. Tagged @ 8,487°. (Bon 2. Spot 30 sx Cl H cmt @ 7,634°. No tag. Spot 30 sx Cl H @ 7,634°. Tagged @ 7,44 Spot 30 sx Cl C cmt @ 5,341° – 5,531°. Spot 60 sx Cl C cmt @ 4,561°. Tagged @ 4,199°. (B.Salt @ 4,296°. T.Bell Canyon interval @ 4,556°-5,360°) Cut 7" csg @ 3,712° twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442°. Tagged @ 4,175°. Spot 30 sx Cl C from 3,612° to 3,785°. (Csg Cut 7" csg @ 3,485°. Unable to pull. Cut & pull 7" csg from 3,068°. Spot 30 sx Cl 	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712)
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998.	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712)
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958')	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712)
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697')	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958')	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697')	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 10 surf	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx C C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1 Spud Date: Rig Release Date:	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 3,712) to a 3,559'. Tagged @ 3,414'. Spot 45 sx Cl the spring perfs 8725'-9445') to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,500'
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 10 surf	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 3,712) to a 3,559'. Tagged @ 3,414'. Spot 45 sx Cl the spring perfs 8725'-9445') to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,500'. Sqzd swd to a 4,199'. Spot 50 to a 4,500'. Sqzd swd to a 4,500'
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx C C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1 Spud Date: Rig Release Date:	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) the C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl the mole marker. Wellbore plugged & abandoned.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx C C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1 Spud Date: Rig Release Date:	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) the C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl the mole marker. Wellbore plugged & abandoned.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx C C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge. SIGNATURE	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) the C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl the mole marker. Wellbore plugged & abandoned. The provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) The provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) The provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) The provious plug tag was @ 4,199'. Spot 45 sx Cl The provious plug tag was @ 4,199'. Spot 45 sx Cl
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 1,022'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1. Spud Date: Rig Release Date:	mpletions: Attach wellbore diagram of the Spring perfs 8725'-9445') to a 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) the C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl the mole marker. Wellbore plugged & abandoned. The provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) the provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) The provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) The provious plug tag was @ 4,199'. Spot 50 cut @ 3,712) The provious plug tag was @ 4,199'. Spot 45 sx Cl The provious plug tag was @ 4,199'. Spot 45 sx Cl
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1. Spud Date: Rig Release Date: Type or print nameRonnie SlackE-mail address: _Ronnie.Slack@dvn.com P For State Use Only	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl mole marker. Wellbore plugged & abandoned. e and belief. DATE 3-4-15 HONE: _405-552-4615
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1. Spud Date: Rig Release Date: Type or print nameRonnie SlackE-mail address: _Ronnie.Slack@dvn.com P For State Use Only	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl mole marker. Wellbore plugged & abandoned. e and belief. DATE 3-4-15 HONE: _405-552-4615
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx C C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1. Spud Date: Rig Release Date: Title Operations Technician Type or print name Ronnie Slack E-mail address:Ronnie.Slack@dvn.com P For State Use Only APPROVED BY:	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl mole marker. Wellbore plugged & abandoned. e and belief. DATE 3-4-15 HONE: _405-552-4615
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. (9# mud circulated between plugs) 1. 2/3/15-MIRU. Set CIBP @ 8,700'. Spot 30 sx Cl H cmt. Tagged @ 8,487'. (Bon 2. Spot 30 sx Cl H cmt @ 7,634'. No tag. Spot 30 sx Cl H @ 7,634'. Tagged @ 7,44 3. Spot 30 sx Cl C cmt @ 5,341' – 5,531'. 4. Spot 60 sx Cl C cmt @ 4,561'. Tagged @ 4,199'. (B.Salt @ 4,296'. T.Bell Canyo interval @ 4,556'-5,360') 5. Cut 7" csg @ 3,712' twice. Unable to pull. Dropped csg spear. Tagged spear @ 4, sx Cl C @ 4,442'. Tagged @ 4,175'. Spot 30 sx Cl C from 3,612' to 3,785'. (Csg 6. Cut 7" csg @ 3,485'. Unable to pull. Cut & pull 7" csg from 3,068'. Spot 30 sx Cl C @ 3,137'. Tagged @ 2,998. 7. Spot 55 sx Cl C @ 1,022'. Tagged @ 873'. (T.Salt @ 958') 8. Spot 55 sx Cl C @ 776'. Tagged @ 637'. (13-3/8" shoe @ 697') 9. 2/19/15-Spot 40 sx Cl C from 129' to surface. 2/26/15-Cut wellhead off. Set dry 1. Spud Date: Rig Release Date: Type or print nameRonnie SlackE-mail address: _Ronnie.Slack@dvn.com P For State Use Only	mpletions: Attach wellbore diagram of e Spring perfs 8725'-9445') 0'. n @ 4,317'. 9-5/8" shoe @ 4,500'. Sqzd swd 442'. Previous plug tag was @ 4,199'. Spot 50 cut @ 3,712) cl C @ 3,559'. Tagged @ 3,414'. Spot 45 sx Cl mole marker. Wellbore plugged & abandoned. e and belief. DATE 3-4-15 HONE: _405-552-4615

Ī