

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State <input type="checkbox"/> For <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	JUL 14 1980	8. Firm or Lease Name Teledyne 8
3. Address of Operator P.O. Box 68 Hobbs, NM 88240	O. C. D.	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>2180</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>23-S</u> RANGE <u>29-E</u> NMPM.	ARTESIA, OFFICE	10. Field and Pool, or Wildcat Und-Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 2969.5 GR		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Request permission to plug and abandon well per the following: Pull 2-7/8" tubing. Spot 35' of cement on top of cast iron bridge plug at 7700' and cap with 35' of cement. Spot a 24-SX, 100' Class H cement plug from 6450'-6550'. Spot a 24-SX 100' Class H cement plug from 2750'-2850'. Run free point. Cut and pull casing from above free point (estimated to be at approx. 1000'.) Spot a 37-SX, 100' Class H cement plug 50' in and 50' out of the 7-5/8" casing stub at approx. 1000'. Spot a 52-SX, 100' Class H cement plug from 360'-460'. Spot a 20-SX Class H cement surface plug and weld cap on. Install a P X A marker and clean up and level location. Will advise when ready for final inspection.

0+4-NMOCD, A 1-Hou 1-Susp 1-LBG

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Davis TITLE Admin. Analyst DATE 7-11-80

APPROVED BY W. A. Bessett TITLE SUPERVISOR, DISTRICT II DATE JUL 15 1980

CONDITIONS OF APPROVAL, IF ANY: