

Submit 3 Copies 10 Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30- 015-33943
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Otis "33"
8. Well Number 3
9. OGRID Number 004378
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
CHI OPERATING, INC

3. Address of Operator
PO BOX 1799 MIDLAND, TX 79702

4. Well Location

Unit Letter C : 660 feet from the NORTH line and 1650 feet from the WEST line
Section 33 Township 22s Range 27e NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3142' KB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plug & Abandonment Procedure

1. Set CIBP @ 5150' W/35' cmt on top.
2. Set 50sx cement plug @ 2600'.
3. Set 50sx plug @ 390' TAG.
4. Set 10sx surface plug. (Min 60')
5. Cut off wellhead and weld on dry hole marker.

* Set 100' cmt plug @ 1990' - 1865' - TAG.
(Delaware, D.U. Tank)

* Set 100' cmt plug @ 1708' - 1608' (B. Salt) TAG.

* Set 100' cmt plug @ 605' - 505' (Salado) TAG.

Well information attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE: Rob Askew TITLE: Regulatory Clerk DATE: 12/13/05

Type or print name: ROBIN ASKEW E-mail address: _____ Telephone No: 432-685-5001

For State Use Only

APPROVED BY: [Signature] TITLE: Field Sup. DATE: 12/19/05

Conditions of Approval (if any):

Notify OCD 24 hrs. prior to
any work done.

If earthen pits are used in
association with this work a
pit permit is required prior
to construction.

Chi Operating, Inc.
Otis "33" #3
API# 30-015-33943
Plug and Abandon

Location: 660' FNL & 1650' FWL, Section 33 - T22S - R27E

Directions: South from Carlsbad, NM on Hwy 285. Turn right on Tidwell Rd. Go approx 1½ mile. Turn right on Pacanero Dr. approx .3 mile, left to location

SUPERVISORY PERSONNEL:

	Office	Home	Mobile
Sonny Mann	505-365-2338	432-365-2722	915-634-7062
Gary Womack	432-685-5001	432-682-5315	915-634-8958

CURRENT WELLBORE:

KB: 14'
Int Csg @: 357' 13-3/8", 68#, J55
Prod Csg. @: 5490' 9-5/8", 36 & 40# J55 & N80
PBSD: 5449'

DV Tool: 1917'

Prod Tbg: 2 7/8"-6.5#-J55 N-80, 8rd.

Perforations: 5272-5290', 5156-5164', 5166-5169', 5179-5181'

Plug and Abandonment Procedure

^{35'}
1. Set CIBP @ 5150' w/25' cmt on top.

2. Set 50 sx cement plug at 2600'

TAG * → **3. Set 50 sx plug at 390'.** ← TAG 13 3/8" csg 5' here

4. Set 10 sx surface plug.

5. Cut off wellhead and weld on dry hole marker.

* Set ^{125'} ~~100'~~ cmt plug @ 1990'-1865' (DV Tool, Dekawave) TAG.

* Set 100' cmt plug @ 1708'-1608' (B. Seal T.) - TAG

* Set 100' cmt plug @ 665'-505' (Sealable) TAG.