Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT	5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an bandoned well. Use form 3160-3 (APD) for such proposals.	NMNM02862		
	6. If Indian, Allottee or Tribe Name		

SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. 891000303X		
1. Type of Well ☐ Gas Well ☐ Other				8. Well Name and No. POKER LAKE UNIT CVX JV BS 28H		
2. Name of Operator BOPCO LP Contact: TRACIE J CHERRY E-Mail: tracie_cherry@xtoenergy.com E-Mail: tra				9. API Well No. 30-015-42393-00-S1		
3a. Address *** Priorie No. (esia	10. Field and Pool or Exploratory Area UNKNOWN WC G 065243026M		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish, State		
Sec 23 T24S R30E NENE 0590FNL 1060FEL 32.208892 N Lat, 103.845917 W Lon				EDDY COUNTY, NM		
12. CHECK THE A	PROPRIATE BOX(ES) TO	INDICATE NATUR	RE OF NOTICE,	REPORT, OR OTHER I	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
	☐ Acidize	☐ Deepen	☐ Product	ion (Start/Resume)	Water Shut-Off	
Notice of Intent	☐ Alter Casing	☐ Hydraulic Fractu	ring SHECLAN	FFACHED FORD'	Well Integrity	
☐ Subsequent Report			*	NS OF APPROVA		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abando		arily Abandon	AL.	
I mai Adamdonment Notice	Convert to Injection	☐ Plug Back	Water □	·		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BOPCO, LP respectfully submits this sundry notice of intent to perform casing repairs on the referenced well. The well is currently shut in with a RBP @ 5400' and a suspected casing leak +/-1538. The leak is to be isolated and repaired so completion operations can be safely performed on offset wells. 1. MIRU Pulling Unit. Nipple Down nightcap and nipple up Tubing head. NU BOPE. PT BOPE. 2. Pick up on-off tool & 2-7/8" work string. 3. Ensure casing through and below leak interval is clean. TIH & set RBP @ 1,780? - below leak interval fr/1,538? - 1,731?. Spot 30? sand on top. CEPTER 1. NMOCD 14. 1 hereby certify that the foregoing is true and correct.						
, , ,	Electronic Submission #4326 For BOPC	O LP. sent to the Ca	rlsbad	•		
Committed to AFMSS for processing by ZOTA STEVENS on 08/27/2018 (18ZS0140SE) Name (Printed/Typed) TRACIE J CHERRY Title REGULATORY ANALYST						
Signature (Electronic S	Submission)	Date 08	/24/2018		 	
	THIS SPACE FOR F	EDERAL OR STA	ATE OFFICE U	SE		
Approved By ZQTA STEVENS		TitlePETF	ROLEUM ENGIN	ER	Date 08/27/2018	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Carlsbad						
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				ake to any department or agenc	y of the United	

Additional data for EC transaction #432688 that would not fit on the form

32. Additional remarks, continued

- 4. PT casing & attempt to establish circulation to surface thru Braiden head valve. Casing has been previously tested to 1,100 psig ID & 1,100 down BH valve. Both tested good.
- 5. MIRU WLU. RIH GR. POH. RIH CCL/USIT csg inspection log. Evaluate log. Poss determine where to shoot squeeze holes.
- 6. Establish Circulation to surface thru BH valve or Establish Injection Rate (EIR) into squeeze holes. Calculate cement needed for squeeze operations.
- 7. TIH Cast Iron Cement Retainer (CICR) and tubing. Set CICR #/- squeeze holes or Leak interval. Establish Circ or EIR with fresh water.
- 8. If circulation is established, cement through leak to surface with 275 sks Class C cement. If circulation is not established, squeeze leak with Class C cement. Sting out of retainer with tubing and circulate any remaining cement in tubing to surface. TOH stinger.
- 9. TIH with bit and tubing. Drill out cement retainer and cement through leak interval. TOH.
- 10. PT squeeze to 500 psig for 30 minutes.
- 11. TIH on-off tI and tubing. Wash and circulate sand off top of RBP. Release RBP. TOH tog and RBP.
- 12. Notify BLM / NMOCD 24 hrs prior to MIT. Load well with FW. PT casing to 500 psig for 30 minutes with chart for MIT to confirm.
- 13. Circ csg with 10# brine. Note: RBP?s @ 4,900? & 5,400? for a double barrier to protect WB until nearby hydraulic fracturing operations are complete.

POKER LAKE UNIT CVX JV BS 28H 30-015- 42393 BOPCO, LP August 27, 2018 Conditions of Approval

- 1. Contact BLM 575-361-2822 a minimum of 24 hours prior to performing MIT.
- 2. Surface disturbance beyond the originally approved pad must have prior approval.
- 3. Closed loop system required.
- 4. 3000 (3M) psi workover BOP to be used with pulling unit. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. Pressure test cement squeeze. If it bleeds off more than 10 percent notify the BLM Engineer (575-234-5972).
- 6. Subsequent sundry with test chart required.

ZS 082718