

New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Joanna Prukop
Cabinet Secretary
Reese Fullerton
Deputy Cabinet Secretary

7007 3020 0000 6292 6475

Mark Fesmire
Division Director
Oil Conservation Division



Response Required – Deadline Enclosed

*Unauthorized Distribution of this Document is Prohibited
Penalty: Up to \$5,000 and/or 5 Years Imprisonment*

21-Mar-08

TIPTON OIL & GAS ACQUISITIONS, INC.
P.O. BOX 1597
LOVINGTON NM 88260

ORBIT PETROLEUM, INC.
1131 E. Britton Rd.
Oklahoma City, OK 73131



LOV NO. 62-08-047

LETTER OF VIOLATION and SHUT-IN DIRECTIVE **Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

TWIN LAKES SAN ANDRES UNIT No.035

30-005-60026-00-00

Expired TA Injection - (All Types)

K-36-8S-28E

Test Date: 3/20/2008

Permitted Injection PSI:

Actual PSI:

Test Reason: Standby or Idle Well Test

Test Result: F

Repair Due: 6/23/2008

Test Type: Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: As pumper started pressuring up, water shot out of the open tubing.



TWIN LAKES SAN ANDRES UNIT No.074**30-005-60248-00-00**

Active Injection - (All Types)

K-1-9S-28E

Test Date: 3/19/2008

Permitted Injection PSI:

Actual PSI:

Test Reason: 5-year Test

Test Result: F

Repair Due: 6/22/2008

Test Type: Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Well will not hold pressure

TWIN LAKES SAN ANDRES UNIT No.002**30-005-60648-00-00**

Active Injection - (All Types)

K-25-8S-28E

Test Date: 3/19/2008

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 6/22/2008

Test Type: Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Continuous Blow from casing valve.

TWIN LAKES SAN ANDRES UNIT No.076**30-005-60809-00-00**

Active Injection - (All Types)

I-1-9S-28E

Test Date: 3/19/2008

Permitted Injection PSI:

Actual PSI: 700

Test Reason: Annual IMIT

Test Result: F

Repair Due: 6/22/2008

Test Type: Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Continuous Blow from casing valve.

TWIN LAKES SAN ANDRES UNIT No.109**30-005-61772-00-00**

Active Injection - (All Types)

J-12-9S-28E

Test Date: 3/20/2008

Permitted Injection PSI:

Actual PSI:

Test Reason: 5-year Test

Test Result: F

Repair Due: 6/23/2008

Test Type: Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: well will not hold pressure. Told operator well must be shut-in.

NORTHEAST SQUARE LAKE PREMIER UNIT No.021**30-015-04837-00-00**

Active Injection - (All Types)

G-10-16S-31E

Test Date: 3/21/2008

Permitted Injection PSI:

Actual PSI:

Test Reason: 5-year Test

Test Result: F

Repair Due: 6/24/2008

Test Type: Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Well will not hold pressure.

NORTHEAST SQUARE LAKE PREMIER UNIT No.025**30-015-04845-00-00**

Expired TA Injection - (All Types)

I-10-16S-31E

Test Date: 3/21/2008

Permitted Injection PSI:

Actual PSI:

Test Reason: Standby or Idle Well Test

Test Result: F

Repair Due: 6/24/2008

Test Type: Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Operator reports well will not pressure up.

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually.

Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.