

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-103
May 27, 2004

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-22606
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator BP America Production Company		6. State Oil & Gas Lease No. B-3823-1
3. Address of Operator P.O. Box 1089, Eunice NM 88231		7. Lease Name or Unit Agreement Name: EMPIRE ABO UNIT 'I'
4. Well Location Unit Letter A : 175 feet from the N line and 300 feet from the E line Section 5 Township 18S Range 28E NMPM County EDDY		8. Well Number 283
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3661' GR		9. OGRID Number 00778
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat EMPIRE ABO

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Notify OCD 24 hrs. prior to any work done.

Proposed P&A procedure:

1. MIRU PU. Check casing and surface pipe for pressure - bleed off into containment. Monitor well and assure it's stable, ND WH & install BOP (assure that BOP has been shop tested). Test BOP to 500 psi.
2. Unset Baker Lok Set 5 1/2" x 2 3/8" packer and POOH with tubing and packer. (Send tubing to yard for inspection).
3. TTH with work string and set 5 1/2" OD CIBP @ 5950' (50' above top perf). Load hole with produced water and pressure test casing to 500 psi.

Continued on page 2.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Barry C. Price TITLE Area Operations Team Lead DATE 8/4/08

Type or print name Barry C. Price

Approval Granted providing work is complete by 90 days

E-mail address: barry.price@bp.com
Telephone No. 575-394-1648

For State Use Only

APPROVED BY PHD Hawken TITLE Comptroller DATE 8/8/08

Conditions of Approval, if any:

Form C-103
Empire Abo Unit I-283
30-015-22606
Continued from Page 1

4. Spot 25 sx of cement on top of CIBP @ 5950' (cement plug from 5950'-5700').
5. Circulate hole with mud laden fluid.
6. POH to 4110' (Stage Collar @ 3989'). Spot 25 sack balanced plug from 4110' – 3860'. PU and WOC 2 hours. Tag plug, re-spot if necessary.
7. POH to 3470' (Top of Glorietta @ 3592'). Spot 25 sack balanced plug from 3470' – 3220'.
8. POH to 700' (Surface Casing Shoe @ 580', Top of Yates @ 405', Surface Plug). Spot approx 70 sx cement from 700' – 0', which also provides surface plug, surface casing shoe plug, and top of Yates plug. POH w/ tbg & WOC to set.
9. POH w/ tbg. If necessary, fill well bore with cement to 3' below GL.
10. RD PU and clean location.
11. Dig out WH and cut-off casingheads to 3' below GL.
12. Install regulation dry-hole marker. Clean location and prepare location for BLM & NMOCD inspections.

Do not enter values in yellow boxes these boxes receive inputs from the Well History sheet.

[illegible]

Do not enter values in yellow boxes these boxes receive inputs from the Well History sheet.

[illegible]