Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resource	ces	June 19, 2008	
1625 N French Dr., Hobbs, NM 88240 District II	au annual VE	D	WELL API NO. 30-015-23160	
1301 W Grand Ave , Artesia, NM 88210	OIL CONSERVATION DIVISIO	M	5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	06	STATE FEE	
<u>District IV</u> 1220 S St Francis Dr , Santa Fe, NM	San 2019e, NM \$550 \$11 3	-	6. State Oil & Gas Lease No.	
87505			18757	
	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO		7. Lease Name or Unit Agreement Name	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ATION FOR PERMIT" (FORM C-101) FOR SUCH	А	State LG 2985	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🔯 Other		8. Well Number 1	
2. Name of Operator	AUG 2 1 2008		9. OGRID Number	
Vernon E. Faulconer, Inc	- 1 L000		148394	
3. Address of Operator	UUU-ARIESII		10. Pool name or Wildcat	
P O Box 7995 Tyler, Texas 75703			Morrow	
4. Well Location	1000 6 (6)	10		
Unit LetterK Section 26	1980feet from theS line and		And the second s	
Section 26	Township 18S Range 11. Elevation (Show whether DR, RKB, RT, C	28E	NMPM County Eddy	
St. Bully and Line Co.	3514' KB	т, ек.,		
	West of the second seco			
12. Check A	ppropriate Box to Indicate Nature of N	otice,	Report or Other Data	
NOTICE OF IN	TENTION TO:	CLID	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛 REMEDIAL			
TEMPORARILY ABANDON			LLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/C	EMENT	「JOB □	
DOWNHOLE COMMINGLE				
OTHER:	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
or recompletion.				
	•		Nolly OCD 24 hrs. prior	
Can Attached Procedure			To any work done.	
See Attached Procedure				
			Approval Granted proyiding work	
			is complete by 11/26/08	
			, , ,	
[·				
Spud Date:	Rig Release Date:			
I hereby certify that the information a	pove is true and complete to the best of my kno	wledge	and helief	
	· · · · · · · · · · · · · · · · · · ·	micage	and series.	
CICHATURE Character	d		7	
SIGNATURE J CHMON	TITLE_Production Analyst		DATE_8/11/08	
Type or print nameShannan Johnson	n E-mail address:shan8598@g	yahoo.c	om PHONE: _(903) 581-4382	
For State Use Only				
APPROVED BY: /h Hay	Ri TITLEConslin of	/	DATE 8/25/08	
Conditions of Approval (if any):	The same of	 -	DAIL 1/21/20	

VERNON E. FAULCONER, INC.

"State LG"
"Plug & Abandon"
August 11, 2008
Page 1

- 1. MIRU WO RIG
- 2. NIPPLE DOWN X-MAS TREE, NIPPLE UP BOP'S
- 3. PICK UP ON TUBING AND ATTEMPT TO PULL SEALS OUT OF PACKER. IF SEALS FAIL TO RELEASE, RU ELECTRIC LINE AND CUT TUBING AT 10775. POOH WITH TUBING.
- 4. (PLUG 1) RIH AND SET CIBP @ 10,750', DUMPBAIL 35' OF CMT ON PLUG.
- 5. (PLUG 2) RIH W/ TUBING TO 8400 AND DISPLACE WELL WITH 9 #/GAL. MUD.
 MIX AND SPOT A 5-SX BALANCED CEMENT PLUG.
- 6. POOH TO 6400' LAYING DOWN TUBING.
- 7. (PLUG 3) MIX AND SPOT A 15 SX BALANCED CEMENT PLUG @ 6400'. POOH LAYING DOWN TUBING TO 3150'. POOH AND STAND BACK REMAINDER OF TUBING.
- AC. X- CSG 37-4
 - 8. RU ELECTRIC LINE AND CUT 5 ½ CASING AT 3000' OR FREE POINT, WHICH EVER IS DEEPER, RD ELECTRIC LINE, POOH LAYING DOWN CASING.
 - 9. (PLUG 4) RIH WITH TUBING AND SPOT A 40 SX BALANCED CEMENT PLUG 50'
 INSIDE THE STUB. PULL UP OUT OF PLUG 6 STANDS AND REVERSE OUT
 TUBING WAIT ON CEMENT TO SET, TAG TOP OF PLUG.
 - 10. (PLUG 5) POOH LAYING DOWN TUBING TO 2580. MIX AND SPOT A 35 SX BALANCED CEMENT PLUG @ 2580'. PULL UP OUT OF PLUG 6 STANDS AND REVERSE OUT TUBING. WAIT ON CEMENT TO SET, TAG TOP OF PLUG.
 - 11 (PLUG 6) POOH LAYING DOWN TUBING TO 2150. MIX AND SPOT A 35 SX

 BALANCED CEMENT PLUG @ 2150'. PULL UP OUT OF PLUG 6 STANDS AND

 REVERSE OUT TUBING. WAIT ON CEMENT TO SET, TAG TOP OF PLUG.
 - 12. (PLUG 7)POOH LAYING DOWN TUBING TO 525. MIX AND SPOT A 35 SX BALANCED CEMENT PLUG @ 525'. PULL UP OUT OF PLUG 6 STANDS AND REVERSE OUT TUBING. WAIT ON CEMENT TO SET, TAG TOP OF PLUG
 - # Pers. I Squz. 100' cmT in + Out TAG

 # DV Tool 100' cmt, 50' About 50' below
 # 100' cmt Ply. 50' About N 50' below CSG. STub. TAG.

 # 100' cmt Ply At. 722' Bar od Sulz. TAG.
 100' cmt Ply & 210' Tup of Salt TAG.

VERNON E. FAULCONER, INC.

"State LG"
"Plug & Abandon"
August 11, 2008
Page 2

- 13. (PLUG 8) POOH LAYING DOWN TUBING TO 60. MIX AND SPOT A 20 SX BALANCED CEMENT PLUG CIRCULATING CEMENT TO SURFACE. POOH LAYING DOWN ALL TUBING.
- 14. NIPPLE DOWN BOP'S.
- 15. CUT OFF BRADEN HEAD AND WELD A STEEL PLATE ACROSS ALL CASINGS.
- 12. INSTALL a steel marker not less than four inches (4") in diameter set in cement and extending at least four feet (4') above mean ground level. The operator name, lease name and well number and location, including unit letter, section, township and range, shall be welded, stamped or otherwise permanently engraved into the metal of the marker
- 13. RDMO WO RIG.
- 14. REMOVE ALL SURFACE EQUIPMENT AND CLEAN OFF LOCATION.

Approval	Date	Yes
RS		
PHJ		
RF		
DJE		



