Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

| OCD-ARTES | |
|----------------|---|
| MAR 2 6 2009 1 | ľ |

FORM APPROVED OMB NO. 1004-0135

Expires: November 30, 2000 5. Lease Serial No.

| SUNDRY NOTICES AND REPORTS ON | WELLS | NM-105538 |
|---|--|--|
| Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. | | 6. If Indian, Allottee or Tribe Name |
| SUBMIT IN TRIPLICATE - Other instructions of | n reverse side | 7. If Unit or CA/Agreement, Name and/or |
| 1. Type of Well | TYPE OF ACT Deepen Process Fracture Treat Recess New Construction Recess X Plug and Abandon Tem Plug Back Wat including estimated starting date of a surface locations and measured and tr d No. on file with BLM/BIA. Requirements and trequirements, including recess TYPE OF ACT | duction (Start/Resume) Water Shut-Off Ilamation Well Integrity Other Imporarily Abandon Importantly Abandon I |
| | <u> </u> | SUPERVISOR-EPS |
| 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart | Title Sr. Regulatory | / Analyst |
| Va Staf | Date 3(11/09) | |
| | * | |

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title Date Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

Sergeant Canyon 31 Fed #1

02/26/09

MI rig #1703 and plugging equipment. Dig out cellar, pressure down well. Will rig up pulling unit in the AM. SI, SDFN.

02/27/09

RU pulling unit. NU BOP, RIH w/ tbg and tagged CIBP @ 6913'. SI, SDFW.

03/02/09

RU cementer, circulated hole w/ plugging mud, pumped 25sx C cmt 6913-6667', PUH. SI, SDFN.

03/03/09

ND BOP, NDWH. RU casing pulling equipment. Stabbed casing w/ spear, stretched casing, determined free point of 3592'. NU wellhead, NU BOP. RIH w/ tbg to 5614', RU cementer, circulated hole, pumped 25sx C cmt @ 5614-4727', will tag in the AM. SI SDFN:

03/04/09

RU wireline, RIH and tagged cmt @ 4727', PUH w/ wireline and perforated @ 4520', POOH. RIH w/ pkr to 4187', loaded hole, set pkr, established injection rate of 2 BPM, squeezed 60sx C cmt w/ 2% CaCl2 4520–4283', POOH w/ tbg. RU wireline, RIH and tagged cmt @ 4283', POOH. RIH w/ wireline, cut casing @ 3500', POOH. ND BOP & wellhead, RU spear, pull casing free, PPOH w/ spear. NUWH & BOP, SI, SDFN.

03/05/09

ND BOP, ND wellhead, RU casing equipment. POOH w/ 3500' of casing (84 jts). RD casing equipment. Shut down due to high winds. SI, SDFN.

03/06/09

RIH w/ tbg to 3552', RU cementer, circulated hole. Began pumping cmt, pumped two bbls of cmt, problem w/ pump, displaced 13bbls, PUH w/ tbg. Contacted BLM, instructed to tag cmt. Fixed pump. Shut down due to wind. SI.

03/09/09

RIH w/ tbg and tagged cmt @ 3,520'. Contacted BLM, instructed to pump 85sx on top of cmt. Loaded hole, pumped 85sx C cmt 3520–3298', PUH and WOC. RIH w/ tbg and tagged cmt @ 3298'. Contacted BLM, instructed to pump 25sx @ 2727'. PUH to 2727', pumped 25sx C cmt 2727–2601', POOH. Will tag in the AM, SI, SDFN.

03/10/09

RIH w/ tbg and tagged cmt @ 2601'. PUH to 1586', loaded hole, pumped 60sx C cmt 1586–1420', PUH and WOC. RIH w/ tbg and tagged cmt @ 1420'. PUH to 840', loaded hole, pumped 110sx C cmt 840–521'. PUH to 126', loaded hole, pumped 50 sx C cmt 126' to surface. RD pulling unit and plugging equipment.

61