Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		May 27, 2004
1625 N French Dr., Hobbs, NM 88240		210004,100	WELL API NO.
District II 1301 W. Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION		30-015-00286	
1301 W Grand Ave, Artesia, NM 88210 District III 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE STATE FEE
District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505			
page 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ICES AND REPORTS ON	WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR USE "APPLIC PROPOSALS.)		C-101) FOR SUCH	ATOKA SAN ANDRES UNIT
1. Type of Well: Oil Well	Gas Well Other	RECEIVED	8. Well Number 132
2. Name of Operator		OCT 3 1 2005	9. OGRID Number
Devon Energy Production Comp	any, L.P.		6137
3. Address of Operator		OGDINALCON	10. Pool name or Wildcat
20 North Broadway, Suite 1500,	Oklahoma City, Oklahom	na 73102	ATOKA (SAN ANDRES)
4. Well Location			
Unit Letter C : 990 feet from the NORTH line and 2310 feet from the WEST line			
Section 14	Township		NMPM Eddy County
	11. Elevation (Show whe	ether DR, RKB, RT, GR, etc.,	
Pit or Below-grade Tank Application			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR			K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON			LLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Procedure to Plug & Abandon Welli	pore		
1. MIRU. Tag existing CIBP at 1475' and dump 35' cement on top.			
2. Circulate wellbore with 9 PPG Mud.			
3. Spot 150' cement plug across 8-5/8" casing shoe from 1117' to 1267'. WOC & Tag. (8-5/8" casing shoe at 1192')			
4. Cut 5-1/2" casing @ +/- 390'. POOH and lay down.			
5. Spot 150' cement stub plug from 315' to 465'. WOC & Tag			
6. Set 60' surface cement plug.7. Cut wellhead off 3' BGL. Set dry hole marker.			
7. Cut wellhead off 3' BGL. Set dry hole marker. 8. Clean location.			
o. Clean tocation.			
	Luc mular éa		
Notify OCD 24 hrs . prior to carry work done.			
Mark transcent			
I hereby certify that the information	above is true and complete	to the best of my knowledg	e and belief. I further certify that any pit or below-
0 0.		uidennes 🔲, a general permit 📙	or an (attached) alternative OCD-approved plan [].
SIGNATURE WMMAO	^ ₩ T	ITI E Engineering Techni	10/26/05



